



CORRIGENDUM

ETR 283

March 1997

Source: ETSI TC-EE

Reference: RTR/EE-02006-C1

ICS: 33.020

Key words: Power supply, protection, transient

**This corrigendum modifies
the ETSI Technical Report ETR 283 (1996)**

**Equipment Engineering (EE);
Transient voltages at Interface A
on telecommunications
direct current (dc) power distributions**

ETSI

European Telecommunications Standards Institute

ETSI Secretariat

Postal address: F-06921 Sophia Antipolis CEDEX - FRANCE

Office address: 650 Route des Lucioles - Sophia Antipolis - Valbonne - FRANCE

X.400: c=fr, a=atlas, p=etsi, s=secretariat - **Internet:** secretariat@etsi.fr

Tel.: +33 4 92 94 42 00 - Fax: +33 4 93 65 47 16

Copyright Notification: No part may be reproduced except as authorized by written permission. The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 1997. All rights reserved.

Foreword

This corrigendum corrects formula 6, to insert the parameter "I" which was omitted from the original version.

Amendment

Page 11, subclause 8.3.1

Modify formula 6 as follows:

$$L = l \times \frac{\mu}{\pi} \ln \frac{d}{r} \quad (6)$$

Where:

- l = the length of the conductors;

History

| Document history | |
|-------------------------|------------------------------|
| May 1996 | First Edition |
| March 1997 | Corrigendum to First Edition |
| | |
| | |
| | |