

ETSI TS 134 123-3 V9.5.0 (2012-10)



Technical Specification

**Universal Mobile Telecommunications System (UMTS);
User Equipment (UE) conformance specification;
Part 3: Abstract test suite (ATS)
(3GPP TS 34.123-3 version 9.5.0 Release 9)**



ReferenceRTS/TSGR-0534123-3v950

KeywordsUMTS

ETSI

650 Route des Lucioles
F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - NAF 742 C
Association à but non lucratif enregistrée à la
Sous-Préfecture de Grasse (06) N° 7803/88

Important notice

Individual copies of the present document can be downloaded from:

<http://www.etsi.org>

The present document may be made available in more than one electronic version or in print. In any case of existing or perceived difference in contents between such versions, the reference version is the Portable Document Format (PDF). In case of dispute, the reference shall be the printing on ETSI printers of the PDF version kept on a specific network drive within ETSI Secretariat.

Users of the present document should be aware that the document may be subject to revision or change of status. Information on the current status of this and other ETSI documents is available at

<http://portal.etsi.org/tb/status/status.asp>

If you find errors in the present document, please send your comment to one of the following services:

http://portal.etsi.org/chaicor/ETSI_support.asp

Copyright Notification

No part may be reproduced except as authorized by written permission.
The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 2012.
All rights reserved.

DECT™, **PLUGTESTS™**, **UMTS™** and the ETSI logo are Trade Marks of ETSI registered for the benefit of its Members.
3GPP™ and **LTE™** are Trade Marks of ETSI registered for the benefit of its Members and
of the 3GPP Organizational Partners.
GSM® and the GSM logo are Trade Marks registered and owned by the GSM Association.

Intellectual Property Rights

IPRs essential or potentially essential to the present document may have been declared to ETSI. The information pertaining to these essential IPRs, if any, is publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: *"Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards"*, which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (<http://ipr.etsi.org>).

Pursuant to the ETSI IPR Policy, no investigation, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

Foreword

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under <http://webapp.etsi.org/key/queryform.asp>.

Contents

| | |
|--|----------|
| Intellectual Property Rights | 2 |
| Foreword..... | 2 |
| Foreword..... | 4 |
| Introduction | 4 |
| 1 Scope | 5 |
| 2 References | 5 |
| 3 Definitions and abbreviations..... | 6 |
| 3.1 Definitions | 6 |
| 4 Requirements on the TTCN development..... | 6 |
| 5 to 8 Void..... | 6 |
| Annex A to I: Void | 6 |
| Annex J (informative): Change history | 7 |
| History | 63 |

Foreword

This Technical Specification has been produced by the 3rd Generation Partnership Project (3GPP).

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

x the first digit:

- 1 presented to TSG for information;
- 2 presented to TSG for approval;
- 3 or greater indicates TSG approved document under change control.

y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.

z the third digit is incremented when editorial only changes have been incorporated in the document.

Introduction

The present document is part 3 of a multi-part conformance test specification for UE. The specification contains a TTCN2 design frame work and the detailed test specifications in TTCN for UE at the Uu interface.

3GPP TS 34.123-1 "User Equipment (UE) conformance specification; Part 1: Protocol conformance specification".

3GPP TS 34.123-2: "User Equipment (UE) conformance specification; Part 2: Implementation Conformance Statement (ICS) proforma specification".

3GPP TS 34.123-3: "Abstract Test Suite (ATS)" (the present document).

1 Scope

The present document specifies the protocol conformance testing in TTCN for the 3GPP User Equipment (UE) at the Uu interface.

The present document is the 3rd part of a multi-part test specification, 3GPP TS 34.123. The following TTCN test specification and design considerations can be found in the present document:

- the overall test suite structure;
- the testing architecture;
- the test methods and PCO definitions;
- the test configurations;
- the design principles, assumptions, and used interfaces to the TTCN tester (System Simulator);
- TTCN styles and conventions;
- the partial PIXIT proforma;
- the TTCN.MP and TTCN.GR forms for the mentioned protocols tests.

The Abstract Test Suites designed in the document are based on the test cases specified in prose (3GPP TS 34.123-1).

The present document is valid for UE implemented according to 3GPP Release 1999, 3GPP Release 4, 3GPP Release 5, 3GPP Release 6, 3GPP Release 7 or 3GPP Release 8 or 3GPP Release 9.

2 References

The following documents contain provisions, which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document *in the same Release as the present document*.
 - For a Release 1999 UE, references to 3GPP documents are to version 3.x.y, when available.
 - For a Release 4 UE, references to 3GPP documents are to version 4.x.y, when available.
 - For a Release 5 UE, references to 3GPP documents are to version 5.x.y, when available.
 - For a Release 6 UE, references to 3GPP documents are to version 6.x.y, when available.
 - For a Release 7 UE, references to 3GPP documents are to version 7.x.y, when available.
 - For a Release 8 UE, references to 3GPP documents are to version 8.x.y, when available.
 - For a Release 9 UE, references to 3GPP documents are to version 9.x.y, when available.

[1] to [62] (void)

[63] 3GPP TS 34.123-3 Release 10: "User Equipment (UE) conformance specification; Part 3: Abstract Test Suite (ATS)".

3 Definitions and abbreviations

3.1 Definitions

Void

4 Requirements on the TTCN development

The requirements of the present document are provided in 3GPP TS 34.123-3 Release 10 [63].

5 to 8 Void

Annex A to I: Void

Annex J (informative): Change history

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|--|-----|----------|----------|-----------|
| TP-18 | TP-020301 | | | Approval of the specification | | 2.0.0 | 3.0.0 | |
| TP-24 | - | - | - | One correction performed in the NAS ATS part (the other ATS parts remain in v.3.6.0) | | 3.6.0 | 3.6.1 | - |
| TP-20 | - | - | - | Regeneration of RRC and RLC ATS | | 3.2.0 | 3.2.1 | - |
| TP-21 | TP-030199 | - | - | Add new approved TTCN test cases in test case list in Annex A | F | 3.2.1 | 3.3.0 | - |
| TP-23 | TP-040044 | - | - | Updating Annex A | F | 3.4.0 | 3.5.0 | - |
| TP-23 | - | - | - | Editorial clean-up by ETSI | | 3.5.0 | 3.5.1 | - |
| TP-23 | - | - | - | Sections 8.3.28 - 8.3.31 were misplaced | | 3.5.1 | 3.5.2 | - |
| TP-19 | TP-030051 | 001 | - | Change to test case 9.2.3 required for approval | F | 3.0.0 | 3.1.0 | T1-030120 |
| TP-19 | TP-030051 | 002 | - | Change to test case 9.2.4 required for approval | F | 3.0.0 | 3.1.0 | T1-030121 |
| TP-19 | TP-030051 | 003 | - | Change to test case 10.1.3.4.1 required for approval | F | 3.0.0 | 3.1.0 | T1-030122 |
| TP-19 | TP-030051 | 004 | - | Inclusion of RLC test case 7.2.2.3 to RLC ATS V3.0.0 | F | 3.0.0 | 3.1.0 | T1-030123 |
| TP-19 | TP-030051 | 005 | - | Inclusion of RLC test case 7.2.2.4 to RLC ATS V3.0.0 | F | 3.0.0 | 3.1.0 | T1-030124 |
| TP-19 | TP-030051 | 006 | - | Inclusion of RLC test case 7.2.2.7 to RLC ATS V3.0.0 | F | 3.0.0 | 3.1.0 | T1-030125 |
| TP-19 | TP-030051 | 007 | - | Inclusion of RLC test case 7.2.3.4 to RLC ATS V3.0.0 | F | 3.0.0 | 3.1.0 | T1-030126 |
| TP-19 | TP-030051 | 008 | - | Inclusion of RLC test case 7.2.3.5 to RLC ATS V3.0.0 | F | 3.0.0 | 3.1.0 | T1-030127 |
| TP-19 | TP-030051 | 009 | - | Changes to TS34.123-3 V200 to introduce TC_8_1_1_4 | F | 3.0.0 | 3.1.0 | T1-030128 |
| TP-19 | TP-030051 | 010 | - | TTCN changes to the approved test cases in V300 | F | 3.0.0 | 3.1.0 | T1-030129 |
| TP-19 | TP-030051 | 011 | 1 | CR 34.123-3, V300 as T1S030009rev1 | F | 3.0.0 | 3.1.0 | T1-030260 |
| TP-19 | TP-030051 | 012 | - | Introducing Test Case 8.1.2.7 | F | 3.0.0 | 3.1.0 | T1-030245 |
| TP-19 | TP-030051 | 013 | - | Introduction of Test Case 8.2.1.1 | F | 3.0.0 | 3.1.0 | T1-030246 |
| TP-19 | TP-030051 | 014 | - | Introduction of Test Case 8.2.3.1 | F | 3.0.0 | 3.1.0 | T1-030247 |
| TP-19 | TP-030051 | 015 | - | Addition of RRC test case 8.1.9 to RRC ATS V3.0.0 NOTE: There was a missing TTCN fix in TP-030051. In the TTCN line 6 of TC_8_1_2_1, replace +ts_SendDefSysInfo(tsc_CellA) with +ts_SendSysInfoWithSpecialSIB11(tsc_CellA, tcv_SIB11IntraFreqRepQuantityRACH). Otherwise, a good UE would be failed at the regression test. | F | 3.0.0 | 3.1.0 | T1-030248 |
| TP-20 | TP-030104 | 016 | - | Test Case 7.1.1.2 | F | 3.1.0 | 3.2.0 | T1-030397 |
| TP-20 | TP-030104 | 017 | - | Test Case 7.1.1.8 | F | 3.1.0 | 3.2.0 | T1-030399 |
| TP-20 | TP-030104 | 018 | - | Test Case 8.1.1.2 | F | 3.1.0 | 3.2.0 | T1-030401 |
| TP-20 | TP-030104 | 019 | - | Test Case 8.1.1.3 | F | 3.1.0 | 3.2.0 | T1-030403 |
| TP-20 | TP-030104 | 020 | - | Test Case 8.1.1.8 | F | 3.1.0 | 3.2.0 | T1-030411 |
| TP-20 | TP-030104 | 021 | - | Test Case 8.2.1.8 | F | 3.1.0 | 3.2.0 | T1-030413 |
| TP-20 | TP-030104 | 022 | - | Test Case 8.2.1.10 | F | 3.1.0 | 3.2.0 | T1-030415 |
| TP-20 | TP-030104 | 023 | - | Test Case 8.1.5.1 | F | 3.1.0 | 3.2.0 | T1-030425 |
| TP-20 | TP-030104 | 024 | - | Test Case 8.1.5.4 | F | 3.1.0 | 3.2.0 | T1-030427 |
| TP-20 | TP-030104 | 025 | - | Test Case 8.2.3.7 | F | 3.1.0 | 3.2.0 | T1-030429 |
| TP-20 | TP-030104 | 026 | - | Addition of RLC test case 7.2.3.6 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030438 |
| TP-20 | TP-030104 | 027 | - | Addition of RLC test case 7.2.3.25 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030440 |
| TP-20 | TP-030104 | 028 | - | Addition of RLC test case 7.2.3.14 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030442 |
| TP-20 | TP-030104 | 029 | - | Addition of RLC test case 7.2.3.15 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030444 |
| TP-20 | TP-030104 | 030 | - | Addition of RLC test case 7.2.3.16 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030446 |
| TP-20 | TP-030104 | 031 | - | Addition of RLC test case 7.2.3.33 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030448 |
| TP-20 | TP-030104 | 032 | - | Addition of NAS test case 10.1.2.5.1 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030450 |
| TP-20 | TP-030104 | 033 | - | 7.1.1.1 | B | 3.1.0 | 3.2.0 | T1-030452 |
| TP-20 | TP-030104 | 034 | - | 7.1.1.3 | B | 3.1.0 | 3.2.0 | T1-030454 |
| TP-20 | TP-030104 | 035 | - | 7.1.1.4 | B | 3.1.0 | 3.2.0 | T1-030456 |
| TP-20 | TP-030104 | 036 | - | Introduction of Test Case 7.1.1.5 | B | 3.1.0 | 3.2.0 | T1-030458 |
| TP-20 | TP-030104 | 037 | - | Test Case 8.2.3.15 | F | 3.1.0 | 3.2.0 | T1-030464 |
| TP-20 | TP-030104 | 038 | - | Test Case 8.2.3.18 | F | 3.1.0 | 3.2.0 | T1-030466 |
| TP-20 | TP-030104 | 039 | - | Test Case 8.2.3.19 | F | 3.1.0 | 3.2.0 | T1-030468 |
| TP-20 | TP-030104 | 040 | - | Test Case 12.3.1.2 | F | 3.1.0 | 3.2.0 | T1-030474 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|-----|-----|---|-----|-------------|-------------|-----------|
| TP-20 | TP-030104 | 041 | - | Test Case 8.3.3.1 | F | 3.1.0 | 3.2.0 | T1-030479 |
| TP-20 | TP-030104 | 042 | - | Addition of RLC test case 7.2.3.13 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030484 |
| TP-20 | TP-030104 | 043 | - | Addition of RLC test case 7.2.3.18 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030486 |
| TP-20 | TP-030104 | 044 | - | Addition of RLC test case 7.2.2.5 to RLC ATS V3.0.0 | B | 3.1.0 | 3.2.0 | T1-030490 |
| TP-20 | TP-030104 | 045 | - | Addition of RLC test case 7.2.2.6 to RLC ATS V3.0.0 | B | 3.1.0 | 3.2.0 | T1-030492 |
| TP-20 | TP-030104 | 046 | - | Addition of RLC test case 7.2.3.17 to RLC ATS V3.0.0 | B | 3.1.0 | 3.2.0 | T1-030495 |
| TP-20 | TP-030104 | 047 | - | Addition of RLC test case 7.2.3.20 to RLC ATS V3.0.0 | B | 3.1.0 | 3.2.0 | T1-030496 |
| TP-20 | TP-030104 | 048 | - | Addition of RLC test case 7.2.3.34 to RLC ATS V3.0.0 | B | 3.1.0 | 3.2.0 | T1-030498 |
| TP-20 | TP-030104 | 049 | - | Addition of SM test case 11.1.1.1 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030500 |
| TP-20 | TP-030104 | 050 | - | Addition of RLC test case 7.2.3.23 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030535 |
| TP-20 | TP-030104 | 051 | - | Addition of RLC test case 7.2.3.24 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030537 |
| TP-20 | TP-030104 | 052 | - | Addition of RLC test case 7.2.3.26 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030539 |
| TP-20 | TP-030104 | 053 | - | Addition of RLC test case 7.2.3.27 to RLC ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030541 |
| TP-20 | TP-030104 | 054 | - | Addition of SM test case 11.3.1 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030576 |
| TP-20 | TP-030104 | 055 | - | Addition of SM test case 11.3.2 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030577 |
| TP-20 | TP-030104 | 056 | - | Addition of GMM test case 12.3.1.5 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030578 |
| TP-20 | TP-030104 | 057 | - | Addition of GMM test case 12.7 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030580 |
| TP-20 | TP-030104 | 058 | - | Test Case 8.2.1.9 | F | 3.1.0 | 3.2.0 | T1-030594 |
| TP-20 | TP-030104 | 059 | - | Test Case 8.2.3.8 | F | 3.1.0 | 3.2.0 | T1-030596 |
| TP-20 | TP-030104 | 060 | - | Test Case 12.3.1.1 | F | 3.1.0 | 3.2.0 | T1-030614 |
| TP-20 | TP-030104 | 062 | - | Test Case 12.9.2 | F | 3.1.0 | 3.2.0 | T1-030626 |
| TP-20 | TP-030104 | 063 | - | Addition of GMM test case 12.3.2.1 to NAS ATS V3.1.0 | B | 3.1.0 | 3.2.0 | T1-030638 |
| TP-20 | TP-030104 | 064 | - | CR for correction of generic test step in RLC ATS V3.1.0 | F | 3.1.0 | 3.2.0 | T1-030654 |
| TP-20 | TP-030104 | 065 | - | ASP Enhancement | F | 3.1.0 | 3.2.0 | T1-030665 |
| TP-20 | TP-030104 | 066 | - | Test Case 8.1.2.2 | F | 3.1.0 | 3.2.0 | T1-030395 |
| TP-20 | TP-030104 | 067 | - | Test Case 8.1.2.9 | F | 3.1.0 | 3.2.0 | T1-030396 |
| TP-20 | TP-030110 | 068 | - | Add new approved test cases in test case list in Annex A | F | 3.1.0 | 3.2.0 | -- |
| TP-20 | TP-030141 | 069 | - | Test Case 8.1.3.3 | F | 3.1.0 | 3.2.0 | T1-030460 |
| TP-21 | TP-030194 | 070 | - | Corrections to Package 1 test cases in RRC ATS v3.2.1 for PS mode | F | 3.2.1 | 3.3.0 | T1-031054 |
| TP-21 | TP-030194 | 071 | - | Corrections to Package 1 test cases in RRC ATS v3.2.1 for Integrity | F | 3.2.1 | 3.3.0 | T1-031055 |
| TP-21 | TP-030194 | 072 | - | Corrections to Package 1 test cases in RRC ATS v3.2.1 for configuration of Radio Bearer -3 | F | 3.2.1 | 3.3.0 | T1-031140 |
| TP-21 | TP-030194 | 073 | - | CR to 34.123-3 R99, Moving baseline from March 02 to March 03 and error corrections | F | 3.2.1 | 3.3.0 | T1-031242 |
| TP-21 | TP-030194 | 074 | - | CR to 34.123-3, R99, Update and remove unnecessary PIXIT parameters, so they are aligned with the 3GPP conformance TTCN | F | 3.2.1 | 3.3.0 | T1-031278 |
| TP-21 | TP-030194 | 079 | - | Changes to TS34.123-3 V310 to introduce TC_8_1_1_5 | F | 3.1.0 | 3.3.0 | T1-030405 |
| TP-21 | TP-030194 | 080 | - | Changes to TS34.123-3 V310 to introduce TC_8_1_1_6 | F | 3.1.0 | 3.3.0 | T1-030407 |
| TP-21 | TP-030194 | 084 | - | Changes to TS34.123-3 V310 to introduce TC_12_2_1_1 | F | 3.1.0 | 3.3.0 | T1-030423 |
| TP-21 | TP-030194 | 119 | - | Changes to TS34.123-3 V310 to introduce TC_8_3_4_1 | F | 3.1.0 | 3.3.0 | T1-030602 |
| TP-21 | TP-030194 | 120 | - | Changes to TS34.123-3 V310 to introduce TC_8_3_4_2 | F | 3.1.0 | 3.3.0 | T1-030604 |
| TP-21 | TP-030194 | 121 | - | Changes to TS34.123-3 V310 to introduce TC_8_3_4_3 | F | 3.1.0 | 3.3.0 | T1-030606 |
| TP-21 | TP-030194 | 122 | - | Changes to TS34.123-3 V310 to introduce TC_8_4_1_1 | F | 3.1.0 | 3.3.0 | T1-030608 |
| TP-21 | TP-030194 | 124 | - | Changes to TS34.123-3 V310 to introduce TC_12_9_1 | F | 3.1.0 | 3.3.0 | T1-030624 |
| TP-21 | TP-030194 | 127 | - | CR to 34.123-3 V310 to introduce test case 7.2.3.19 | B | 3.1.0 | 3.3.0 | T1-030657 |
| TP-21 | TP-030194 | 128 | - | CR to 34.123-3 V320 to introduce test case 14.2.13.1 | B | 3.2.0 | 3.3.0 | T1-030877 |
| TP-21 | TP-030194 | 129 | - | CR to 34.123-3 V320 to introduce test case 7.2.2.2 | B | 3.2.0 | 3.3.0 | T1-030879 |
| TP-21 | TP-030194 | 130 | - | CR to 34.123-3 V320 to introduce test case 7.2.3.2 | B | 3.2.0 | 3.3.0 | T1-030881 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|--|-----|----------|----------|-----------|
| TP-21 | TP-030194 | 131 | - | Changes to TS34.123-3 V320 to introduce TC_8_2_3_9 | B | 3.2.0 | 3.3.0 | T1-030896 |
| TP-21 | TP-030194 | 132 | - | Changes to TS34.123-3 V320 to introduce TC_7_2_3_21 | F | 3.2.0 | 3.3.0 | T1-030897 |
| TP-21 | TP-030194 | 133 | - | Changes to TS34.123-3 V320 to introduce TC_7_2_3_22 | F | 3.2.0 | 3.3.0 | T1-030898 |
| TP-21 | TP-030194 | 134 | - | CR to 34.123-3 V320 to introduce test case TC_8_2_6_20 | F | 3.2.1 | 3.3.0 | T1-030928 |
| TP-21 | TP-030194 | 135 | - | CR to 34.123-3 V320 to introduce test case TC_9.2.1 | B | 3.2.1 | 3.3.0 | T1-031016 |
| TP-21 | TP-030194 | 136 | - | CR to 34.123-3 V320 to introduce test case TC_9.3.1 | B | 3.2.1 | 3.3.0 | T1-031018 |
| TP-21 | TP-030194 | 137 | - | CR to 34.123-3 V320 to introduce test case TC_9_4_5_2 | B | 3.2.1 | 3.3.0 | T1-031020 |
| TP-21 | TP-030194 | 138 | - | CR to 34.123-3 V320 to introduce test case TC_9.5.2 | B | 3.2.1 | 3.3.0 | T1-031022 |
| TP-21 | TP-030194 | 139 | - | Changes to TS34.123-3 V321 to introduce TC_8_1_1_7 | F | 3.2.1 | 3.3.0 | T1-031141 |
| TP-21 | TP-030208 | 140 | - | Addition of RRC test case 8.2.2.1 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031280 |
| TP-21 | TP-030208 | 141 | - | Addition of RRC test case 8.2.2.11 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031281 |
| TP-21 | TP-030208 | 142 | - | Addition of RRC test case 8.2.6.1 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031282 |
| TP-22 | TP-030284 | 142 | 2 | ASP changes and MMI string corrections | F | 3.3.0 | 3.4.0 | T1-031707 |
| TP-21 | TP-030208 | 143 | - | Addition of RRC test case 8.2.2.17 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031283 |
| TP-21 | TP-030208 | 144 | - | Addition of RRC test case 8.2.4.10 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031284 |
| TP-21 | TP-030208 | 145 | - | Addition of RRC test case 8.2.6.7 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031285 |
| TP-21 | TP-030208 | 146 | - | Addition of RRC test case 8.2.2.8 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031286 |
| TP-21 | TP-030208 | 147 | - | Addition of RRC test case 8.2.2.10 to 34.123-3 | F | 3.2.1 | 3.3.0 | T1-031287 |
| TP-21 | TP-030208 | 148 | - | Test case 12.5 | F | 3.2.1 | 3.3.0 | T1-031288 |
| TP-21 | TP-030209 | 149 | - | CR to 34.123-3 V321 to introduce test case TC_8_2_2_23 | F | 3.2.1 | 3.3.0 | T1-031289 |
| TP-23 | TP-040042 | 151 | - | GERAN ASP changes | F | 3.4.0 | 3.5.0 | T1-040412 |
| TP-23 | TP-040043 | 152 | | Addition of NAS test case 9.1 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031755 |
| TP-23 | TP-040043 | 153 | | Addition of NAS test case 9.2.2 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031757 |
| TP-23 | TP-040043 | 154 | | Addition of NAS test case 9.4.1 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031759 |
| TP-23 | TP-040043 | 155 | | Addition of NAS test case 9.4.2.1 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031761 |
| TP-21 | TP-030209 | 156 | - | CR to 34.123-3 V321 to introduce test case TC_8_2_6_19 | F | 3.2.1 | 3.3.0 | T1-031296 |
| TP-23 | TP-040043 | 156 | | Addition of NAS test case 9.4.2.4.1 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031763 |
| TP-21 | TP-030209 | 157 | - | CR to 34.123-3 V321 to introduce test case TC_8_2_2_7 | F | 3.2.1 | 3.3.0 | T1-031297 |
| TP-23 | TP-040043 | 157 | | Addition of NAS test case 9.4.4 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031765 |
| TP-21 | TP-030209 | 158 | - | CR to 34.123-3 V321 to introduce test case TC_8_2_2_9 | F | 3.2.1 | 3.3.0 | T1-031298 |
| TP-23 | TP-040043 | 158 | | Addition of NAS test case 9.4.5.3 to NAS ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031767 |
| TP-21 | TP-030209 | 159 | - | CR to 34.123-3 V321 to introduce test case TC_8_3_1_11 | F | 3.2.1 | 3.3.0 | T1-031299 |
| TP-23 | TP-040043 | 159 | | Addition of RRC test case 8.3.7.1 to RRC ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031771 |
| TP-21 | TP-030209 | 160 | - | CR to 34.123-3 V321 to introduce test case TC_8_2_6_8 | F | 3.2.1 | 3.3.0 | T1-031300 |
| TP-23 | TP-040043 | 160 | | Addition of RRC test case 8.3.7.2 to RRC ATS V3.4.0 | F | 3.4.0 | 3.5.0 | T1-031918 |
| TP-21 | TP-030209 | 161 | - | CR to 34.123-3 V321 to introduce test case TC_8_4_1_16 | F | 3.2.1 | 3.3.0 | T1-031301 |
| TP-23 | TP-040043 | 161 | | Addition of RRC test case 8.3.7.4 to RRC ATS V3.4.0 | F | 3.4.0 | 3.5.0 | T1-031772 |
| TP-23 | TP-040043 | 162 | | Addition of NAS test case 12.2.1.7 to NAS ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040029 |
| TP-23 | TP-040043 | 163 | | Addition of RAB test case 14.2.27 to RAB ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040033 |
| TP-23 | TP-040043 | 164 | | Introducing test case 12_6_1_1 to NASv330 | B | 3.4.0 | 3.5.0 | T1-031745 |
| TP-23 | TP-040043 | 165 | | Introducing test case 8.2.4.3 to RRCv330 | F | 3.4.0 | 3.5.0 | T1-031747 |
| TP-23 | TP-040043 | 166 | | Introducing test case 8.2.4.4 to RRCv330 | F | 3.3.0 | 3.5.0 | T1-031749 |
| TP-23 | TP-040043 | 167 | | Introduction of Package 2 test case 8.3.1.21 | F | 3.4.0 | 3.5.0 | T1s040049 |
| TP-23 | TP-040043 | 168 | | Addition of NAS test case 9.4.2.2.1 to NAS ATS V3.4.0 | B | 3.3.0 | | T1s040025 |
| TP-23 | TP-040043 | 169 | | Addition of NAS test case 9.4.2.2.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040027 |
| TP-23 | TP-040043 | 170 | | Addition of NAS test case 9.4.9 to NAS ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040014 |
| TP-23 | TP-040043 | 171 | | Addition of RAB test case 14.2.26 to RAB ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040002 |
| TP-23 | TP-040043 | 171 | | Addition of NAS test case 9.4.2.5 to NAS ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040082 |
| TP-23 | TP-040043 | 172 | | Addition of RAB test case 14.2.4 to TS 34.123-3, V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040004 |
| TP-23 | TP-040043 | 172 | | Correction to RRC Package 1 TC 8.2.1.8 and 8.2.1.9 for the mismatch between Radio Bearer setup and PDP context Activation Accept message | B | 3.4.0 | 3.5.0 | T1s040071 |
| TP-23 | TP-040043 | 173 | | Incorrect timer poll value used for SS RLC transmit entity in tcs 8.2.1.8, 8.2.1.9 (Revision of T1-031782) | F | 3.3.0 | 3.5.0 | T1-031842 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|-----|-----|---|-----|-------------|-------------|-----------|
| TP-23 | TP-040043 | 174 | | Correction of Poll bit checking in tc 7.2.3.13 (Revision of T1-031839) | F | 3.3.0 | 3.5.0 | T1-031921 |
| TP-23 | TP-040043 | 175 | | Modification to Radio Bearer Release message in tc 8.2.3.18 and 8.2.3.19 | F | 3.3.0 | 3.5.0 | T1-031924 |
| TP-23 | TP-040043 | 176 | | Maximum allowed UL TX power should not be present in tcs 8.2.2.8, 8.2.2.9 and 8.2.2.23 | F | 3.3.0 | 3.5.0 | T1-031925 |
| TP-23 | TP-040043 | 177 | | New C-RNTI should not be present in tc 8.2.6.20 | F | 3.3.0 | 3.5.0 | T1-031787 |
| TP-23 | TP-040043 | 178 | | Unnecessary waiting time for reconfiguration in tc 8.2.2.23 | F | 3.3.0 | 3.5.0 | T1-031788 |
| TP-23 | TP-040043 | 179 | | Modification to validate TI flag and TI value in TCs 11.3.1 and 11.3.2 | F | 3.3.0 | 3.5.0 | T1-031795 |
| TP-23 | TP-040043 | 180 | | Change U-RNTI and remove UTRAN DRX cycle length coefficient tc 8.3.3.1 | F | 3.3.0 | 3.5.0 | T1-031841 |
| TP-23 | TP-040043 | 181 | | Corrections of Status PDU checking in tc 7.2.3.34 | F | 3.3.0 | 3.5.0 | T1-031786 |
| TP-23 | TP-040043 | 182 | | Correction of number of negatively acknowledged PDUs in tc 7.2.3.16 | F | 3.3.0 | 3.5.0 | T1-031789 |
| TP-23 | TP-040043 | 183 | | Correction of sequence number checking and Verdict assessments in tc 7.2.3.17 | F | 3.3.0 | 3.5.0 | T1-031790 |
| TP-23 | TP-040043 | 184 | | Introducing test case 8.3.1.1 to RRCv340 | F | 3.3.0 | 3.5.0 | T1-031733 |
| TP-23 | TP-040043 | 184 | | Poll Bit and Status PDU content checking in tc 7.2.3.14 | F | 3.3.0 | 3.5.0 | T1-031791 |
| TP-23 | TP-040043 | 185 | | Additional verdicts assigned in tc 7.2.3.20 | F | 3.3.0 | 3.5.0 | T1-031792 |
| TP-23 | TP-040043 | 186 | | SERVICE ACCEPT message NOT to be sent to UE in GMM idle state in tc 11.3.1 and 11.3.2 | F | 3.3.0 | 3.5.0 | T1-031794 |
| TP-23 | TP-040043 | 187 | | Change to performing integrity protection in tc 12.2.1.1 | F | 3.3.0 | 3.5.0 | T1-031778 |
| TP-23 | TP-040043 | 188 | | Correction of Poll bit checking in tc 7.2.3.18 | F | 3.3.0 | 3.5.0 | T1-031781 |
| TP-23 | TP-040019 | 189 | | Addition of RAB test case 14.2.29 to RAB ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040199 |
| TP-23 | TP-040019 | 190 | | Addition of RAB test case 14.2.31.1 to RAB ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040198 |
| TP-23 | TP-040019 | 191 | | Addition of RAB test case 14.2.32.1 to RAB ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040197 |
| TP-23 | TP-040043 | 192 | | Introducing test case 8.3.1.22 to RRCv340 | F | 3.3.0 | 3.5.0 | T1-031797 |
| TP-23 | TP-040019 | 193 | | Addition of RAB test case 14.4.3 to RAB ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1s040196 |
| TP-23 | TP-040043 | 195 | | Introducing test case 8.2.2.18 to RRCv340 | F | 3.4.0 | 3.5.0 | T1-031932 |
| TP-23 | TP-040043 | 205 | | Addition of RRC test case 8.3.2.1 to RRC ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1-031823 |
| TP-23 | TP-040043 | 206 | | Addition of RRC test case 8.3.2.4 to RRC ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031825 |
| TP-23 | TP-040043 | 207 | | Addition of RRC test case 8.3.2.7 to RRC ATS V3.4.0 | F | 3.4.0 | 3.5.0 | T1-031827 |
| TP-23 | TP-040043 | 210 | | Addition of NAS test case 12.2.2.1 to NAS ATS V3.4.0 | F | 3.4.0 | 3.5.0 | T1-031936 |
| TP-23 | TP-040043 | 211 | | Addition of NAS test case 12.4.3.1 to NAS ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1-031937 |
| TP-23 | TP-040043 | 216 | | Revised CR for Changes to Introducing test case 8.2.6.9 required for approval to RRCv340 | F | 3.4.0 | 3.5.0 | T1s040088 |
| TP-23 | TP-040043 | 220 | | Addition of RRC test case 8.4.1.17 to RRC ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1-031940 |
| TP-23 | TP-040043 | 221 | | Addition of RRC test case 8.2.2.19 to RRC ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1-031939 |
| TP-23 | TP-040043 | 222 | | Addition of NAS test case 12.2.1.3 to NAS ATS V3.4.0 | B | 3.4.0 | 3.5.0 | T1-031938 |
| TP-23 | TP-040043 | 224 | | Addition of RRC test case 8.3.1.31 to RRC ATS V3.4.0 | B | 3.3.0 | 3.5.0 | T1-031909 |
| TP-23 | TP-040043 | 226 | | Validation of TMSI status in ATTACH REQUEST message for tc 12.3.1.5 | F | 3.4.0 | 3.5.0 | T1-031913 |
| TP-23 | TP-040043 | 227 | | Validation of optional old PTMSI signature in ATTACH REQUEST message for tc 12.2.1.1 | F | 3.3.0 | 3.5.0 | T1-031914 |
| TP-23 | TP-040043 | 230 | | Validation of CS CKSN in paging response in tc 9.2.1 | F | 3.3.0 | 3.5.0 | T1-031922 |
| TP-23 | TP-040043 | 232 | | To add verified GCF package 1 RRC test case 8.3.1.3 to the approved RRC ATS V3.4.0 | F | 3.4.0 | 3.5.0 | T1-031926 |
| TP-23 | TP-040043 | 233 | | Introducing test case 8.3.1.4 to RRCv340 | F | 3.4.0 | 3.5.0 | T1s040087 |
| TP-24 | TP-040117 | 233 | | Clarification of Section 8.5.1 Authentication: Explicitly stating that Authentication after IDT is an optional/dependent procedure. | F | 3.5.2 | 3.6.0 | T1-040761 |
| TP-23 | TP-040043 | 234 | | Introducing test case 12_4_2_1 to NASv340 | F | 3.4.0 | 3.5.0 | T1-031930 |
| TP-24 | TP-040117 | 234 | | GERAN generic procedures and TTCN encoding rules for CSN.1 specific encoding | F | 3.5.2 | 3.6.0 | T1-040940 |
| TP-22 | TP-030285 | 251 | - | Updating Annex A | F | 3.3.0 | 3.4.0 | - |
| TP-22 | TP-030284 | 252 | - | Security ASP changes | F | 3.3.0 | 3.4.0 | T1-031732 |
| TP-24 | TP-040118 | 255 | | Addition of MAC test case 7.1.3.1 to MAC ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040295 |
| TP-24 | TP-040118 | 256 | | Addition of RAB test case 14.2.49.1 to RAB ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040254 |
| TP-24 | TP-040118 | 257 | | Addition of GCF P1 test case 8.4.1.2 to RRC ATS | B | 3.5.1 | 3.6.0 | T1s040252 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|--|-----|----------|----------|-----------|
| | | | | V3.5.1 | | | | |
| TP-24 | TP-040118 | 258 | | Revised CR for P3 NAS test case 13.2.2.1 to NAS ATS V3.5.1 (revision of T1-040239) | B | 3.5.1 | 3.6.0 | T1s040330 |
| TP-24 | TP-040118 | 259 | | Revised CR for P3 NAS test case 13.2.2.2 to NAS ATS V3.5.1 (revision of T1-040241) | B | 3.5.1 | 3.6.0 | T1s040331 |
| TP-24 | TP-040118 | 260 | | Addition of GCF P3 test case 8.4.1.31 to RRC ATS v3.5.1 | B | 3.5.1 | 3.6.0 | T1s040285 |
| TP-24 | TP-040118 | 261 | | Revised CR for addition of GCF P2 test case 12.4.2.2 to NAS ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040283 |
| TP-24 | TP-040118 | 262 | | Addition of RRC test case 8.3.2.11 to RRC ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040262 |
| TP-24 | TP-040118 | 263 | | Addition of RRC test case 8.4.1.30 to RRC ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040260 |
| TP-24 | TP-040118 | 264 | | Addition of RRC test case 8.4.1.29 to RRC ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040258 |
| TP-24 | TP-040118 | 265 | | Addition of RAB test case 14.2.7a to RAB ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040249 |
| TP-24 | TP-040118 | 266 | | Addition of RAB test case 14.2.5a to RAB ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040247 |
| TP-24 | TP-040118 | 267 | | Addition of RAB test case 14.2.4a to RAB ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040245 |
| TP-24 | TP-040118 | 268 | | Addition of GCF P1 test case 12.4.1.1a to NAS ATS V3.5.1 | B | 3.5.1 | 3.6.0 | T1s040266 |
| TP-24 | TP-040118 | 269 | | Test Case 13.2.1.1 | B | 3.5.1 | 3.6.0 | T1s040237 |
| TP-24 | TP-040118 | 270 | | Addition of GCF P3 test case 10.1.2.6.6 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040234 |
| TP-24 | TP-040118 | 271 | | Addition of GCF P3 test case 10.1.2.7.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040233 |
| TP-24 | TP-040118 | 272 | | Addition of GCF P3 test case 10.1.2.5.5 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040231 |
| TP-24 | TP-040118 | 273 | | Addition of GCF P3 test case 10.1.2.6.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040232 |
| TP-24 | TP-040118 | 274 | | Addition of GCF P3 test case 10.1.2.4.10 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040230 |
| TP-24 | TP-040118 | 275 | | Addition of GCF P3 test case 10.1.2.3.3 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040229 |
| TP-24 | TP-040118 | 276 | | Addition of NAS test case 8.3.1.2 to RRC ATS V3.4.0 (revision of T1-031735) | B | 3.4.0 | 3.6.0 | T1s040226 |
| TP-24 | TP-040118 | 277 | | Addition of NAS test case 8.3.1.5 to RRC ATS V3.4.0 (revision of T1-031807) | B | 3.4.0 | 3.6.0 | T1s040227 |
| TP-24 | TP-040118 | 278 | | Addition of NAS test case 8.3.1.6 to RRC ATS V3.4.0 (revision of T1-031809) | B | 3.4.0 | 3.6.0 | T1s040228 |
| TP-24 | TP-040118 | 279 | | Addition of GCF P3 test case 14.2.12 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040225 |
| TP-24 | TP-040118 | 280 | | Addition of NAS test case 10.1.3.3.1 to NAS ATS V3.4.0 (Revision of T1s040170) | B | 3.4.0 | 3.6.0 | T1s040222 |
| TP-24 | TP-040118 | 281 | | Addition of RRC test case 8.1.10.1 to RRC ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040223 |
| TP-24 | TP-040118 | 282 | | Addition of GCF P2 test case 8.4.1.18 to RRC ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040215 |
| TP-24 | TP-040118 | 283 | | Addition of GCF P2 test case 8.4.1.19 to RRC ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040216 |
| TP-24 | TP-040118 | 284 | | Addition of NAS test case 10.1.3.5.6 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040213 |
| TP-24 | TP-040118 | 285 | | Addition of NAS test case 10.1.2.2.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040209 |
| TP-24 | TP-040118 | 286 | | Addition of RRC test case 8.4.1.26 to RRC ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040207 |
| TP-24 | TP-040118 | 287 | | Addition of GCF P1 test case 8.4.1.3 to RRC ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040205 |
| TP-24 | TP-040118 | 288 | | Addition of RRC test case 8.3.7.3 to RRC ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1-040084 |
| TP-24 | TP-040118 | 289 | | Introducing package 2 test case 8.3.1.10 to RRCv340 (revision of T1-031739) | B | 3.4.0 | 3.6.0 | T1s040204 |
| TP-24 | TP-040118 | 290 | | Introducing package 2 test case 8.3.1.9 to RRCv340 (revision of T1-031737) | B | 3.4.0 | 3.6.0 | T1s040203 |
| TP-24 | TP-040118 | 291 | | Addition of NAS test case 10.1.2.1.1 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040178 |
| TP-24 | TP-040118 | 292 | | Addition of NAS test case 10.1.3.3.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040172 |
| TP-24 | TP-040118 | 293 | | Addition of NAS test case 10.1.3.3.4 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040174 |
| TP-24 | TP-040118 | 294 | | Addition of NAS test case 10.1.2.7.3 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040161 |
| TP-24 | TP-040118 | 295 | | Addition of NAS test case 10.1.2.5.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040149 |
| TP-24 | TP-040118 | 296 | | Addition of RAB test case 14.2.23a.1 to RAB ATS | B | 3.4.0 | 3.6.0 | T1s040065 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|--|-----|----------|----------|-----------|
| | | | | V3.4.0 | | | | |
| TP-24 | TP-040118 | 297 | | Addition of RAB test case 14.2.23b to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040067 |
| TP-24 | TP-040118 | 298 | | Addition of RAB test case 14.2.23c to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040069 |
| TP-24 | TP-040118 | 299 | | Addition of RAB test case 14.2.14.1 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040055 |
| TP-24 | TP-040118 | 300 | | Addition of RAB test case 14.2.14.2 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040057 |
| TP-24 | TP-040118 | 301 | | Addition of RAB test case 14.2.15 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040059 |
| TP-24 | TP-040118 | 302 | | Addition of RAB test case 14.2.16 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040061 |
| TP-24 | TP-040118 | 303 | | Addition of RAB test case 14.2.17 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040063 |
| TP-24 | TP-040118 | 304 | | Addition of RAB test case 14.2.13.2 to RAB ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040053 |
| TP-24 | TP-040118 | 305 | | Addition of NAS test case 10.1.2.4.9 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040129 |
| TP-24 | TP-040118 | 306 | | Addition of NAS test case 10.1.2.4.4 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040121 |
| TP-24 | TP-040118 | 307 | | Addition of NAS test case 10.1.2.4.6 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040123 |
| TP-24 | TP-040118 | 308 | | Addition of NAS test case 10.1.2.6.3 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040139 |
| TP-24 | TP-040118 | 309 | | Addition of NAS test case 10.1.2.4.7 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040099 |
| TP-24 | TP-040118 | 310 | | Addition of NAS test case 10.1.2.4.8 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040101 |
| TP-24 | TP-040118 | 311 | | Addition of NAS test case 10.1.2.9.1 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040107 |
| TP-24 | TP-040118 | 312 | | Addition of NAS test case 10.1.2.3.1 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040091 |
| TP-24 | TP-040118 | 313 | | Addition of NAS test case 10.1.2.4.3 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040093 |
| TP-24 | TP-040118 | 314 | | Addition of NAS test case 9.4.2.3 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040080 |
| TP-24 | TP-040118 | 315 | | Addition of NAS test case 9.4.8 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040023 |
| TP-24 | TP-040118 | 316 | | Addition of NAS test case 12.6.1.2 to NAS ATS V3.4.0 | B | 3.4.0 | 3.6.0 | T1s040016 |
| TP-24 | TP-040119 | 317 | | Quality of Service (QoS) initialisation when setting up a PS call | F | 3.5.1 | 3.6.0 | T1s040320 |
| TP-24 | TP-040119 | 318 | | Correction to RRC Package 2 TC 8.3.1.4 to stop the timer t_WaitS after receiving expected UTRAN MOBILITY INFORMATION CONFIRM message from UE. | F | 3.5.1 | 3.6.0 | T1s040322 |
| TP-24 | TP-040119 | 319 | | Corrections to RRC package 1 and 2 test cases from sections 8.1.x, 8.2.x and 8.3.x to add a delay before SS reconfigures MAC according to the new C-RNTI or U-RNTI assigned to UE. | F | 3.5.1 | 3.6.0 | T1s040323 |
| TP-24 | TP-040119 | 320 | | Correction to RRC TC 8.3.1.3 on the contents of CELL UPDATE CONFIRM message | F | 3.5.1 | 3.6.0 | T1s040324 |
| TP-24 | TP-040119 | 321 | | Correction to RRC Package 1 TC 8.1.1.2 and 8.1.1.3 to add delay before switching to CELL_PCH or URA_PCH | F | 3.5.1 | 3.6.0 | T1s040321 |
| TP-24 | TP-040119 | 322 | | Correction to Package 2 GMM test case 12.2.1.3 for supporting USIM removal without power off | F | 3.5.2 | 3.6.0 | T1s040289 |
| TP-24 | TP-040119 | 323 | | Correction to Package 3 NAS CC test cases 10_1_2_5_5, 10_1_2_6_2 and 10_1_2_7_2 to validate the current TI value. | F | 3.5.1 | 3.6.0 | T1s040297 |
| TP-24 | TP-040119 | 324 | | Correction to Package 3 NAS CC test cases 10.1.2.6.6; introducing PIXIT parameter for UE Call waiting support. | F | 3.5.1 | 3.6.0 | T1s040298 |
| TP-24 | TP-040119 | 325 | | Correction to Package 1 SM test case 11.1.1.1 in handling Modify PDP Context procedure. | F | 3.5.1 | 3.6.0 | T1s040299 |
| TP-24 | TP-040119 | 326 | | Correction to Radio Bearer setup message for Package 1 RAB test case 14.2.13.1 and package 2 RAB test case 14.2.15. | F | 3.5.1 | 3.6.0 | T1s040300 |
| TP-24 | TP-040119 | 327 | | Correction to Package 3 RAB test case 14.2.14.1 Radio Bearer setup in the SS. | F | 3.5.1 | 3.6.0 | T1s040301 |
| TP-24 | TP-040119 | 328 | | Correction to RRC TC 8.2.2.18 and 8.2.2.17 on contents of radio bearer reconfiguration message and comments in test steps of TC 8.2.2.18. | F | 3.5.1 | 3.6.0 | T1s040302 |
| TP-24 | TP-040119 | 329 | | Correction to RRC Package 2 TC 8.3.1.3 to delete the Radio Bearer BCCH mapped to FACH(RB_BCCH_FACH) in the old cell before configuring in the new cell. | F | 3.5.1 | 3.6.0 | T1s040303 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|---|-----|----------|----------|-----------|
| TP-24 | TP-040119 | 330 | | Correction to Package 3 NAS MM test case 9.4.2.2.2 to disable cell C ATT flag | F | 3.5.1 | 3.6.0 | T1s040304 |
| TP-24 | TP-040119 | 331 | | Correction to Package 2 NAS MM test case 9.4.9; introducing postamble to remove PLMN2 from USIM forbidden PLMN list. | F | 3.5.2 | 3.6.0 | T1s040305 |
| TP-24 | TP-040119 | 332 | | Modification to RLC 7.2.3.33 TTCN to meet Test Procedure 'f' in Prose 34.123-1-571. | F | 3.5.1 | 3.6.0 | T1s040306 |
| TP-24 | TP-040119 | 333 | | Correction to Package 3 NAS CC test case 10.1.2.7.3 for assigning FAIL verdict on receiving unexpected RELEASE message. | F | 3.5.1 | 3.6.0 | T1s040288 |
| TP-24 | TP-040119 | 334 | | Correction to RRC TC 8.2.2.10 on contents of radio bearer reconfiguration message. | F | 3.5.1 | 3.6.0 | T1s040291 |
| TP-24 | TP-040119 | 335 | | Correction to RRC Package 2 TC 8.4.1.16 and 8.4.1.17 for contents of SIB 11 and Measurement reporting Interval. | F | 3.5.1 | 3.6.0 | T1s040292 |
| TP-24 | TP-040119 | 336 | | Correction to common test step "ts_SS_2_FACH_1_RACH_ModifyDCH_Cfg" of RRC ATS to release unused RLC entity, related to test cases 8.4.1.18 and 8.4.1.19 | F | 3.5.1 | 3.6.0 | T1s040293 |
| TP-24 | TP-040119 | 337 | | Correction to Package 1 SM TC 11.1.1.1, 11.3.1 and 11.3.2 to harmonize the timer handling and to account for T1-040514, T1s040243 and T1s040244 concerning RAB release and detaching. | F | 3.5.1 | 3.6.0 | T1s040287 |
| TP-24 | TP-040119 | 338 | | Correction to Approved Package 1 TC 11.1.1.1 | F | 3.5.0 | 3.6.0 | T1S040284 |
| TP-24 | TP-040119 | 339 | | Correction to package 2 TC 9.1 to handle PS attach and detach. | F | 3.5.2 | 3.6.0 | T1s040282 |
| TP-24 | TP-040119 | 340 | | Correction to Approved RRC Package 1 TC 8.4.1.1 | F | 3.5.0 | 3.6.0 | T1s040279 |
| TP-24 | TP-040119 | 341 | | Changes to the test step ts_CC_InitTCV_MO | F | 3.5.1 | 3.6.0 | T1s040277 |
| TP-24 | TP-040119 | 342 | | Correction to Package 1 GMM test case 12.3.1.2 for P-TMSI signature check at Step 12. | F | 3.5.1 | 3.6.0 | T1s040278 |
| TP-24 | TP-040119 | 343 | | Regression error corrections to wk12 and wk15. | F | 3.5.1 | 3.6.0 | T1s040274 |
| TP-24 | TP-040119 | 344 | | Correction to Package 2 MM TC 9.4.9 to handle situation when pc_PS is TRUE also. | F | 3.5.2 | 3.6.0 | T1s040273 |
| TP-24 | TP-040119 | 345 | | Correction to GFC P1 RAB test case 14.2.4 | F | 3.5.1 | 3.6.0 | T1s040272 |
| TP-24 | TP-040119 | 346 | | Correction to GFC P3 RAB test cases 14.2.26 and 14.2.27 | F | 3.5.1 | 3.6.0 | T1s040251 |
| TP-24 | TP-040119 | 347 | | Correction to Approved RRC Package 1 TC 8.3.4.2 and 8.3.4.3 | F | 3.5.0 | 3.6.0 | T1s040235 |
| TP-24 | TP-040119 | 348 | | Correction to Approved RRC Package 1 TC 8.3.4.1 | F | 3.5.0 | 3.6.0 | T1s040224 |
| TP-24 | TP-040119 | 349 | | Correction to RRC Package 2 TC 8.2.2.7 for radio bearer messages with specified IEs and correction of default PS RAB and SRBs RLC configurations in RRC ATS. (Revision of T1s040165). | F | 3.4.0 | 3.6.0 | T1s040219 |
| TP-24 | TP-040119 | 350 | | Correction to NAS Package 1 TC 12.5 for selecting UE operation mode C only when mode A not supported and validating RRC connection establishment cause | F | 3.4.0 | 3.6.0 | T1s040220 |
| TP-24 | TP-040119 | 351 | | Correction to RRC Package 1 TC 8.1.2.1 modification to UE system specific capabilities (Revision of T1s040078). | F | 3.4.0 | 3.6.0 | T1s040221 |
| TP-24 | TP-040119 | 352 | | Error correction lists to iWD-wk04 and iWD-wk07 | F | 3.4.0 | 3.6.0 | T1s040188 |
| TP-24 | TP-040119 | 353 | | TTCN corrections to Generic Setup Procedures | F | 3.4.0 | 3.6.0 | T1s040189 |
| TP-24 | TP-040119 | 354 | | General correction to approved GCF P1 (Cell FACH) MAC test cases | F | 3.4.0 | 3.6.0 | T1s040185 |
| TP-24 | TP-040119 | 355 | | Correction to RRC Package 1 TC 8.2.1.8 and 8.2.1.9 for the mismatch between Radio Bearer setup and PDP context Activation Request message (Revision of T1s040071). | F | 3.4.0 | 3.6.0 | T1s040163 |
| TP-24 | TP-040119 | 356 | | Modification to ATT flag usage in TC 12.3.1.5. (Re-submission of T1-031923 on v3.4.0) | F | 3.4.0 | 3.6.0 | T1s040164 |
| TP-24 | TP-040119 | 357 | | Corrections to RRC Package 1 TC 8.1.2.9 to modify timers and RRC Setup Request constraints | F | 3.4.0 | 3.6.0 | T1s040077 |
| TP-24 | TP-040119 | 358 | | Corrections to Package 1 test case tc_8_1_1_1 | F | 3.4.0 | 3.6.0 | T1s040079 |
| TP-24 | TP-040123 | 359 | | Updating Annex A | F | 3.5.2 | 3.6.0 | - |
| TP-25 | TP-040162 | 359 | | ASP updating and other corrections | F | 3.6.1 | 3.7.0 | T1-041407 |
| TP-25 | TP-040149 | 360 | - | Addition of GCF P3 test case 16.1.1 to SMS ATS V3.5.1 | B | 3.5.1 | 3.7.0 | T1s040264 |
| TP-25 | TP-040149 | 361 | - | Addition of GCF P3 test case 16.1.9.1 to SMS ATS V3.5.1 | B | 3.5.1 | 3.7.0 | T1s040307 |
| TP-25 | TP-040149 | 362 | - | Addition of GCF P3 test case 16.1.9.2 to SMS ATS V3.5.1 | B | 3.6.1 | 3.7.0 | T1s040309 |
| TP-25 | TP-040149 | 363 | - | Addition of GCF P3 test case 16.1.10 to SMS ATS V3.5.1 | B | 3.6.1 | 3.7.0 | T1s040311 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|---|-----|----------|----------|-----------|
| TP-25 | TP-040149 | 364 | - | Addition of GCF P3 test case 16.2.1 to SMS ATS V3.6.1 | B | 3.5.1 | 3.7.0 | T1s040313 |
| TP-25 | TP-040149 | 365 | - | Addition of GCF P3 test case 16.2.2 to SMS ATS V3.5.1 | B | 3.6.1 | 3.7.0 | T1s040315 |
| TP-25 | TP-040149 | 366 | - | Addition of GCF P3 test case 16.2.10 to SMS ATS V3.5.1 | B | 3.6.0 | 3.7.0 | T1s040317 |
| TP-25 | TP-040149 | 367 | - | Addition of P2 NAS test case 9.4.2.4 proc 2 to NAS ATS V3.5.1 (revision of T1-040109) | B | 3.6.0 | 3.7.0 | T1s040329 |
| TP-25 | TP-040149 | 368 | - | Addition of NAS test case 12.4.2.5a.2 to NAS ATS V3.5.1 | B | 3.5.1 | 3.7.0 | T1s040337 |
| TP-25 | TP-040149 | 369 | - | Revised CR for addition of GCF P3 test case 8.2.4.1a to RRC ATS V3.5.1 | B | 3.5.1 | 3.7.0 | T1s040339 |
| TP-25 | TP-040149 | 370 | - | Revised CR for Addition of P2 test case 6.2.1.1 to IR_U ATS v3.5.1 (Revision of T1s040325) | B | 3.6.1 | 3.7.0 | T1s040345 |
| TP-25 | TP-040149 | 371 | - | Revised CR for Addition of P2 test case 6.2.1.6 to IR_U ATS v3.5.1 (Revision of T1s040327) | B | 3.5.1 | 3.7.0 | T1s040346 |
| TP-25 | TP-040149 | 372 | - | Addition of RRC test case 8.4.1.40 to RRC ATS V3.5.1 | B | 3.5.1 | 3.7.0 | T1s040352 |
| TP-25 | TP-040149 | 373 | - | Addition of RRC Package 3 test case 8.4.1.33 to IR_U ATS V3.5.1 | B | 3.5.1 | 3.7.0 | T1s040358 |
| TP-25 | TP-040149 | 374 | - | Revised CR for addition of GCF P3 test case 16.1.2 to SMS ATS V3.5.1 | B | 3.6.1 | 3.7.0 | T1s040360 |
| TP-25 | TP-040149 | 375 | - | Revised CR for the addition of GCF P3 test case 8.4.1.35 to IR_U ATS V3.5.1 | B | 3.6.1 | 3.7.0 | T1s040361 |
| TP-25 | TP-040149 | 376 | - | CR for the addition of GCF P3 test case 8.4.1.36 to IR_U ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040364 |
| TP-25 | TP-040149 | 377 | - | Addition of GCF P3 test case 8.3.2.12 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040385 |
| TP-25 | TP-040149 | 378 | - | Addition of RAB Package 3 test case 14.2.57 to RAB ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040387 |
| TP-25 | TP-040149 | 379 | - | Addition of GCF P3 test case 14.2.58 to RAB ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040395 |
| TP-25 | TP-040149 | 380 | - | Addition of GCF P1 test cases 8.1.7.1 to RRC ATS v3.6.1 | B | 3.6.1 | 3.7.0 | T1s040398 |
| TP-25 | TP-040149 | 381 | - | Addition of GCF P1 test case 8.1.7.2 to RRC ATS v3.6.1 | B | 3.5.1 | 3.7.0 | T1s040400 |
| TP-25 | TP-040149 | 382 | - | Addition of RAB Package 2 test case 14.4.2.1 to RAB ATS V3.6.1 | B | 3.5.1 | 3.7.0 | T1s040430 |
| TP-25 | TP-040149 | 383 | - | Addition of RAB Package 3 test case 14.2.38a to RAB ATS V3.6.1 | B | 3.5.1 | 3.7.0 | T1s040432 |
| TP-25 | TP-040149 | 384 | - | Addition of RAB Package 3 test case 14.2.38e to RAB ATS V3.6.1 | B | 3.5.1 | 3.7.0 | T1s040433 |
| TP-25 | TP-040149 | 385 | - | Addition of RAB Package 2 test case 14.4.2.2 to RAB ATS V3.6.1 | B | 3.5.1 | 3.7.0 | T1s040462 |
| TP-25 | TP-040149 | 386 | - | Addition of RAB Package 2 test case 14.4.2.3 to RAB ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040464 |
| TP-25 | TP-040149 | 387 | - | Addition of RAB test case 14.2.51.1 to RAB ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040466 |
| TP-25 | TP-040149 | 388 | - | Addition of RAB test case 14.2.51a.1 to RAB ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040468 |
| TP-25 | TP-040149 | 389 | - | Addition of P3 test case 8.4.1.27 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040470 |
| TP-25 | TP-040149 | 390 | - | Revision CR to introduce GCF P3 Test Case 8.4.1.24 to ATS v3.6.0 | B | 3.5.1 | 3.7.0 | T1s040482 |
| TP-25 | TP-040149 | 391 | - | Revision CR to introduce GCF P3 Test Case 8.4.1.25 to ATS v3.6.0 | B | 3.5.1 | 3.7.0 | T1s040483 |
| TP-25 | TP-040149 | 392 | - | Addition of NAS test case 9.4.7 to NAS ATS V3.6.0 | B | 3.6.1 | 3.7.0 | T1s040513 |
| TP-25 | TP-040149 | 393 | - | Addition of GCF P3 test case 8.4.1.34 to IR_U ATS v3.6.1 | B | 3.6.1 | 3.7.0 | T1s040479 |
| TP-25 | TP-040148 | 394 | - | TTCN correction to P2 test case 8.1.10.1 | F | 3.5.2 | 3.7.0 | T1s040236 |
| TP-25 | TP-040148 | 395 | - | Correction to Approved RRC Package 1 TC 8.3.1.1 | F | 3.5.1 | 3.7.0 | T1s040334 |
| TP-25 | TP-040148 | 396 | - | Correction to Package 2 NAS MM test case 9.4.2.2.1 to validate of LOCATION UPDATE REQUEST message and disable ATT flag. | F | 3.5.1 | 3.7.0 | T1s040335 |
| TP-25 | TP-040148 | 397 | - | Correction to RRC Package 2 TC 8.4.1.18 and TC 8.4.1.19 for inconsistency in System Information Block 12. | F | 3.5.1 | 3.7.0 | T1s040336 |
| TP-25 | TP-040148 | 398 | - | Correction to Approved Package 1 RRC TC 8.1.2.2 | F | 3.5.1 | 3.7.0 | T1s040341 |
| TP-25 | TP-040148 | 399 | - | Corrections to RRC test case 6.2.1.1 | F | 3.5.1 | 3.7.0 | T1s040347 |
| TP-25 | TP-040148 | 400 | - | Corrections to RRC test case 6.2.1.6 | F | 3.5.1 | 3.7.0 | T1s040349 |
| TP-25 | TP-040148 | 401 | - | Correction to Approved RRC Package 1 TC 8.3.4.2 | F | 3.5.0 | 3.7.0 | T1s040351 |
| TP-25 | TP-040148 | 402 | - | Correction to Approved RRC Package 2 TC 8.2.4.3 | F | 3.5.0 | 3.7.0 | T1s040363 |
| TP-25 | TP-040148 | 403 | - | Correction to Approved RRC Package 1 TC 8.3.4.3 | F | 3.6.0 | 3.7.0 | T1s040366 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|-----|-----|---|-----|----------|----------|-----------|
| TP-25 | TP-040148 | 404 | - | Regression error corrections to wk17, wk20 and wk23. | F | 3.6.1 | 3.7.0 | T1s040367 |
| TP-25 | TP-040148 | 405 | - | TTCN Correction to GCF P2 IR_U 8.3.7.1 & 8.3.7.4 | F | 3.6.0 | 3.7.0 | T1s040374 |
| TP-25 | TP-040148 | 406 | - | Correction to Package 2 NAS CCMM test cases 9.4.8; for removal of 'USIM removal possible while UE is powered' support. | F | 3.6.1 | 3.7.0 | T1s040375 |
| TP-25 | TP-040148 | 407 | - | Correction to RRC TC 8.3.2.4 on value of the wait timer started for the UE to enter Idle mode. | F | 3.6.1 | 3.7.0 | T1s040376 |
| TP-25 | TP-040148 | 408 | - | Correction to RRC Package 2 TC 8.2.1.9 to handle cell update before configuring radio bearer from DCH to FACH. | F | 3.6.1 | 3.7.0 | T1s040377 |
| TP-25 | TP-040148 | 409 | - | Correction to RRC TC 8.2.6.19 and 8.2.6.20 to add delay before switching to CELL_PCH/URA_PCH | F | 3.6.1 | 3.7.0 | T1s040378 |
| TP-25 | TP-040148 | 410 | - | Correction to Package 3 RAB test case 14.2.27, 14.2.29, 14.2.31.1 and 14.2.32.1 for the dl_TxPower in DL DPCH Info during Radio Bearer Setup at the SS. | F | 3.6.1 | 3.7.0 | T1s040383 |
| TP-25 | TP-040148 | 411 | - | Correction to Package 2 RAB test case 14.4.3 | F | 3.6.1 | 3.7.0 | T1s040384 |
| TP-25 | TP-040148 | 412 | - | Correction to test steps "ts_ReceiveFirstSDUs_RB10" and "ts_ReceiveFirstSDUs_RB13" of Package 3 RAB test case 14.2.49.1 | F | 3.6.1 | 3.7.0 | T1s040389 |
| TP-25 | TP-040148 | 413 | - | Correction to GMM Package 2 approved TC 12.6.1.2 in handling Attach procedure. | F | 3.6.1 | 3.7.0 | T1s040402 |
| TP-25 | TP-040148 | 414 | - | Delay to ensure the proper transmission of Cell Update Confirm in 8.3.4.2. | F | 3.6.1 | 3.7.0 | T1s040403 |
| TP-25 | TP-040148 | 415 | - | Guard timer setting if registration is made to a PLMN different from the normal one | F | 3.6.1 | 3.7.0 | T1s040420 |
| TP-25 | TP-040148 | 416 | - | Correction to RRC Package 2 TC 8.3.1.31. | F | 3.6.1 | 3.7.0 | T1s040422 |
| TP-25 | TP-040148 | 417 | - | Correction to Package 2 RAB test case 14.4.3 to assign tcv_CN_Domain. | F | 3.6.1 | 3.7.0 | T1s040423 |
| TP-25 | TP-040148 | 418 | - | Addition of a delay after reception of an RRC Connection Release Complete Message | F | 3.6.1 | 3.7.0 | T1s040424 |
| TP-25 | TP-040148 | 419 | - | General correction for test cases where UE is switched off Cell(s) released and reconfigured | F | 3.6.1 | 3.7.0 | T1s040425 |
| TP-25 | TP-040148 | 420 | - | Corrections to RRC Package 3 TC 8.4.1.29 and 8.4.1.30. | F | 3.6.1 | 3.7.0 | T1s040429 |
| TP-25 | TP-040148 | 421 | - | Correction to RRC TC 8.2.3.8 in ts_RRC_ReceiveRB_SetupCmpl. | F | 3.6.1 | 3.7.0 | T1s040478 |
| TP-25 | TP-040148 | 422 | - | Correction to Approved RRC Package 2 TC 8.3.1.22 | F | 3.6.0 | 3.7.0 | T1s040426 |
| TP-25 | TP-040148 | 423 | - | TTCN Correction to test case 8.4.1.1 to RRC ATS V3.6.0 | F | 3.6.0 | 3.7.0 | T1s040390 |
| TP-25 | TP-040167 | 424 | - | Addition of NAS test case 9.4.3.5 to NAS ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040460 |
| TP-25 | TP-040167 | 425 | - | Addition of GCF P4 test case 10.1.2.2.1 ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040410 |
| TP-25 | TP-040167 | 426 | - | Addition of GCF P4 test case 9.5.5 ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040408 |
| TP-25 | TP-040167 | 427 | - | Addition of NAS test case 12.6.1.3.2 to NAS ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040456 |
| TP-25 | TP-040167 | 428 | - | Addition of NAS test case 12.9.14 to NAS ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040458 |
| TP-25 | TP-040167 | 429 | - | Addition of NAS test case 12.4.1.3 to NAS ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040452 |
| TP-25 | TP-040167 | 430 | - | Addition of NAS test case 12.9.3 to NAS ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040519 |
| TP-25 | TP-040167 | 431 | - | Addition of NAS test case 12.9.4 to NAS ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040521 |
| TP-25 | TP-040167 | 432 | - | Addition of RRC test case 8.2.2.4 to RRC ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040515 |
| TP-25 | TP-040167 | 433 | - | Addition of RRC test case 8.2.6.12 to RRC ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040517 |
| TP-25 | TP-040167 | 434 | - | Addition of RAB test case 14.2.38c to RAB ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040527 |
| TP-25 | TP-040167 | 435 | - | Addition of RAB test case 14.2.38f to RAB ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040529 |
| TP-25 | TP-040167 | 436 | - | Addition of RAB test case 14.2.40 to RAB ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040523 |
| TP-25 | TP-040167 | 437 | - | Addition of RAB test case 14.2.41 to RAB ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040525 |
| TP-25 | TP-040167 | 438 | - | Addition of RRC Package 4 test case 8.1.3.5 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040500 |
| TP-25 | TP-040167 | 439 | - | Addition of RRC Package 4 test case 8.2.1.4 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040502 |
| TP-25 | TP-040167 | 440 | - | Addition of RRC Package 4 test case 8.2.1.7 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040504 |
| TP-25 | TP-040167 | 441 | - | Addition of RRC Package 4 test case 8.1.2.3 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040498 |
| TP-25 | TP-040167 | 442 | - | Addition of P4 RRC test case 8.3.2.9 | B | 3.6.1 | 3.7.0 | T1s040495 |
| TP-25 | TP-040167 | 443 | - | Addition of P4 RRC test case 8.2.6.2 | B | 3.6.1 | 3.7.0 | T1s040573 |
| TP-25 | TP-040167 | 444 | - | Addition of P4 RRC test case 8.3.1.17 | B | 3.6.1 | 3.7.0 | T1s040493 |
| TP-25 | TP-040167 | 445 | - | Addition of P4 RRC test case 8.1.6.1 | B | 3.6.1 | 3.7.0 | T1s040489 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| TP-25 | TP-040167 | 446 | - | Addition of GCF P4 test case 8.3.1.12 to RRC ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040446 |
| TP-25 | TP-040167 | 447 | - | Addition of GCF P4 test case 8.2.6.11 to RRC ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040444 |
| TP-25 | TP-040167 | 448 | - | Addition of GCF P4 test case 9.5.4 ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040440 |
| TP-25 | TP-040167 | 449 | - | Addition of P3 test case 8.4.1.37 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040474 |
| TP-25 | TP-040167 | 450 | - | Addition of P3 test case 8.4.1.38 to RRC ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040476 |
| TP-25 | TP-040167 | 451 | - | Addition of GCF P4 test case 12.2.1.2 ATS V3.6.0 | B | 3.6.0 | 3.7.0 | T1s040450 |
| TP-25 | TP-040167 | 452 | - | Addition of RAB Package 3 test case 14.2.38b to RAB ATS V3.6.1 | B | 3.6.1 | 3.7.0 | T1s040533 |
| TP-25 | TP-040167 | 453 | - | Modification to MAC Package 2 test case 7.1.3.1 | F | 3.6.1 | 3.7.0 | T1s040531 |
| TP-25 | TP-040167 | 454 | - | Correction to NAS test cases 9.4.2.3 (P2), 9.4.2.4 Proc 2 (P2), and 12.4.1.1a (P1) | F | 3.6.1 | 3.7.0 | T1s040514 |
| TP-25 | TP-040167 | 455 | - | Correction to Package 3 SMS test case 16.2.1. | F | 3.6.1 | 3.7.0 | T1s040497 |
| TP-25 | TP-040167 | 456 | - | Correction to GCF P1 test case 8.3.1.1 | F | 3.6.0 | 3.7.0 | T1s040484 |
| TP-25 | TP-040193 | 460 | - | Updating Annex A | F | 3.6.1 | 3.7.0 | - |
| TP-26 | TP-040237 | 461 | - | ASP update and other corrections | F | 3.7.0 | 3.8.0 | T1-041975 |
| TP-26 | TP-040237 | 462 | - | Addition of AT command lists used in ATSSs | F | 3.7.0 | 3.8.0 | T1-041976 |
| TP-26 | TP-040237 | 463 | - | ASP change for Radio Link Modification | F | 3.7.0 | 3.8.0 | T1-041694 |
| TP-26 | TP-040241 | 1050 | - | Addition of GCF P4 test case 8.2.2.35 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040743 |
| TP-26 | TP-040241 | 1051 | - | Addition of RRC test case 8.3.1.18 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040448 |
| TP-26 | TP-040241 | 1052 | - | Addition of GCF P1 test case 8.4.1.5 to RRC ATS v3.7.0 | B | 3.7.0 | 3.8.0 | T1s040739 |
| TP-26 | TP-040241 | 1053 | - | Addition of GCF P4 test case 8.1.7.1d to RRC ATS v3.7.0 | B | 3.7.0 | 3.8.0 | T1s040717 |
| TP-26 | TP-040241 | 1054 | - | Addition of RRC Package 3 test case 6.1.1.5 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040698 |
| TP-26 | TP-040241 | 1055 | - | Addition of GCF P4 test case 12.2.1.4.1 ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040690 |
| TP-26 | TP-040241 | 1056 | - | Addition of GCF P4 test case 12.4.1.4a ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040679 |
| TP-26 | TP-040241 | 1057 | - | Addition of RRC test case 8.2.3.29 to RRC ATS V3.7.0 (Revision of T1s040688) | B | 3.7.0 | 3.8.0 | T1s040703 |
| TP-26 | TP-040241 | 1058 | - | Changes to GCF package 2 IR_U test case 12.8 required for approval | B | 3.7.0 | 3.8.0 | T1s040615 |
| TP-26 | TP-040241 | 1059 | - | Addition of P4 test case 8.3.11.1 to IR_U ATS v3.7.0, (Revision of T1s040633). | B | 3.7.0 | 3.8.0 | T1s040684 |
| TP-26 | TP-040241 | 1060 | - | Addition of GCF P4 test cases 8.1.7.1c to RRC ATS v3.7.0 | B | 3.7.0 | 3.8.0 | T1s040677 |
| TP-26 | TP-040241 | 1061 | - | Correction to Package 4 test case 12.9.7b ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040674 |
| TP-26 | TP-040241 | 1062 | - | Addition of GCF P4 test case 12.4.1.4b ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040628 |
| TP-26 | TP-040241 | 1063 | - | Correction to Package 4 GMM test case 12.4.1.1b (Revised CR T1s040467) | B | 3.7.0 | 3.8.0 | T1s040656 |
| TP-26 | TP-040241 | 1064 | - | Addition of RRC test case 8.3.1.24 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040671 |
| TP-26 | TP-040241 | 1065 | - | Addition of RRC test case 8.3.2.2 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040669 |
| TP-26 | TP-040241 | 1066 | - | Addition of NAS test case 12.4.1.4c2 to NAS ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040664 |
| TP-26 | TP-040241 | 1067 | - | Addition of RRC test case 8.3.1.25 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040658 |
| TP-26 | TP-040241 | 1068 | - | Addition of NAS test case 12.6.1.3.3 to NAS ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040651 |
| TP-26 | TP-040241 | 1069 | - | Addition of RRC test case 8.3.2.13 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040653 |
| TP-26 | TP-040241 | 1070 | - | Addition of P4 test case 8.1.3.4 to the RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040649 |
| TP-26 | TP-040241 | 1071 | - | Addition of P4 test case 8.3.7.13 to IR_U ATS v3.7.0 | B | 3.7.0 | 3.8.0 | T1s040638 |
| TP-26 | TP-040241 | 1072 | - | Addition of P4 test case 8.3.7.7 to IR_U ATS v3.7.0 | B | 3.7.0 | 3.8.0 | T1s040640 |
| TP-26 | TP-040241 | 1073 | - | Addition of NAS test case 12.9.8 to NAS ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040613 |
| TP-26 | TP-040241 | 1074 | - | Addition of NAS test case 12.4.1.4d1 to NAS ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040635 |
| TP-26 | TP-040241 | 1075 | - | Addition of P2 test case 6.2.1.9 to IR_U ATS v3.7.0 | B | 3.7.0 | 3.8.0 | T1s040604 |
| TP-26 | TP-040241 | 1076 | - | Addition of GCF P4 test case 12.2.1.5b ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040595 |
| TP-26 | TP-040241 | 1077 | - | Addition of GCF P4 test case 12.9.7c ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040587 |
| TP-26 | TP-040241 | 1078 | - | Addition of GCF P4 test case 8.2.2.31 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040485 |
| TP-26 | TP-040241 | 1079 | - | Addition of RAB Package 4 test case 14.4.2a.3 to RAB ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040626 |
| TP-26 | TP-040241 | 1080 | - | Addition of RAB Package 4 test case 14.4.2a.2 to RAB ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040624 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| TP-26 | TP-040241 | 1081 | - | Addition of RAB Package 4 test case 14.4.2a.1 to RAB ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040622 |
| TP-26 | TP-040241 | 1082 | - | Addition of RRC Package 4 test case 8.2.3.11 to RRC ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040620 |
| TP-26 | TP-040241 | 1083 | - | Addition of NAS test case 12.4.3.4 to NAS ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040609 |
| TP-26 | TP-040241 | 1084 | - | Addition of NAS test case 12.9.6 to NAS ATS V3.7.0 | B | 3.7.0 | 3.8.0 | T1s040607 |
| TP-26 | TP-040241 | 1085 | - | Changes to GCF package 4 IR_U test case 8.3.7.9 required for approval. | B | 3.7.0 | 3.8.0 | T1s040552 |
| TP-26 | TP-040241 | 1086 | - | Changes to GCF package 4 IR_U test case 8.3.7.5 required for approval. | B | 3.7.0 | 3.8.0 | T1s040548 |
| TP-26 | TP-040241 | 1087 | - | Addition of GCF P4 test case 12.4.1.2 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040585 |
| TP-26 | TP-040241 | 1088 | - | Addition of GCF P4 test case 10.1.2.2.3 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040412 |
| TP-26 | TP-040241 | 1089 | - | Addition of GCF P4 test case 9.5.7.1 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040404 |
| TP-26 | TP-040241 | 1090 | - | Addition of GCF P4 test cases 8.1.12 to RRC ATS v3.6.1 | B | 3.7.0 | 3.8.0 | T1s040602 |
| TP-26 | TP-040241 | 1091 | - | Addition of GCF P4 test cases 8.1.7.1b to RRC ATS v3.6.1 | B | 3.7.0 | 3.8.0 | T1s040600 |
| TP-26 | TP-040241 | 1092 | - | Addition of GCF P4 test case 12.2.1.6.2 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040436 |
| TP-26 | TP-040241 | 1093 | - | Addition of GCF P4 test case 12.2.1.5a.1 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040434 |
| TP-26 | TP-040241 | 1094 | - | Addition of GCF P4 test case 8.3.1.15 to RRC ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040487 |
| TP-26 | TP-040241 | 1095 | - | Addition of GCF P4 test case 8.1.2.4 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040442 |
| TP-26 | TP-040241 | 1096 | - | Addition of NAS test case 12.4.1.4d2 to NAS ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040579 |
| TP-26 | TP-040241 | 1097 | - | Addition of GCF P3 test case 6.1.1.7 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040427 |
| TP-26 | TP-040241 | 1098 | - | Addition of GCF P3 test case 12.4.2.5a.1 ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040472 |
| TP-26 | TP-040241 | 1099 | - | Re-submission of GCF package 2 IR_U test case 6.2.2.1 for approval. | B | 3.7.0 | 3.8.0 | T1s040534 |
| TP-26 | TP-040241 | 1100 | - | Addition of RAB test case 14.2.51b.1 to RAB ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040570 |
| TP-26 | TP-040241 | 1101 | - | Addition of RRC test case 10.1.2.3.7 to RRC ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040508 |
| TP-26 | TP-040241 | 1102 | - | Addition of RRC test case 10.1.2.7.1 to RRC ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040510 |
| TP-26 | TP-040241 | 1103 | - | Addition of RRC test case 10.1.2.3.2 to RRC ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040506 |
| TP-26 | TP-040241 | 1104 | - | Addition of NAS Package 4 test case 12.2.1.6 Proc1 to NAS ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040565 |
| TP-26 | TP-040241 | 1105 | - | Addition of NAS Package 4 test case 12.2.1.4 proc2 to NAS ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040561 |
| TP-26 | TP-040241 | 1106 | - | Addition of NAS Package 4 test case 12.2.1.5a Proc2 to NAS ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040563 |
| TP-26 | TP-040241 | 1107 | - | Addition of NAS Package 4 test case 12.2.1.10 to NAS ATS V3.6.1 | B | 3.7.0 | 3.8.0 | T1s040559 |
| TP-26 | TP-040241 | 1108 | - | Addition of RAB test case 14.2.23a2 to RAB ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040556 |
| TP-26 | TP-040241 | 1109 | - | Addition of NAS test case 12.6.1.3.1 to NAS ATS V3.6.0 | B | 3.7.0 | 3.8.0 | T1s040454 |
| TP-26 | TP-040241 | 1110 | - | Addition of GCF P2 RRC 8.4.1.7 - Revision of T1s040381 | B | 3.7.0 | 3.8.0 | T1s040766 |
| TP-26 | TP-040242 | 1111 | - | Correction to RRC P3 TC 8.4.1.37 | F | 3.7.0 | 3.8.0 | T1s040735 |
| TP-26 | TP-040242 | 1112 | - | Correction to RRC P2 TC 8.3.1.31 for the timer value before step 5. | F | 3.7.0 | 3.8.0 | T1s040736 |
| TP-26 | TP-040242 | 1113 | - | Correction to approved GCF P4 test cases 8.1.7.1c | F | 3.7.0 | 3.8.0 | T1s040734 |
| TP-26 | TP-040242 | 1114 | - | Correction to approved package 4 NAS Test case tc_12_6_1_3_2 | F | 3.7.0 | 3.8.0 | T1s040737 |
| TP-26 | TP-040242 | 1115 | - | Corrections to RRC Package 1 TC 8.4.1.1. | F | 3.7.0 | 3.8.0 | T1s040738 |
| TP-26 | TP-040242 | 1116 | - | Correction to the RRC default message handler on Dc SAP for Deactivate PDP Context Request message in RRC ATS. | F | 3.7.0 | 3.8.0 | T1s040731 |
| TP-26 | TP-040242 | 1117 | - | Correction to TTCN for MultiRAB test cases. | F | 3.7.0 | 3.8.0 | T1s040732 |
| TP-26 | TP-040242 | 1118 | - | Correction to approved package 4 NAS Test case tc_12_6_1_3_1 | F | 3.7.0 | 3.8.0 | T1s040733 |
| TP-26 | TP-040242 | 1119 | - | Summary of regression errors in the wk45 ATS. | F | 3.7.0 | 3.8.0 | T1s040723 |
| TP-26 | TP-040242 | 1120 | - | Correction to RRC P4 TC 8.1.7.1b for comments in test steps. | F | 3.7.0 | 3.8.0 | T1s040711 |
| TP-26 | TP-040242 | 1121 | - | Correction to GCF P3 NAS test Cases 13.2.1.1, 13.2.2.1 and 13.2.2.2 | F | 3.7.0 | 3.8.0 | T1s040712 |
| TP-26 | TP-040242 | 1122 | - | Correction to GCF P4 NAS test Case 12.2.1.6.2 | F | 3.7.0 | 3.8.0 | T1s040713 |
| TP-26 | TP-040242 | 1123 | - | Correction to RAB test case 14.4.2.3 and 14.4.2a.3. | F | 3.7.0 | 3.8.0 | T1s040714 |
| TP-26 | TP-040242 | 1124 | - | Correction to RRC Package 2 TC 8.3.1.3. | F | 3.7.0 | 3.8.0 | T1s040722 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| TP-26 | TP-040242 | 1125 | - | Correction to AT Command used for GCF P1 NAS test Case 10.1.2.5.1 | F | 3.7.0 | 3.8.0 | T1s040724 |
| TP-26 | TP-040242 | 1126 | - | Correction in TTCN for execution of Opmode C UE. | F | 3.7.0 | 3.8.0 | T1s040725 |
| TP-26 | TP-040242 | 1127 | - | Correction to RRC Package 4 TC 8.1.2.3 | F | 3.7.0 | 3.8.0 | T1s040726 |
| TP-26 | TP-040242 | 1128 | - | Correction to RRC test cases 8.1.2.1 and 8.1.2.7 | F | 3.7.0 | 3.8.0 | T1s040727 |
| TP-26 | TP-040242 | 1130 | - | Correction to RRC test cases 8.1.3.1, 8.1.3.3, 8.1.3.4 and 8.1.3.5 | F | 3.7.0 | 3.8.0 | T1s040729 |
| TP-26 | TP-040242 | 1131 | - | Correction to RRC Package 1 TC 8.1.2.9 | F | 3.7.0 | 3.8.0 | T1s040730 |
| TP-26 | TP-040242 | 1132 | - | Correction to Package 2 RRC test case 8.3.1.4 | F | 3.7.0 | 3.8.0 | T1s040721 |
| TP-26 | TP-040242 | 1133 | - | Correction to Package 3 RRC inter-RAT measurement test cases 8.4.1.31 + 8.4.1.33 + 8.4.1.34 + 8.4.1.35 + 8.4.1.36 + 8.4.1.40 | F | 3.7.0 | 3.8.0 | T1s040715 |
| TP-26 | TP-040242 | 1134 | - | Correction to approved NAS test case 12.9.4 | F | 3.7.0 | 3.8.0 | T1s040716 |
| TP-26 | TP-040242 | 1135 | - | Correction to Approved RRC Package 2 TC 8.3.7.2 | F | 3.7.0 | 3.8.0 | T1s040709 |
| TP-26 | TP-040242 | 1136 | - | Correction to Approved RRC Package 3 TC 8.2.4.1a | F | 3.7.0 | 3.8.0 | T1s040708 |
| TP-26 | TP-040242 | 1137 | - | Correction to Approved RRC Package 3 TC 8.4.1.31 | F | 3.7.0 | 3.8.0 | T1s040707 |
| TP-26 | TP-040242 | 1138 | - | Correction to GCF P2 test cases 6.2.1.1, 6.2.1.6 and 6.2.1.9 to IR_U ATS v3.7.0 to check the displayed PLMN. | F | 3.7.0 | 3.8.0 | T1s040693 |
| TP-26 | TP-040242 | 1139 | - | Correction to Package 2 RAB test case 14.4.2.2 and 14.4.2.3. | F | 3.7.0 | 3.8.0 | T1s040697 |
| TP-26 | TP-040242 | 1140 | - | Correction to GCF P4 NAS test Case 12.4.1.2 (Revision of T1-040673) | F | 3.7.0 | 3.8.0 | T1s040696 |
| TP-26 | TP-040242 | 1141 | - | Correction of GCF P1 test case 7.2.3.23 | F | 3.7.0 | 3.8.0 | T1s040694 |
| TP-26 | TP-040242 | 1142 | - | Global correction of Structured Type Constraints containing wildcards violating coding convention E.3.7 | F | 3.7.0 | 3.8.0 | T1s040695 |
| TP-26 | TP-040242 | 1143 | - | Correction to GCF P4 RRC test Case 8.3.1.15 | F | 3.7.0 | 3.8.0 | T1s040675 |
| TP-26 | TP-040242 | 1144 | - | Extension to Guard Timer for Approved NAS GMM Test Cases | F | 3.7.0 | 3.8.0 | T1s040692 |
| TP-26 | TP-040242 | 1145 | - | Correction to RRC TC 8.1.12 for handling correct number of RRC Connection Release Complete message based on the value of N308 | F | 3.7.0 | 3.8.0 | T1s040687 |
| TP-26 | TP-040242 | 1146 | - | Corrections Required for the wk42 ATS | F | 3.7.0 | 3.8.0 | T1s040682 |
| TP-26 | TP-040242 | 1147 | - | Corrections to release of SS resources for a cell during test case execution | F | 3.7.0 | 3.8.0 | T1s040681 |
| TP-26 | TP-040242 | 1148 | - | Correction to approved RRC Package 1 8.3.1.1 | F | 3.7.0 | 3.8.0 | T1s040668 |
| TP-26 | TP-040242 | 1149 | - | Correction to approved RRC Package 4 TC 8.2.6.11 | F | 3.7.0 | 3.8.0 | T1s040667 |
| TP-26 | TP-040242 | 1150 | - | Regression test error corrections to TTCN deliveries of wk40 | F | 3.7.0 | 3.8.0 | T1s040666 |
| TP-26 | TP-040242 | 1151 | - | Correction of GCF P1 test case 7.2.3.14 | F | 3.7.0 | 3.8.0 | T1s040660 |
| TP-26 | TP-040242 | 1152 | - | Correction of GCF P1 test case 11.1.1.1 | F | 3.7.0 | 3.8.0 | T1s040661 |
| TP-26 | TP-040242 | 1153 | - | Correction of GCF P3 SMS test cases 16.1.1, 16.1.2, 16.1.9.1, 16.1.9.2, 16.1.10, 16.2.1, 16.2.2, 16.2.10 | F | 3.7.0 | 3.8.0 | T1s040662 |
| TP-26 | TP-040242 | 1154 | - | Corrections Required for the wk40 ATS | F | 3.7.0 | 3.8.0 | T1s040663 |
| TP-26 | TP-040242 | 1155 | - | Correction to Approved RRC Package 2 TC 8.2.4.3 | F | 3.7.0 | 3.8.0 | T1s040655 |
| TP-26 | TP-040242 | 1156 | - | Correction to Package 3 SMS test cases. | F | 3.7.0 | 3.8.0 | T1s040637 |
| TP-26 | TP-040242 | 1157 | - | Correction to approved package 4 NAS Test case tc_12_4_1_4d2 | F | 3.7.0 | 3.8.0 | T1s040648 |
| TP-26 | TP-040242 | 1158 | - | Correction to Package 4 NAS test case 12.2.1.2 for increasing the guard timer. | F | 3.7.0 | 3.8.0 | T1s040630 |
| TP-26 | TP-040242 | 1159 | - | Regression error corrections to TTCN deliveries of wk34 and wk37 | F | 3.7.0 | 3.8.0 | T1s040636 |
| TP-26 | TP-040242 | 1160 | - | Summary of regression errors in the wk37 ATS. | F | 3.7.0 | 3.8.0 | T1s040617 |
| TP-26 | TP-040242 | 1161 | - | Correction to RRC Package 1 test cases 8.1.7.1 and 8.1.7.2 (Revision of T1s040532) | F | 3.7.0 | 3.8.0 | T1s040618 |
| TP-26 | TP-040242 | 1162 | - | Corrections Required for the wk37 ATS (Revision of T1s040606) | F | 3.7.0 | 3.8.0 | T1s040619 |
| TP-26 | TP-040242 | 1163 | - | Correction to Package 2 RRC test case 8.3.2.11 to increase the timer while waiting for URA Update. | F | 3.7.0 | 3.8.0 | T1s040599 |
| TP-26 | TP-040242 | 1164 | - | Correction to Approved RRC Package 1 TC 8.1.2.2 | F | 3.7.0 | 3.8.0 | T1s040584 |
| TP-26 | TP-040242 | 1165 | - | Radiolink removal and subsequent addition to align the TTCN with 34.123-1 | F | 3.7.0 | 3.8.0 | T1s040583 |
| TP-26 | TP-040242 | 1166 | - | TTCN Correction to Test Case 14.2.12 and 14.2.16 | F | 3.7.0 | 3.8.0 | T1s040581 |
| TP-26 | TP-040242 | 1167 | - | Correction to Approved RRC Package 2 TC 8.4.1.2 | F | 3.7.0 | 3.8.0 | T1s040582 |
| TP-26 | TP-040242 | 1168 | - | Corrections to GCF package 2 IR_U test case 6.2.1.1 | F | 3.7.0 | 3.8.0 | T1s040536 |
| TP-26 | TP-040242 | 1169 | - | Corrections to GCF package 2 IR_U test case 6.2.1.6 | F | 3.7.0 | 3.8.0 | T1s040538 |
| TP-26 | TP-040242 | 1170 | - | Correction of GCF package 2 IR_U test case 8.3.7.1. | F | 3.7.0 | 3.8.0 | T1s040540 |
| TP-26 | TP-040242 | 1171 | - | Correction of GCF package 2 IR_U test case 8.3.7.2. | F | 3.7.0 | 3.8.0 | T1s040542 |
| TP-26 | TP-040242 | 1172 | - | Correction of GCF package 2 IR_U test case 8.3.7.3. | F | 3.7.0 | 3.8.0 | T1s040544 |
| TP-26 | TP-040242 | 1173 | - | Correction of GCF package 2 IR_U test case 8.3.7.4. | F | 3.7.0 | 3.8.0 | T1s040546 |
| TP-26 | TP-040242 | 1174 | - | Correction of GCF package 2 IR_U test case 8.4.1.40. | F | 3.7.0 | 3.8.0 | T1s040554 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| TP-26 | TP-040242 | 1175 | - | TTCN changes to approved package 1 RRC testcase 8.4.1.3 | F | 3.7.0 | 3.8.0 | T1s040576 |
| TP-26 | TP-040242 | 1176 | - | Correction to MultiRAB test cases 14.2.38a, 14.2.38b and 14.2.38e | F | 3.7.0 | 3.8.0 | T1s040575 |
| TP-26 | TP-040242 | 1177 | - | Correction to Approved RRC Package 2 TC 8.4.1.2 | F | 3.7.0 | 3.8.0 | T1s040572 |
| TP-26 | TP-040242 | 1178 | - | Addition of verdicts in RRC default message handler on Dc SAP for Deactivate PDP Context Request message in RRC ATS.(Revision of T1s040512) | F | 3.7.0 | 3.8.0 | T1s040569 |
| TP-26 | TP-040242 | 1179 | - | Regression error corrections to TTCN deliveries of wk26 and wk31 | F | 3.7.0 | 3.8.0 | T1s040558 |
| TP-26 | TP-040242 | 1180 | - | Modification to MAC Package 2 test case 7.1.3.1 | F | 3.7.0 | 3.8.0 | T1s040531 |
| TP-26 | TP-040242 | 1181 | - | Correction to NAS test cases 9.4.2.3 (P2), 9.4.2.4 Proc 2 (P2), and 12.4.1.1a (P1) | F | 3.7.0 | 3.8.0 | T1s040514 |
| TP-26 | TP-040242 | 1182 | - | Correction to Package 3 SMS test case 16.2.1. | F | 3.7.0 | 3.8.0 | T1s040497 |
| TP-26 | TP-040242 | 1183 | - | Correction to GCF P1 test case 8.3.1.1 | F | 3.7.0 | 3.8.0 | T1s040484 |
| TP-26 | TP-040242 | 1184 | - | Regression test error corrections to TTCN deliveries of wk42 | F | 3.7.0 | 3.8.0 | T1s040699 |
| TP-26 | TP-040238 | 1185 | - | Updating Annex A | F | 3.7.0 | 3.8.0 | - |
| TP-27 | TP-050039 | 1185 | | RRC Connection Establishment: Reject with InterRATInfo is set to GSM and selection to the designated system fails | B | 3.8.0 | 5.0.0 | T1s050056 |
| TP-27 | TP-050039 | 1186 | | RRC Connection Establishment: Reject with interRATInfo is set to GSM | B | 3.8.0 | 5.0.0 | T1s050054 |
| TP-27 | TP-050039 | 1187 | | MM connection / abortion by the network / cause not equal to #6 | B | 3.8.0 | 5.0.0 | T1s050044 |
| TP-27 | TP-050039 | 1188 | | PS detach / rejected / PS services not allowed in this PLMN/ test1 | B | 3.8.0 | 5.0.0 | T1s050046 |
| TP-27 | TP-050039 | 1189 | | Routing area updating / abnormal cases / attempt counter check / miscellaneous reject causes | B | 3.8.0 | 5.0.0 | T1s050018 |
| TP-27 | TP-050039 | 1190 | | RRC / Paging for Connection in connected mode (URA_PCH, multiple paging records) | B | 3.8.0 | 5.0.0 | T1s050038 |
| TP-27 | TP-050039 | 1191 | | Combined routing area updating / abnormal cases / access barred due to access class control / test procedure 1 | B | 3.8.0 | 5.0.0 | T1s050036 |
| TP-27 | TP-050039 | 1192 | | Combined routing area updating / abnormal cases / access barred due to access class control / test procedure 2 | B | 3.8.0 | 5.0.0 | T1s050034 |
| TP-27 | TP-050039 | 1193 | | Interactive or background / UL:64 DL:384 kbps / PS RAB + UL:3.4 DL: 3.4 kbps SRBs for DCCH / 20 ms TTI | B | 3.8.0 | 5.0.0 | T1s050025 |
| TP-27 | TP-050039 | 1194 | | Measurement Report on INITIAL DIRECT TRANSFER message and UPLINK DIRECT TRANSFER message | B | 3.8.0 | 5.0.0 | T1s050031 |
| TP-27 | TP-050039 | 1195 | | Conversational / speech / UL:5.9 DL:5.9 kbps / CS RAB + UL:3.4 DL:3.4 kbps SRBs for DCCH | B | 3.8.0 | 5.0.0 | T1s050023 |
| TP-27 | TP-050039 | 1196 | | Interactive or background / UL:384 DL:384 kbps / PS RAB + UL:3.4 DL:3.4 kbps SRBs for DCCH / 10 ms TTI | B | 3.8.0 | 5.0.0 | T1s050010 |
| TP-27 | TP-050039 | 1197 | | Interactive or background / UL:128 DL:128 kbps / PS RAB + UL:3.4 DL:3.4 kbps SRBs for DCCH | B | 3.8.0 | 5.0.0 | T1s050008 |
| TP-27 | TP-050039 | 1198 | | Cell change order from UTRAN/To GPRS/CELL_DCH/Failure (Physical channel & Reversion Failure) | B | 3.8.0 | 5.0.0 | T1s050001 |
| TP-27 | TP-050039 | 1199 | | RRC Connection Release in CELL_DCH state (Network Authentication Failure): Success | B | 3.8.0 | 5.0.0 | T1s050006 |
| TP-27 | TP-050039 | 1200 | | Inter system handover from UTRAN/To GSM/Speech/Failure (Physical channel Failure and Reversion Failure) | B | 3.8.0 | 5.0.0 | T1s040798 |
| TP-27 | TP-050039 | 1201 | | Cell reselection using cell status and cell reservations | B | 3.8.0 | 5.0.0 | T1s040794 |
| TP-27 | TP-050039 | 1202 | | RRC / Radio Bearer Establishment for transition from CELL_DCH to CELL_FACH (Frequency band modification): Success | B | 3.8.0 | 5.0.0 | T1s040796 |
| TP-27 | TP-050039 | 1203 | | Correct Selection of RACH parameters (FDD) | B | 3.8.0 | 5.0.0 | T1s040755 |
| TP-27 | TP-050039 | 1204 | | Measurement Control and Report: Additional Measurements list | B | 3.8.0 | 5.0.0 | T1s040791 |
| TP-27 | TP-050039 | 1205 | | PS attach / rejected / PS services not allowed in this PLMN | B | 3.8.0 | 5.0.0 | T1s040779 |
| TP-27 | TP-050039 | 1206 | | Access Service class selection for RACH transmission | B | 3.8.0 | 5.0.0 | T1s040757 |
| TP-27 | TP-050039 | 1207 | | Selection of RAT for UPLMN; Automatic mode | B | 3.8.0 | 5.0.0 | T1s040746 |
| TP-27 | TP-050039 | 1208 | | Selection of RAT for OPLMN; Automatic mode | B | 3.8.0 | 5.0.0 | T1s040748 |
| TP-27 | TP-050039 | 1209 | | Cell reselection if cell becomes barred or S<0; UTRAN to GPRS (CELL_FACH) | B | 3.8.0 | 5.0.0 | T1s040701 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| TP-27 | TP-050039 | 1210 | | Service Request / RAB re-establishment / UE initiated / multiple PDP contexts | B | 3.8.0 | 5.0.0 | T1s040719 |
| TP-27 | TP-050040 | 1211 | | Summary of regression errors in the wk04 ATS | F | 3.8.0 | 5.0.0 | T1s050063 |
| TP-27 | TP-050040 | 1212 | | Summary of regression errors in the wk04 ATS. | F | 3.8.0 | 5.0.0 | T1s050062 |
| TP-27 | TP-050040 | 1213 | | Correction to RRC P2 TC 8.4.1.7 | F | 3.8.0 | 5.0.0 | T1s050040 |
| TP-27 | TP-050040 | 1214 | | Summary of regression errors in the wk04 ATS. | F | 3.8.0 | 5.0.0 | T1s050061 |
| TP-27 | TP-050040 | 1215 | | Summary of regression errors in the wk04 ATS. | F | 3.8.0 | 5.0.0 | T1s050058 |
| TP-27 | TP-050040 | 1216 | | Correction to approved package 4 NAS Test case 12_6_1_3_3 | F | 3.8.0 | 5.0.0 | T1s050052 |
| TP-27 | TP-050040 | 1217 | | Correction to Approved RRC Package 3 TC 8.4.1.38 | F | 3.8.0 | 5.0.0 | T1s050051 |
| TP-27 | TP-050040 | 1218 | | Correction to Approved NAS Package 3 TC 9.4.7 | F | 3.8.0 | 5.0.0 | T1s050053 |
| TP-27 | TP-050040 | 1219 | | Correction to Approved RRC Package 2 TC 8.3.7.2 / 8.3.7.3 | F | 3.8.0 | 5.0.0 | T1s050050 |
| TP-27 | TP-050040 | 1220 | | Correction to Approved RRC Package 3 TC 8.4.1.36 | F | 3.8.0 | 5.0.0 | T1s050048 |
| TP-27 | TP-050040 | 1221 | | Correction to Approved IR_U Package 2 test case 6.2.2.1 | F | 3.8.0 | 5.0.0 | T1s050042 |
| TP-27 | TP-050040 | 1222 | | Correction to Approved IR_U Package 4 Test Case 8.3.7.12 | F | 3.8.0 | 5.0.0 | T1s050043 |
| TP-27 | TP-050040 | 1223 | | Correction to test step "ts_AT_TerminateCall". | F | 3.8.0 | 5.0.0 | T1s050041 |
| TP-27 | TP-050040 | 1224 | | Wk51 regression error report on unapproved and approved Idlemode testcases 6.1.2.x | F | 3.8.0 | 5.0.0 | T1s050027 |
| TP-27 | TP-050040 | 1225 | | Correction to approved package 3 NAS Test case 9_4_7 | F | 3.8.0 | 5.0.0 | T1s050030 |
| TP-27 | TP-050040 | 1226 | | Summary of regression errors in the wk51 ATS. | F | 3.8.0 | 5.0.0 | T1s050028 |
| TP-27 | TP-050040 | 1227 | | Correction to RRC P1 TC 8.4.1.3 | F | 3.8.0 | 5.0.0 | T1s050020 |
| TP-27 | TP-050040 | 1228 | | Correction to RRC P2 TC 8.3.1.22 for removing check of "FOR" field value from ROUTING AREA UPDATING REQUEST message. | F | 3.8.0 | 5.0.0 | T1s050021 |
| TP-27 | TP-050040 | 1229 | | Correction to Package 4 NAS test case 12.9.14 | F | 3.8.0 | 5.0.0 | T1s050022 |
| TP-27 | TP-050040 | 1230 | | Summary of regression errors in the wk51 ATS. | F | 3.8.0 | 5.0.0 | T1s050033 |
| TP-27 | TP-050040 | 1231 | | Correction to 34.123-3, section 16, SMS test cases regarding Validity Period Formats | F | 3.8.0 | 5.0.0 | T1s050029 |
| TP-27 | TP-050040 | 1232 | | Additional Corrections required for 14.4.2.2 test cases in the RAB ATS. | F | 3.8.0 | 5.0.0 | T1s050017 |
| TP-27 | TP-050040 | 1233 | | Revised corrections to approved IR_U test cases 6_2_1_1, 6_2_1_7 and 6_2_1_8. | F | 3.8.0 | 5.0.0 | T1s050012 |
| TP-27 | TP-050040 | 1234 | | Corrections required for "Combinations on SCCPCH" test cases in the RAB ATS. | F | 3.8.0 | 5.0.0 | T1s040801 |
| TP-27 | TP-050040 | 1235 | | Correction to RRC P1 TC 8.4.1.5 | F | 3.8.0 | 5.0.0 | T1s040797 |
| TP-27 | TP-050040 | 1236 | | Additional Corrections Required for the wk47 ATS | F | 3.8.0 | 5.0.0 | T1s040765 |
| TP-27 | TP-050040 | 1237 | | Correction to Package 4 NAS test case 12.2.1.5a Proc1 | F | 3.8.0 | 5.0.0 | T1s040773 |
| TP-27 | TP-050040 | 1238 | | Summary of regression errors in the wk49 ATS. | F | 3.8.0 | 5.0.0 | T1s040790 |
| TP-27 | TP-050040 | 1239 | | Summary of regression errors in wk49 ATS. | F | 3.8.0 | 5.0.0 | T1s040789 |
| TP-27 | TP-050040 | 1240 | | Correction to Approved RRC Package 4 TC 8.3.11.1 | F | 3.8.0 | 5.0.0 | T1s040788 |
| TP-27 | TP-050040 | 1241 | | Correction required to Package 4 NAS test case 12.9.13. | F | 3.8.0 | 5.0.0 | T1s040787 |
| TP-27 | TP-050040 | 1242 | | Correction to approved GCF P4 NAS test case 12.9.8: improvement of incomplete implementation of T1-041930 | F | 3.8.0 | 5.0.0 | T1s040786 |
| TP-27 | TP-050040 | 1243 | | Correction to SIB1 contents for approved RRC Idle Mode and InterRAT test cases. | F | 3.8.0 | 5.0.0 | T1s040774 |
| TP-27 | TP-050040 | 1244 | | Correction to Package 4 NAS test cases 12.4.3.4. | F | 3.8.0 | 5.0.0 | T1s040781 |
| TP-27 | TP-050040 | 1245 | | Corrections to RRC Package 3 TC 8.4.1.26 to change the Downlink Power level settings of Cell A at Time Instant 'T1'. | F | 3.8.0 | 5.0.0 | T1s040782 |
| TP-27 | TP-050040 | 1246 | | Correction to GMM Test cases for removing check of "FOR" field value from ATTACH REQUEST and ROUTING AREA UPDATING REQUEST messages. (Revision to TTCN CR T1s040763) | F | 3.8.0 | 5.0.0 | T1s040783 |
| TP-27 | TP-050040 | 1247 | | Correction to RRC P1 TC 8.4.1.5 (Revision of T1s040739) | F | 3.8.0 | 5.0.0 | T1s040770 |
| TP-27 | TP-050040 | 1248 | | Corrections required to rlc_SizeIndex in the RAB ATS | F | 3.8.0 | 5.0.0 | T1s040772 |
| TP-27 | TP-050040 | 1249 | | Corrections to RRC 8.3.2.x for Special LI | F | 3.8.0 | 5.0.0 | T1s040769 |
| TP-27 | TP-050040 | 1250 | | Summary of regression errors in the wk47 ATS. | F | 3.8.0 | 5.0.0 | T1s040768 |
| TP-27 | TP-050040 | 1251 | | Summary of regression errors in the wk47 ATS. | F | 3.8.0 | 5.0.0 | T1s040760 |
| TP-27 | TP-050040 | 1252 | | Correction to Package 2 RRC test case 8.3.2.11 to increase the wait time while checking that UE does not send URA Update. | F | 3.8.0 | 5.0.0 | T1s040752 |
| TP-27 | TP-050040 | 1253 | | Correction to RRC Test Case 8.3.1.22. | F | 3.8.0 | 5.0.0 | T1s040753 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|---|-----|-------------|-------------|-------------|
| TP-27 | TP-050040 | 1254 | | Correction to approved package 2 NAS Test case 9.4.2.3 | F | 3.8.0 | 5.0.0 | T1s040761 |
| TP-27 | TP-050040 | 1255 | | Corrections to RRC Package 1 TC 8.3.1.1 to add a delay before SS reconfigures MAC according to the new C-RNTI or U-RNTI assigned to UE. | F | 3.8.0 | 5.0.0 | T1s040762 |
| TP-27 | TP-050040 | 1256 | | Summary of regression errors in the wk47 ATS. | F | 3.8.0 | 5.0.0 | T1s040750 |
| TP-27 | TP-050040 | 1257 | | Corrections Required for the wk47 ATS | F | 3.8.0 | 5.0.0 | T1s040758 |
| TP-27 | TP-050040 | 1258 | | Summary of regression errors in IR_U wk47 ATS. | F | 3.8.0 | 5.0.0 | T1s040754 |
| TP-27 | TP-050040 | 1259 | | Correction to package 1 test case 8.3.4.3. | F | 3.8.0 | 5.0.0 | T1s040742 |
| TP-27 | TP-050040 | 1260 | | Correction to approved package 4 NAS Test cases 12.2.1.6 proc1, 12.2.1.6 proc2 and 12.9.8 | F | 3.8.0 | 5.0.0 | T1s040745 |
| TP-27 | TP-050037 | 1261 | - | Add new verified TTCN test cases CR to 34.123-3 (prose) in Annex A | F | 3.8.0 | 5.0.0 | - |
| TP-27 | TP-050036 | 1263 | - | Corrections Required for "Combinations on SCCPCH" configurations. | F | 3.8.0 | 5.0.0 | T1-050201r3 |
| TP-27 | TP-050036 | 1264 | - | Introduce ASP for HSDPA | B | 3.8.0 | 5.0.0 | T1-050036 |
| TP-27 | TP-050036 | 1265 | - | Introduce ASP for LCR TDD | B | 3.8.0 | 5.0.0 | T1-050037 |
| TP-27 | TP-050036 | 1266 | - | Replacement of 34.123-3 Release 99 by a pointer to the newly created Release 5 version | F | 3.8.0 | 3.9.0 | T1-050250 |
| TP-27 | TP-050036 | 1267 | - | Corrections of encoding rules and postambles | F | 3.8.0 | 5.0.0 | T1-050282 |
| TP-27 | TP-050036 | 1268 | - | Introduce ASP for A-GPS | B | 3.8.0 | 5.0.0 | T1-050284 |
| RP-28 | RP-050365 | 1270 | - | Addition of NAS WI 12 test case 12.3.2.7 to NAS ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050128 |
| RP-28 | RP-050365 | 1271 | - | Addition of WI-012 NAS test case 12.9.7a to NAS ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050134 |
| RP-28 | RP-050365 | 1272 | - | Addition of NAS WI 12 test case 12.9.9 to NAS ATS V3.8.0 | B | 5.0.0 | 5.1.0 | R5s050080 |
| RP-28 | RP-050365 | 1273 | - | Addition of WI-010 P3 RAB test case 14.2.43.1 to RAB ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050100 |
| RP-28 | RP-050365 | 1274 | - | Addition of WI-012 RAB test case 14.2.43.2 to RAB ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050098 |
| RP-28 | RP-050365 | 1275 | - | Addition of WI-012 RAB test case 14.2.58a to RAB ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050096 |
| RP-28 | RP-050365 | 1276 | - | Addition of WI-012 RLC test case 7.2.3.28 to RLC ATS V3.8.0 | B | 5.0.0 | 5.1.0 | R5s050066 |
| RP-28 | RP-050365 | 1277 | - | Addition of WI-012 RLC test case 7.2.3.32 to RLC ATS V3.8.0 | B | 5.0.0 | 5.1.0 | R5s050068 |
| RP-28 | RP-050365 | 1278 | - | Addition of WI-012 RLC test case 7.2.3.35 to RLC ATS V3.8.0 | B | 5.0.0 | 5.1.0 | R5s050070 |
| RP-28 | RP-050365 | 1279 | - | Addition of WI12 test case 8.1.1.9 to RRC ATS v5.0.0 (Revision of R5s050125) | B | 5.0.0 | 5.1.0 | R5s050141 |
| RP-28 | RP-050365 | 1280 | - | Addition of WI12 test cases 8.1.2.11 to RRC ATS v3.8.0 | B | 5.0.0 | 5.1.0 | R5s050074 |
| RP-28 | RP-050365 | 1281 | - | Addition of RRC WI-012 test case 8.3.1.30 to RRC ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050138 |
| RP-28 | RP-050365 | 1282 | - | Addition of WI-012 test case 8.3.7.16 to IR_U ATS 3.8.0. | B | 5.0.0 | 5.1.0 | R5s050076 |
| RP-28 | RP-050365 | 1283 | - | Regression changes on TC 8.3.9.5 - WK09 | B | 5.0.0 | 5.1.0 | R5s050112 |
| RP-28 | RP-050365 | 1284 | - | Addition of RRC WI-012 test case 8.4.1.6 to RRC ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050132 |
| RP-28 | RP-050365 | 1285 | - | Addition of WI-012 NAS test case 9.4.5.4.6 to NAS ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050136 |
| RP-28 | RP-050365 | 1286 | - | Addition of NAS P4 test case 12.4.1.4c Proc1 to NAS ATS V5.0.0 | B | 5.0.0 | 5.1.0 | R5s050170 |
| RP-28 | RP-050365 | 1287 | - | Revision and Addition of WI-10 (P2) test cases 6.2.2.2 to IR_U ATS v5.0.0 | B | 5.0.0 | 5.1.0 | R5s050173 |
| RP-28 | RP-050281 | 1289 | - | Summary of regression errors for IR_U_r3_wk17. | F | 5.0.0 | 5.1.0 | R5s050146 |
| RP-28 | RP-050281 | 1290 | - | Correction to Approved RRC Package 4 TC 8.4.1.40 | F | 5.0.0 | 5.1.0 | R5s050169 |
| RP-28 | RP-050281 | 1291 | - | Correction of a missing LB entity in LB setup introduced in Rel-5 in the definition of CLOSE UE TEST LOOP | F | 5.0.0 | 5.1.0 | R5s050168 |
| RP-28 | RP-050281 | 1292 | - | Correction to approved testcase 8.2.2.4 and 8.2.4.4 | F | 5.0.0 | 5.1.0 | R5s050165 |
| RP-28 | RP-050281 | 1293 | - | Summary of additional regression errors in the wk17 ATS. | F | 5.0.0 | 5.1.0 | R5s050166 |
| RP-28 | RP-050281 | 1294 | - | Correction to approved testcase 8.2.1.9 | F | 5.0.0 | 5.1.0 | R5s050163 |
| RP-28 | RP-050281 | 1295 | - | Correction in TTCN to support Band II UE for UE capability Information | F | 5.0.0 | 5.1.0 | R5s050167 |
| RP-28 | RP-050281 | 1296 | - | Correction to value of periodic RA update timer IE in Attach Accept message | F | 5.0.0 | 5.1.0 | R5s050152 |
| RP-28 | RP-050281 | 1297 | - | Correction to Order of AT commands used for initiation of PS call | F | 5.0.0 | 5.1.0 | R5s050153 |
| RP-28 | RP-050281 | 1298 | - | Correction to approved testcase 8.1.7.1b | F | 5.0.0 | 5.1.0 | R5s050154 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| RP-28 | RP-050281 | 1299 | - | Regression Error Report based on wk17ATS | F | 5.0.0 | 5.1.0 | R5s050164 |
| RP-28 | RP-050281 | 1300 | - | Correction in TTCN to enable ciphering for 3G to 2G handover. | F | 5.0.0 | 5.1.0 | R5s050149 |
| RP-28 | RP-050281 | 1301 | - | Correction to approved RRC testcases 8.1.3.3 and 8.1.3.4 | F | 5.0.0 | 5.1.0 | R5s050148 |
| RP-28 | RP-050281 | 1302 | - | Correction to GCF WI-10 test case 8.4.1.3 | F | 5.0.0 | 5.1.0 | R5s050140 |
| RP-28 | RP-050281 | 1303 | - | Corrections to WI-010 P3 RAB test cases 14.2.12, 14.2.16 & 14.2.17 | F | 5.0.0 | 5.1.0 | R5s050127 |
| RP-28 | RP-050281 | 1304 | - | Correction required for WI-010 P3 RAB Testcase 14.2.38c. | F | 5.0.0 | 5.1.0 | R5s050124 |
| RP-28 | RP-050281 | 1305 | - | Correction to GCF Package 3 RRC test case 8.3.1.24 | F | 5.0.0 | 5.1.0 | R5s050123 |
| RP-28 | RP-050281 | 1306 | - | Summary of additional regression errors in the wk09 ATS. | F | 5.0.0 | 5.1.0 | R5s050116 |
| RP-28 | RP-050281 | 1307 | - | Correction to approved RRC Package 4 TC 8.3.1.18 | F | 5.0.0 | 5.1.0 | R5s050117 |
| RP-28 | RP-050281 | 1308 | - | Correction to WI-12 Test Case 8.3.7.16 | F | 5.0.0 | 5.1.0 | R5s050115 |
| RP-28 | RP-050282 | 1309 | - | Correction to RRC P3 TC 8.3.2.13 | F | 5.0.0 | 5.1.0 | R5s050113 |
| RP-28 | RP-050282 | 1310 | - | Regression Error Report based on wk09 ATS | F | 5.0.0 | 5.1.0 | R5s050114 |
| RP-28 | RP-050282 | 1311 | - | Summary of regression errors for IR_U_wk09. | F | 5.0.0 | 5.1.0 | R5s050110 |
| RP-28 | RP-050282 | 1312 | - | Correction to RRC P2 TC 8.3.1.21 | F | 5.0.0 | 5.1.0 | R5s050111 |
| RP-28 | RP-050282 | 1313 | - | Correction to Approved NAS Package 4 TC 12.4.1.4a | F | 5.0.0 | 5.1.0 | R5s050109 |
| RP-28 | RP-050283 | 1314 | - | Summary of regression errors in the wk09 ATS. | F | 5.0.0 | 5.1.0 | R5s050106 |
| RP-28 | RP-050282 | 1315 | - | Correction for the MM test step "ts_GMM_RAU_AcceptEPLMN" | F | 5.0.0 | 5.1.0 | R5s050105 |
| RP-28 | RP-050282 | 1316 | - | Correction to SMS Test Suite for AT Commands | F | 5.0.0 | 5.1.0 | R5s050104 |
| RP-28 | RP-050282 | 1317 | - | Changes required to support Release 5 | F | 5.0.0 | 5.1.0 | R5s050095 |
| RP-28 | RP-050282 | 1318 | - | Correction to approved package WI-12 NAS Test case 9_5_7_2 | F | 5.0.0 | 5.1.0 | R5s050103 |
| RP-28 | RP-050283 | 1319 | - | Correction to approved testcase 8.1.10.1 | F | 5.0.0 | 5.1.0 | R5s050102 |
| RP-28 | RP-050282 | 1320 | - | Handling of L2 Acknowledgement on GERAN side. | F | 5.0.0 | 5.1.0 | R5s050094 |
| RP-28 | RP-050282 | 1321 | - | Correction to Approved RRC Package 4 TC 8.3.1.18 | F | 5.0.0 | 5.1.0 | R5s050093 |
| RP-28 | RP-050282 | 1322 | - | Correction to IR_U P4 Approved test case 8.3.11.4 | F | 5.0.0 | 5.1.0 | R5s050091 |
| RP-28 | RP-050282 | 1323 | - | Summary of iWD_07 regression test errors | F | 5.0.0 | 5.1.0 | R5s050078 |
| RP-28 | RP-050282 | 1324 | - | Corrections to section 16 SMS test cases to improve AT command handling | F | 5.0.0 | 5.1.0 | R5s050090 |
| RP-28 | RP-050282 | 1325 | - | Correction to approved GCF P4 test cases 8.1.7.1c | F | 5.0.0 | 5.1.0 | R5s050086 |
| RP-28 | RP-050282 | 1326 | - | Summary of regression errors in the wk07 ATS. | F | 5.0.0 | 5.1.0 | R5s050088 |
| RP-28 | RP-050282 | 1327 | - | Correction to approved NAS WI 12 test case 12.4.1.5. | F | 5.0.0 | 5.1.0 | R5s050083 |
| RP-28 | RP-050282 | 1328 | - | Correction to approved GCF P4 test cases 8.1.7.1d | F | 5.0.0 | 5.1.0 | R5s050087 |
| RP-28 | RP-050282 | 1329 | - | Correction to approved package 2 NAS Test case 9_5_2 | F | 5.0.0 | 5.1.0 | R5s050082 |
| RP-28 | RP-050282 | 1330 | - | Correction to RRC P1 TC 8.4.1.1, 8.4.1.3 and P3 TC 8.4.1.29 | F | 5.0.0 | 5.1.0 | R5s050065 |
| RP-28 | RP-050365 | 1331 | - | Revision of RRC WI-14 test case 8.2.3.30 to RRC ATS v5.0.0 | B | 5.0.0 | 5.1.0 | R5s050179 |
| RP-28 | RP-050365 | 1332 | - | Addition of RRC WI-014 test case 8.2.4.36 to RRC ATS V5.0.0 (Revision of R5s050161) | B | 5.0.0 | 5.1.0 | R5s050199 |
| RP-28 | RP-050366 | 1333 | 1 | Add new verified and e-mail approved TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 5.0.0 | 5.1.0 | - |
| RP-28 | RP-050278 | 1334 | - | Correction to specification version references | F | 5.0.0 | 5.1.0 | R5-050639 |
| RP-29 | RP-050527 | 1334 | - | Addition of WI-10 NAS test case 12.4.2.4 to NAS ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050295 |
| RP-28 | RP-050278 | 1335 | - | Modifying AT Commands, ASPs, TSOs and PIXITs | F | 5.0.0 | 5.1.0 | R5-050955 |
| RP-29 | RP-050527 | 1335 | - | Addition of WI12 test case 8.2.1.24 to RRC ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050259 |
| RP-28 | RP-050278 | 1336 | - | HSDPA ASP Modification | F | 5.0.0 | 5.1.0 | R5-050975 |
| RP-29 | RP-050527 | 1336 | - | Addition of WI12 test case 8.2.1.34 to RRC ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050261 |
| RP-28 | RP-050278 | 1337 | - | Modifying G_L2_SYSINFO_REQ ASP | F | 5.0.0 | 5.1.0 | R5-050980 |
| RP-29 | RP-050527 | 1337 | - | Addition of RRC WI-012 test case 8.2.1.33 to RRC ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050242 |
| RP-28 | RP-050278 | 1338 | - | CR to 34.123-3 Rel-5: Addition of a new ASP required for test case tc_8_1_7_1d | F | 5.0.0 | 5.1.0 | R5-050983 |
| RP-29 | RP-050527 | 1338 | - | Addition of NAS WI-012 test case 12.2.1.11 to NAS ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050236 |
| RP-29 | RP-050527 | 1339 | - | Addition of WI-10 RRC test case 8.4.1.14 to RRC ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050228 |
| RP-29 | RP-050527 | 1340 | - | Addition of RRC WI-14 test case 8.2.6.42 to RRC ATS v5.0.0 | B | 5.1.0 | 5.2.0 | R5s050225 |
| RP-29 | RP-050527 | 1341 | - | Addition of WI-010 (P4) test case 8.3.9.3 to IR_U ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050219 |
| RP-29 | RP-050527 | 1342 | - | Addition of RRC WI-010 (P2) test case 8.2.4.1 to | B | 5.1.0 | 5.2.0 | R5s050210 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| | | | | RRC ATS V5.0.0 | | | | |
| RP-29 | RP-050527 | 1343 | - | Addition of RRC WI-014 test case 8.3.1.32 to RRC ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050217 |
| RP-29 | RP-050527 | 1344 | - | Addition of RRC WI-014 test case 8.2.1.28 to RRC ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050212 |
| RP-29 | RP-050527 | 1345 | - | Addition of RRC WI-14 test case 8.2.1.32 to RRC ATS v5.0.0 | B | 5.1.0 | 5.2.0 | R5s050206 |
| RP-29 | RP-050527 | 1346 | - | Addition of RRC WI-14 test case 8.2.1.31 to RRC ATS v5.0.0 | B | 5.1.0 | 5.2.0 | R5s050204 |
| RP-29 | RP-050527 | 1347 | - | Addition of RRC WI-014 test case 8.2.2.38 to RRC ATS V5.0.0 (Revision of R5s050157) | B | 5.1.0 | 5.2.0 | R5s050197 |
| RP-29 | RP-050527 | 1348 | - | Addition of WI-010 RRC test case 6.1.2.1 to RRC ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050189 |
| RP-29 | RP-050527 | 1349 | - | Addition of RRC WI-14 test case 8.2.1.30 to RRC ATS v5.0.0 | B | 5.1.0 | 5.2.0 | R5s050184 |
| RP-29 | RP-050527 | 1350 | - | Addition of RRC WI-10 test case 8.3.1.23 to RRC ATS V5.0.0 | B | 5.1.0 | 5.2.0 | R5s050175 |
| RP-29 | RP-050527 | 1351 | - | Addition of RRC WI-14 test case 8.2.1.29 to RRC ATS v5.0.0 | B | 5.1.0 | 5.2.0 | R5s050182 |
| RP-29 | RP-050527 | 1352 | - | Addition of WI-014 test case 8.3.1.34 to HS_ENH ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050347 |
| RP-29 | RP-050527 | 1353 | - | Addition of WI14 test case 8.3.1.35 to HS_ENH ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050321 |
| RP-29 | RP-050528 | 1354 | - | Addition of WI14 test case 8.2.6.40 to HS_ENH ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050323 |
| RP-29 | RP-050528 | 1355 | - | Addition of WI-014 MAC test case 7.1.5.4 to HS_ENH ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050318 |
| RP-29 | RP-050528 | 1356 | - | Addition of WI14 test case 7.1.5.3 to HS_ENH ATS V5.1.0 | B | 5.1.0 | 5.2.0 | R5s050315 |
| RP-29 | RP-050528 | 1357 | - | Revision (of R5s0500248) to introduce test case 8_2_2_40 based on wk31 ATS | B | 5.1.0 | 5.2.0 | R5s050339 |
| RP-29 | RP-050528 | 1358 | - | Revision (of R5s050253) to introduce test case 8_3_1_33 based on wk31 ATS | B | 5.1.0 | 5.2.0 | R5s050341 |
| RP-29 | RP-050528 | 1359 | - | Revision (of R5s050250) to introduce test case 14_6_1 based on wk31 ATS | B | 5.1.0 | 5.2.0 | R5s050345 |
| RP-29 | RP-050528 | 1360 | - | Addition of WI14 test case 7.1.5.5 to HS_ENH ATS V5.1.0 (Revision of R5s050276) | B | 5.1.0 | 5.2.0 | R5s050313 |
| RP-29 | RP-050528 | 1361 | - | Addition of WI14 test case 7.1.5.1 to HS_ENH ATS V5.1.0 (Revision of R5s050257) | B | 5.1.0 | 5.2.0 | R5s050311 |
| RP-29 | RP-050528 | 1362 | - | Addition of WI-014 test case 8.2.1.27 to HS_ENH ATS V5.1.0 (Revision of CR R5s050263) | B | 5.1.0 | 5.2.0 | R5s050307 |
| RP-29 | RP-050528 | 1363 | - | Addition of WI-014 test case 8.2.6.49 to HS_ENH ATS V5.1.0 (Revision of R5s050265) | B | 5.1.0 | 5.2.0 | R5s050309 |
| RP-29 | RP-050528 | 1364 | - | Re-submission of WI-014 test case 8.3.11.9 to HS_ENH ATS V5.1.0. (Revision of R5s050150). | B | 5.1.0 | 5.2.0 | R5s050349 |
| RP-29 | RP-050528 | 1365 | - | Addition of WI-014 test case 8.2.2.36 to HS_ENH ATS V5.1.0 (Revision of CR R5s050267) | B | 5.1.0 | 5.2.0 | R5s050360 |
| RP-29 | RP-050529 | 1366 | - | Correction required in HSDPA constraint cbr_108_RRC_ConnReq_r5 | F | 5.1.0 | 5.2.0 | R5s050351 |
| RP-29 | RP-050529 | 1367 | - | Correction to approved WI-010 MM Test Cases 9_4_2_2_1 and 9_4_2_2_2 | F | 5.1.0 | 5.2.0 | R5s050337 |
| RP-29 | RP-050529 | 1368 | - | Corrections to test step ts_C4_CheckCellPCH and ts_C4_CheckCellPCH_r5 | F | 5.1.0 | 5.2.0 | R5s050326 |
| RP-29 | RP-050529 | 1369 | - | Correction to GCF P1(WI-10) approved RRC test case 8.1.1.2 | F | 5.1.0 | 5.2.0 | R5s050320 |
| RP-29 | RP-050529 | 1370 | - | Correction required in HSDPA step ts_RRC_RAB_EstPS_MO_P25 | F | 5.1.0 | 5.2.0 | R5s050317 |
| RP-29 | RP-050529 | 1371 | - | Upgrade HSENH ATS to full R5 | F | 5.1.0 | 5.2.0 | R5s050294 |
| RP-29 | RP-050529 | 1372 | - | Correction to GCF approved RRC test case 8.3.1.18 | F | 5.1.0 | 5.2.0 | R5s050293 |
| RP-29 | RP-050529 | 1373 | - | Correction asn.1 calculated values. | F | 5.1.0 | 5.2.0 | R5s050255 |
| RP-29 | RP-050529 | 1374 | - | Corrections to teststep ts_C5_CheckURA_PCH | F | 5.1.0 | 5.2.0 | R5s050280 |
| RP-29 | RP-050529 | 1375 | - | Correction to approved testcases 8.3.1.5 and 8.3.1.6 | F | 5.1.0 | 5.2.0 | R5s050287 |
| RP-29 | RP-050529 | 1376 | - | Correction to Inter-RAT Test cases | F | 5.1.0 | 5.2.0 | R5s050288 |
| RP-29 | RP-050529 | 1377 | - | Correction to the SMS Test Case 16.1.10 and 16.2.10 | F | 5.1.0 | 5.2.0 | R5s050291 |
| RP-29 | RP-050529 | 1378 | - | Summary of regression errors in the wk27 ATS. | F | 5.1.0 | 5.2.0 | R5s050292 |
| RP-29 | RP-050529 | 1379 | - | Correction to test step ts_CRLC_DL_CipherCfgRB | F | 5.1.0 | 5.2.0 | R5s050290 |
| RP-29 | RP-050529 | 1380 | - | Correction to GCF WI-12 approved NAS test case 9.4.5.4.6 | F | 5.1.0 | 5.2.0 | R5s050281 |
| RP-29 | RP-050529 | 1381 | - | Correction to GCF WI-10 approved IR_U test case 8.4.1.31 | F | 5.1.0 | 5.2.0 | R5s050289 |
| RP-29 | RP-050529 | 1382 | - | Corrections to Approved WI10 test case 9.4.5.2 | F | 5.1.0 | 5.2.0 | R5s050282 |
| RP-29 | RP-050529 | 1383 | - | Correction to GCF WI-10 test case 8.4.1.5 | F | 5.1.0 | 5.2.0 | R5s050234 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-29 | RP-050529 | 1384 | - | Correction to the RRC test case 8.4.1.14 | F | 5.1.0 | 5.2.0 | R5s050278 |
| RP-29 | RP-050529 | 1385 | - | Corrections to teststep ts_HO_SS_ReconfDCH_HS_ToFACH used for WI-14 Test Cases | F | 5.1.0 | 5.2.0 | R5s050279 |
| RP-29 | RP-050530 | 1386 | - | Correction to 8_1_x series approved testcases | F | 5.1.0 | 5.2.0 | R5s050271 |
| RP-29 | RP-050530 | 1387 | - | Correction to test step ts_RRC_ReceiverRB_SetupCmpl to handle IE "Start" for the ciphering path | F | 5.1.0 | 5.2.0 | R5s050272 |
| RP-29 | RP-050530 | 1388 | - | Correction to approved Inter-RAT IR_U testcase 8.3.7.13 | F | 5.1.0 | 5.2.0 | R5s050273 |
| RP-29 | RP-050530 | 1389 | - | Correction to approved testcase 8.2.4.1 | F | 5.1.0 | 5.2.0 | R5s050274 |
| RP-29 | RP-050530 | 1390 | - | Correction required for WI-010 P4 RRC Testcase 6.1.2.9. | F | 5.1.0 | 5.2.0 | R5s050275 |
| RP-29 | RP-050530 | 1391 | - | Correction to GCF WI-12 approved RRC test case 8.3.1.30, 8.4.1.6 and NAS test case 12.3.2.7 | F | 5.1.0 | 5.2.0 | R5s050270 |
| RP-29 | RP-050530 | 1392 | - | Correction to Approved RRC Package 4 TC 8.4.1.33 | F | 5.1.0 | 5.2.0 | R5s050269 |
| RP-29 | RP-050530 | 1393 | - | Guard timer setting needs to be longer in test case 9.4.2.4 Procedure 2. | F | 5.1.0 | 5.2.0 | R5s050252 |
| RP-29 | RP-050530 | 1394 | - | Corrections to WI-012 approved testcases 8.2.2.9 & 8.2.6.12 | F | 5.1.0 | 5.2.0 | R5s050246 |
| RP-29 | RP-050530 | 1395 | - | Corrections to WI-014 approved testcases 8.2.1.28, 8.2.4.36 & 8.2.1.30 | F | 5.1.0 | 5.2.0 | R5s050247 |
| RP-29 | RP-050530 | 1396 | - | Correction in Approved Test Case 12.2.2.1 of NAS_wk07.mp in iWD-TV2003-03_D05wk07.zip | F | 5.1.0 | 5.2.0 | R5s050245 |
| RP-29 | RP-050530 | 1397 | - | Correction to GCF WI-12 approved RRC test case 8.1.6.3 | F | 5.1.0 | 5.2.0 | R5s050233 |
| RP-29 | RP-050530 | 1398 | - | Multiple PICs definitions | F | 5.1.0 | 5.2.0 | R5s050241 |
| RP-29 | RP-050530 | 1399 | - | ASN.1 changes required for introduction of band V & band VI | F | 5.1.0 | 5.2.0 | R5s050215 |
| RP-29 | RP-050530 | 1400 | - | Summary of regression errors in the wk21 IR_U and IR_G ATS. | F | 5.1.0 | 5.2.0 | R5s050240 |
| RP-29 | RP-050530 | 1401 | - | Correction to GCF WI-10 and WI-12 IR_U and IR_G test cases | F | 5.1.0 | 5.2.0 | R5s050239 |
| RP-29 | RP-050530 | 1402 | - | Correction to IdleMode P1 TC 6.1.2.1 | F | 5.1.0 | 5.2.0 | R5s050238 |
| RP-29 | RP-050530 | 1403 | - | Summary of regression errors in the wk21 IR_U ATS. | F | 5.1.0 | 5.2.0 | R5s050230 |
| RP-29 | RP-050530 | 1404 | - | Correction to GCF WI-10 test case 8.3.1.1 | F | 5.1.0 | 5.2.0 | R5s050224 |
| RP-29 | RP-050530 | 1405 | - | Correction to approved WI-010 RRC Test case 6_1_2_1 | F | 5.1.0 | 5.2.0 | R5s050221 |
| RP-29 | RP-050531 | 1406 | - | Correction to approved WI-010 RRC Test case 6_1_2_9 | F | 5.1.0 | 5.2.0 | R5s050227 |
| RP-29 | RP-050531 | 1407 | - | Correction to GCF WI-10 test case 8.2.1.10, 8.3.4.1, 8.3.4.2, 12.4.2.5a Proc 2 | F | 5.1.0 | 5.2.0 | R5s050144 |
| RP-29 | RP-050531 | 1408 | - | Correction to WI 12 approved testcase 8.3.1.30 | F | 5.1.0 | 5.2.0 | R5s050222 |
| RP-29 | RP-050531 | 1409 | - | Correction to approved testcase 8.2.6.19 and 8.2.6.20 | F | 5.1.0 | 5.2.0 | R5s050223 |
| RP-29 | RP-050531 | 1410 | - | Correction to GCF high priority MAC test case 7.1.2.4a | F | 5.1.0 | 5.2.0 | R5s050214 |
| RP-29 | RP-050531 | 1411 | - | Correction to approved testcase 14.2.51b.1 | F | 5.1.0 | 5.2.0 | R5s050209 |
| RP-29 | RP-050531 | 1412 | - | Correction to approved testcase 8.3.7.12 | F | 5.1.0 | 5.2.0 | R5s050203 |
| RP-29 | RP-050531 | 1413 | - | Correction to GCF high priority NAS test case 12.4.1.4b | F | 5.1.0 | 5.2.0 | R5s050181 |
| RP-29 | RP-050531 | 1414 | - | Regression Error Report based on wk19ATS | F | 5.1.0 | 5.2.0 | R5s050202 |
| RP-29 | RP-050531 | 1415 | - | Summary of regression errors in the wk19 ATS. | F | 5.1.0 | 5.2.0 | R5s050196 |
| RP-29 | RP-050531 | 1416 | - | Correction to approved testcase 14.2.58 | F | 5.1.0 | 5.2.0 | R5s050194 |
| RP-29 | RP-050531 | 1417 | - | Correction to WI-12 test case 12.9.7a | F | 5.1.0 | 5.2.0 | R5s050195 |
| RP-29 | RP-050531 | 1418 | - | Summary of regression errors in the wk19 ATS. | F | 5.1.0 | 5.2.0 | R5s050186 |
| RP-29 | RP-050531 | 1419 | - | Correction to IE "radioPrioTOM8" in Attach Accept message. | F | 5.1.0 | 5.2.0 | R5s050193 |
| RP-29 | RP-050531 | 1420 | - | Correction to softhandover test cases in RRC ATS v5.0.0 | F | 5.1.0 | 5.2.0 | R5s050191 |
| RP-29 | RP-050531 | 1421 | - | Correction to RRC and RAB ATS v5.0.0 – regression errors | F | 5.1.0 | 5.2.0 | R5s050192 |
| RP-29 | RP-050531 | 1422 | - | Correction of syntax error in approved test cases | F | 5.1.0 | 5.2.0 | R5s050178 |
| RP-29 | RP-050531 | 1423 | - | Correction to the approved IR_U test cases 8.4.1.33, 8.4.1.34, 8.4.1.35, 8.4.1.36 and 8.4.1.40. | F | 5.1.0 | 5.2.0 | R5s050187 |
| RP-29 | RP-050531 | 1424 | - | Correction to RRC Package 2 TC 8.4.1.23 | F | 5.1.0 | 5.2.0 | R5s050188 |
| RP-29 | RP-050531 | 1425 | - | Correction to RRC P4 TC 8.4.1.41 | F | 5.1.0 | 5.2.0 | R5s050172 |
| RP-29 | RP-050532 | 1426 | - | Correction to approved testcase 14.2.38c and 14.2.40 | F | 5.1.0 | 5.2.0 | R5s050177 |
| RP-29 | RP-050532 | 1427 | - | Summary of regression errors in the wk31 ATS. | F | 5.1.0 | 5.2.0 | R5s050354 |
| RP-29 | RP-050532 | 1428 | - | Corrections to Approved Test case 8_2_1_29 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050327 |
| RP-29 | RP-050532 | 1429 | - | Corrections to Approved test case 8_2_1_30 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050329 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-29 | RP-050532 | 1430 | - | Corrections to Approved test case 8_2_1_31 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050331 |
| RP-29 | RP-050532 | 1431 | - | Corrections to Approved test case 8_2_1_32 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050333 |
| RP-29 | RP-050532 | 1432 | - | Corrections to Approved test case 8_2_6_42 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050335 |
| RP-29 | RP-050532 | 1433 | - | Corrections to Approved test case 8_2_3_30 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050343 |
| RP-29 | RP-050532 | 1434 | - | Corrections to Approved Testcase 8_2_1_28 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050297 |
| RP-29 | RP-050532 | 1435 | - | Corrections to Approved Testcase 8_2_2_38 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050299 |
| RP-29 | RP-050532 | 1436 | - | Corrections to Approved Testcase 8_2_3_30 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050301 |
| RP-29 | RP-050532 | 1437 | - | Corrections to Approved Testcase 8_2_4_36 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050303 |
| RP-29 | RP-050532 | 1438 | - | Corrections to Approved Testcase 8_3_1_32 based on wk31 ATS | F | 5.1.0 | 5.2.0 | R5s050305 |
| RP-29 | RP-050562 | 1439 | - | Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A. | F | 5.1.0 | 5.2.0 | - |
| RP-29 | RP-050526 | 1440 | - | Clarifying L2 Tests - Update TSOs and PIXITs – New configurations for WI-13/14 TCs | F | 5.1.0 | 5.2.0 | R5-051510 |
| RP-30 | RP-050713 | 1441 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 5.2.0 | 5.3.0 | - |
| RP-30 | RP-050766 | 1442 | - | Addition of GCF WI-015 AGPS test case 17.2.4.7 to AGPS ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050480 |
| RP-30 | RP-050766 | 1443 | - | Addition of GCF WI-015 AGPS test case 17.2.4.6 to AGPS ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050478 |
| RP-30 | RP-050766 | 1444 | - | Addition of GCF WI-015 AGPS test case 17.2.4.10 to AGPS ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050476 |
| RP-30 | RP-050766 | 1445 | - | Addition of GCF WI-015 AGPS test case 17.2.4.3 to RLC ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050419 |
| RP-30 | RP-050766 | 1446 | - | Addition of GCF WI-015 AGPS test case 17.2.4.1 to RLC ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050410 |
| RP-30 | RP-050768 | 1447 | - | Addition of GCF WI-14/2 test case 8.2.3.32 to HS_ENH ATS V5.2.0 (Revision of R5s050451) | B | 5.2.0 | 5.3.0 | R5s050495 |
| RP-30 | RP-050768 | 1448 | - | Addition of GCF WI-14/2 test case 8.2.3.34 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050449 |
| RP-30 | RP-050768 | 1449 | - | Addition of GCF WI-014 test case 8.2.2.41 to HS_ENH ATS V5.2.0 (Revision of R5s050455) | B | 5.2.0 | 5.3.0 | R5s050466 |
| RP-30 | RP-050768 | 1450 | - | Addition of GCF WI-014 RAB test case 14.6.3a to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050464 |
| RP-30 | RP-050768 | 1451 | - | Addition of GCF WI-014 RAB test case 14.6.3 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050462 |
| RP-30 | RP-050768 | 1452 | - | Addition of GCF WI-014 test case 8.3.4.9 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050457 |
| RP-30 | RP-050768 | 1453 | - | Addition of GCF WI-014 test case 8.2.3.31 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050444 |
| RP-30 | RP-050768 | 1454 | - | Addition of GCF WI-014 RAB test case 14.6.2 to HS_ENH ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050424 |
| RP-30 | RP-050768 | 1455 | - | Additional Changes to GCF WI-014 test case 8.3.1.37 | B | 5.2.0 | 5.3.0 | R5s050421 |
| RP-30 | RP-050768 | 1456 | - | Addition of GCF WI-014 test case 8.3.11.10 to RRC ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050412 |
| RP-30 | RP-050768 | 1457 | - | Addition of GCF WI-014 test case 8.2.3.35 to HS_ENH ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050407 |
| RP-30 | RP-050768 | 1458 | - | Addition of GCF WI-14/2 test case 8.2.6.46 to HS_ENH ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050405 |
| RP-30 | RP-050768 | 1459 | - | Addition of GCF WI-14/2 test case 8.2.6.41 to HS_ENH ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050403 |
| RP-30 | RP-050768 | 1460 | - | Addition of GCF WI-14/2 test case 8.3.1.36 to HS_ENH ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050385 |
| RP-30 | RP-050768 | 1461 | - | Addition of RRC GCF WI-14 test case 7.1.5.6 to RRC ATS v5.1.0 | B | 5.2.0 | 5.3.0 | R5s050379 |
| RP-30 | RP-050775 | 1462 | - | Addition of BMC GCF WI-10/3 test case 14.4.4 to RAB ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050401 |
| RP-30 | RP-050775 | 1463 | - | Revision of R5s050442 - Addition of GCF WI-10 Idle Mode Test Case 6.1.1.4 to RRC ATS 5.2.0 | B | 5.2.0 | 5.3.0 | R5s050453 |
| RP-30 | RP-050775 | 1464 | - | Addition of NAS GCF WI-12 test case 9.4.3.3 to NAS ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050416 |
| RP-30 | RP-050775 | 1465 | - | Addition of Cell Broadcast GCF WI-12 test case 16.3 to SMS ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050399 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-30 | RP-050775 | 1466 | - | Addition of NAS GCF WI-10 P4 test case 12.9.12 to NAS ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050395 |
| RP-30 | RP-050775 | 1467 | - | Addition of NAS GCF WI-12 test case 9.4.2.4 proc 4 to NAS ATS V5.1.0 | B | 5.2.0 | 5.3.0 | R5s050231 |
| RP-30 | RP-050778 | 1468 | - | Addition of GCF WI-013 RRC test case 8.1.2.15 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050473 |
| RP-30 | RP-050778 | 1469 | - | Addition of GCF WI-013 RRC test case 8.1.2.14 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050471 |
| RP-30 | RP-050778 | 1470 | - | Addition of GCF WI-013 test case 8.3.11.13 to HS_ENH_r5 ATS V5.2.0. | B | 5.2.0 | 5.3.0 | R5s050437 |
| RP-30 | RP-050778 | 1471 | - | Addition of GCF WI-13 RRC test case 8.1.6.5 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050497 |
| RP-30 | RP-050778 | 1472 | - | Addition of GCF WI-013 RRC test case 8.3.1.40 to HS_ENH ATS V5.2.0 | B | 5.2.0 | 5.3.0 | R5s050500 |
| RP-30 | RP-050768 | 1473 | - | Removal of use of deprecated alternative value in RRC Connection Release message (Cell DCH) in HS_ENH suite | F | 5.2.0 | 5.3.0 | R5s050487 |
| RP-30 | RP-050768 | 1474 | - | Removal of use of deprecated alternative value in RRC Connection Setup message (Cell FACH) in HS_ENH suite | F | 5.2.0 | 5.3.0 | R5s050489 |
| RP-30 | RP-050768 | 1475 | - | Correction to GCF WI-14/2 HSDPA RRC test case 8.3.1.37 | F | 5.2.0 | 5.3.0 | R5s050492 |
| RP-30 | RP-050768 | 1476 | - | Additional changes required for addition of GCF WI-014 test case 8.3.11.10 to RRC ATS V5.2.0. | F | 5.2.0 | 5.3.0 | R5s050460 |
| RP-30 | RP-050768 | 1477 | - | Correction to GCF WI-14/2 test case 8.3.1.36 | F | 5.2.0 | 5.3.0 | R5s050439 |
| RP-30 | RP-050768 | 1478 | - | Corrections to GCF WI-014/1 test cases 8.3.1.34 | F | 5.2.0 | 5.3.0 | R5s050427 |
| RP-30 | RP-050768 | 1479 | - | Correction to RRC HSDPA test case 8.2.2.40 | F | 5.2.0 | 5.3.0 | R5s050431 |
| RP-30 | RP-050773 | 1480 | - | Removal of use of deprecated alternative value in RRC Connection Release message (Cell DCH) in all GCF WI-10 and WI-12 test suites | F | 5.2.0 | 5.3.0 | R5s050488 |
| RP-30 | RP-050773 | 1481 | - | Correction to GCF WI-12 RRC test case 8.4.1.6 | F | 5.2.0 | 5.3.0 | R5s050486 |
| RP-30 | RP-050773 | 1482 | - | Corrections to RLC test cases to add check for the PIXIT px_CipheringOnOff | F | 5.2.0 | 5.3.0 | R5s050485 |
| RP-30 | RP-050773 | 1483 | - | Removal of use of deprecated alternative value in RRC Connection Setup message (Cell FACH) in all GCF WI-10 and WI-12 test suites | F | 5.2.0 | 5.3.0 | R5s050490 |
| RP-30 | RP-050773 | 1484 | - | Correction to the GCF WI-10 NAS test case 12.2.1.2 | F | 5.2.0 | 5.3.0 | R5s050491 |
| RP-30 | RP-050773 | 1485 | - | Correction to GCF WI-10 MAC test case 7.1.2.3.1 | F | 5.2.0 | 5.3.0 | R5s050494 |
| RP-30 | RP-050773 | 1486 | - | Correction to GCF WI-10 Idle Mode Test Case 6.1.2.1 | F | 5.2.0 | 5.3.0 | R5s050469 |
| RP-30 | RP-050773 | 1487 | - | Corrections required to GCF WI-10 approved test case 8.3.1.18 | F | 5.2.0 | 5.3.0 | R5s050448 |
| RP-30 | RP-050773 | 1488 | - | Corrections required to GCF WI-14 approved HSDPA test cases | F | 5.2.0 | 5.3.0 | R5s050435 |
| RP-30 | RP-050773 | 1489 | - | TTCN correction to RRC TC 8.2.4.1 | F | 5.2.0 | 5.3.0 | R5s050436 |
| RP-30 | RP-050773 | 1490 | - | Corrections required to GCF W-10 approved test case 8.4.1.40 | F | 5.2.0 | 5.3.0 | R5s050434 |
| RP-30 | RP-050773 | 1491 | - | Correction to the NAS Test Case 12.9.7a | F | 5.2.0 | 5.3.0 | R5s050429 |
| RP-30 | RP-050773 | 1492 | - | Correction to the IR_U Test Case 8.3.7.3 | F | 5.2.0 | 5.3.0 | R5s050430 |
| RP-30 | RP-050773 | 1493 | - | Correction to MultiRAB Test Cases | F | 5.2.0 | 5.3.0 | R5s050432 |
| RP-30 | RP-050773 | 1494 | - | Correction to GCF WI-10/2 RRC test case 8.3.1.21 | F | 5.2.0 | 5.3.0 | R5s050426 |
| RP-30 | RP-050773 | 1495 | - | Summary of regression errors in the wk38 ATS | F | 5.2.0 | 5.3.0 | R5s050428 |
| RP-30 | RP-050773 | 1496 | - | Summary of regression errors in wk38 of RRC ATS | F | 5.2.0 | 5.3.0 | R5s050414 |
| RP-30 | RP-050773 | 1497 | - | Correction in TTCN for test case 7.2.3.19 | F | 5.2.0 | 5.3.0 | R5s050415 |
| RP-30 | RP-050773 | 1498 | - | Regression Error report based on wk36 ATS | F | 5.2.0 | 5.3.0 | R5s050409 |
| RP-30 | RP-050773 | 1499 | - | Summary of regression results for wk36 version of IR_U ATS V5.1.0 | F | 5.2.0 | 5.3.0 | R5s050384 |
| RP-30 | RP-050774 | 1500 | - | Corrections required to GCF WI-10 approved test cases 6.2.1.7 and 6.2.1.8 | F | 5.2.0 | 5.3.0 | R5s050394 |
| RP-30 | RP-050774 | 1501 | - | Corrections required to GCF WI-10 approved test cases 8.3.7.5, 8.3.7.7 and 8.3.7.12 | F | 5.2.0 | 5.3.0 | R5s050397 |
| RP-30 | RP-050774 | 1502 | - | Correction to teststep ts_RRC_NAS_SessionActPS_MO_DCH_ToFACH. | F | 5.2.0 | 5.3.0 | R5s050390 |
| RP-30 | RP-050774 | 1503 | - | Correction to GCF WI-10/4 RRC test case 8.1.3.9 | F | 5.2.0 | 5.3.0 | R5s050378 |
| RP-30 | RP-050774 | 1504 | - | Summary of regression errors in the wk36 ATS | F | 5.2.0 | 5.3.0 | R5s050391 |
| RP-30 | RP-050774 | 1505 | - | Summary of regression errors in the wk36 IR_U ATS. | F | 5.2.0 | 5.3.0 | R5s050392 |
| RP-30 | RP-050774 | 1506 | - | Correction to HS_ENH_wk36 – Regression errors | F | 5.2.0 | 5.3.0 | R5s050389 |
| RP-30 | RP-050774 | 1507 | - | Correction to GCF WI-12 RRC test case 8.4.1.6 | F | 5.2.0 | 5.3.0 | R5s050376 |
| RP-30 | RP-050774 | 1508 | - | Correction to Inter-RAT IR_U test case 8.3.11.4 | F | 5.2.0 | 5.3.0 | R5s050377 |
| RP-30 | RP-050774 | 1509 | - | Correction to generic procedure C.1 (Idle mode check) | F | 5.2.0 | 5.3.0 | R5s050375 |
| RP-30 | RP-050774 | 1510 | - | Summary of regression errors in the wk31 ATS | F | 5.2.0 | 5.3.0 | R5s050367 |
| RP-30 | RP-050774 | 1511 | - | Correction to the test case 14.2.43.1 | F | 5.2.0 | 5.3.0 | R5s050368 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-30 | RP-050774 | 1512 | - | Correction to the NAS Test Case 12.9.13 | F | 5.2.0 | 5.3.0 | R5s050374 |
| RP-30 | RP-050774 | 1513 | - | Correction to all approved Test Cases using ciphering | F | 5.2.0 | 5.3.0 | R5s050373 |
| RP-30 | RP-050774 | 1514 | - | Corrections required for approved GCF WI-10 RRC test cases 8.3.1.21 and 8.3.2.11 | F | 5.2.0 | 5.3.0 | R5s050369 |
| RP-30 | RP-050774 | 1515 | - | Corrections required for approved GCF WI-10 NAS test cases 9.4.2.3 and 9.4.2.5 | F | 5.2.0 | 5.3.0 | R5s050370 |
| RP-30 | RP-050774 | 1516 | - | Summary of regression errors in the wk31 ATS Batch 2. | F | 5.2.0 | 5.3.0 | R5s050372 |
| RP-30 | RP-050774 | 1517 | - | Correction to GCF WI-010 test case 6.1.2.1 for manual attach UE | F | 5.2.0 | 5.3.0 | R5s050366 |
| RP-30 | RP-050774 | 1518 | - | Correction to agreed testcase 8.2.6.8 | F | 5.2.0 | 5.3.0 | R5s050357 |
| RP-30 | RP-050774 | 1519 | - | Correction to agreed IR_U_wk31 MRAT testcases 8.3.9.1 and 8.3.9.5 | F | 5.2.0 | 5.3.0 | R5s050358 |
| RP-30 | RP-050775 | 1520 | - | Correction to P1 NAS Test Case 11.3.1 for AT command confirmation | F | 5.2.0 | 5.3.0 | R5s050359 |
| RP-30 | RP-050775 | 1521 | - | Correction of the NAS Test Case 12.9.14 | F | 5.2.0 | 5.3.0 | R5s050362 |
| RP-30 | RP-050775 | 1522 | - | Correction to the test step ts_RRC_ReceiverRB_RelCmpl | F | 5.2.0 | 5.3.0 | R5s050363 |
| RP-30 | RP-050775 | 1523 | - | Corrections required for QOS constraint in R99 ATS | F | 5.2.0 | 5.3.0 | R5s050364 |
| RP-30 | RP-050775 | 1524 | - | Corrections required for QOS constraint in HSDPA/Rel-5 enhancement ATS | F | 5.2.0 | 5.3.0 | R5s050365 |
| RP-30 | RP-050775 | 1525 | - | Summary of regression errors in the wk42 ATS. | F | 5.2.0 | 5.3.0 | R5s050499 |
| RP-30 | RP-050775 | 1526 | - | Correction to Approved RRC TC 8.3.11.1 | F | 5.2.0 | 5.3.0 | R5s050459 |
| RP-30 | RP-050769 | 1527 | - | Update PIXIT and TSO, clarifications of a TSO and an AT / MMI commands in 34.123-3 | F | 5.2.0 | 5.3.0 | R5-052110 |
| RP-30 | RP-050775 | 1528 | - | Correction to iWD_wk38 IR_U ATS | F | 5.2.0 | 5.3.0 | R5s050470 |
| RP-31 | RP-060158 | 1529 | - | Addition of GCF WI-015 AGPS test case 17.2.2.1 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050561 |
| RP-31 | RP-060158 | 1530 | - | Addition of GCF WI-015 AGPS test case 17.2.2.2 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050563 |
| RP-31 | RP-060158 | 1531 | - | Addition of GCF WI-015 AGPS test case 17.2.2.3 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050565 |
| RP-31 | RP-060158 | 1532 | - | Addition of GCF WI-015 AGPS test case 17.2.2.4 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050587 |
| RP-31 | RP-060158 | 1533 | - | Addition of GCF WI-015 AGPS test case 17.2.3.2 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050567 |
| RP-31 | RP-060158 | 1534 | - | Addition of GCF WI-015 AGPS test case 17.2.3.3 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050589 |
| RP-31 | RP-060158 | 1535 | - | Addition of GCF WI-015 AGPS test case 17.2.3.4 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050591 |
| RP-31 | RP-060158 | 1536 | - | Addition of GCF WI-015 AGPS test case 17.2.3.8 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050593 |
| RP-31 | RP-060158 | 1537 | - | Addition of GCF WI-015 AGPS test case 17.2.3.9 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050569 |
| RP-31 | RP-060158 | 1538 | - | Addition of GCF WI-015 AGPS test case 17.2.4.2 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050595 |
| RP-31 | RP-060158 | 1539 | - | Addition of GCF WI-015 AGPS test case 17.2.4.4 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050572 |
| RP-31 | RP-060158 | 1540 | - | Addition of GCF WI-015 AGPS test case 17.2.4.5 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050574 |
| RP-31 | RP-060158 | 1541 | - | Addition of GCF WI-015 AGPS test case 17.2.4.8 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050576 |
| RP-31 | RP-060158 | 1542 | - | Addition of GCF WI-015 AGPS test case 17.2.4.9 to AGPS ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050578 |
| RP-31 | RP-060148 | 1543 | - | Addition of GCF WI-014 RAB test case 14.6.4 to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050604 |
| RP-31 | RP-060148 | 1544 | - | Addition of GCF WI-014 RAB test case 14.6.4a to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050606 |
| RP-31 | RP-060148 | 1545 | - | Addition of GCF WI-014 RAB test case 14.6.5 to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050608 |
| RP-31 | RP-060148 | 1546 | - | Addition of GCF WI-014 RAB test case 14.6.5a to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050610 |
| RP-31 | RP-060148 | 1547 | - | Addition of GCF WI-014/1 test case 7.1.5.2 to HS_ENH ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050534 |
| RP-31 | RP-060148 | 1548 | - | Addition of RRC GCF WI-14 test case 8.2.2.39 to RRC ATS v5.2.0 | B | 5.3.0 | 5.4.0 | R5s050510 |
| RP-31 | RP-060148 | 1549 | - | Addition of GCF WI-014 test case 8.2.2.42 to HS_ENH ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050536 |
| RP-31 | RP-060148 | 1550 | - | Addition of GCF WI-014/2 test case 8.2.3.33 to HS_ENH ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050540 |
| RP-31 | RP-060148 | 1551 | - | Addition of GCF WI-014 RRC test case 8.2.6.39a to HS_ENH ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050516 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-31 | RP-060148 | 1552 | - | Addition of GCF WI-014 RRC test case 8.2.6.39b to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050598 |
| RP-31 | RP-060148 | 1553 | - | Addition of GCF WI 14/2 test case 8.3.7.14 to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050618 |
| RP-31 | RP-060158 | 1554 | - | Addition of GCF WI-10/1 test case 6.1.2.2 to RRC ATS v5.2.0 | B | 5.3.0 | 5.4.0 | R5s050556 |
| RP-31 | RP-060158 | 1555 | - | Addition of RRC GCF WI-10 test case 6.1.2.3 to RRC ATS v5.3.0 | B | 5.3.0 | 5.4.0 | R5s050614 |
| RP-31 | RP-060158 | 1556 | - | Addition of GCF WI-10 Idle Mode test case 6.1.2.5 | B | 5.3.0 | 5.4.0 | R5s060017 |
| RP-31 | RP-060158 | 1557 | - | Addition of GCF WI-10 RRC test case 6.1.2.6 to RRC ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050584 |
| RP-31 | RP-060158 | 1558 | - | Addition of GCF WI-10/2 RRC test case 6.1.2.8 to RRC ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050547 |
| RP-31 | RP-060158 | 1559 | - | Addition of GCF WI-010/2 test case 6.2.2.3 to IR_U ATS V5.2.0 | B | 5.3.0 | 5.4.0 | R5s050483 |
| RP-31 | RP-060158 | 1560 | - | Addition of GCF WI-12 test case 8.4.1.48 | B | 5.3.0 | 5.4.0 | R5s050612 |
| RP-31 | RP-060165 | 1561 | - | Addition of GCF WI-13 test case 6.1.2.10 | B | 5.3.0 | 5.4.0 | R5s060013 |
| RP-31 | RP-060165 | 1562 | - | Addition of GCF WI-013 RRC test case 8.3.1.38 to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050600 |
| RP-31 | RP-060165 | 1563 | - | Addition of GCF WI-013 RRC test case 8.3.1.39 to HS_ENH ATS V5.3.0 | B | 5.3.0 | 5.4.0 | R5s050602 |
| RP-31 | RP-060149 | 1564 | - | Summary of regression errors in the wk03 HSD_ENH ATS | F | 5.3.0 | 5.4.0 | R5s060011 |
| RP-31 | RP-060149 | 1565 | - | Corrections to GCF WI-014 RAB testcases 14.6.4 and 14.6.4a | F | 5.3.0 | 5.4.0 | R5s060038 |
| RP-31 | RP-060149 | 1566 | - | Corrections to Approved GCF WI-014 RRC testcases 8.2.3.33 | F | 5.3.0 | 5.4.0 | R5s060035 |
| RP-31 | RP-060149 | 1567 | - | Summary of regression errors in wk03 HSDPA ATS. | F | 5.3.0 | 5.4.0 | R5s060030 |
| RP-31 | RP-060149 | 1568 | - | Wk49 regression errors in HS_ENH ATS | F | 5.3.0 | 5.4.0 | R5s050623 |
| RP-31 | RP-060149 | 1569 | - | Summary of regression errors in the wk49 HS_ENH ATS | F | 5.3.0 | 5.4.0 | R5s050621 |
| RP-31 | RP-060149 | 1570 | - | Summary of regression errors in the wk49 HS_ENH ATS | F | 5.3.0 | 5.4.0 | R5s050617 |
| RP-31 | RP-060149 | 1571 | - | Correction to GCF WI14 test case 8.3.4.9 | F | 5.3.0 | 5.4.0 | R5s050620 |
| RP-31 | RP-060149 | 1572 | - | Summary of regression errors in the wk49 HS_ENH ATS | F | 5.3.0 | 5.4.0 | R5s050581 |
| RP-31 | RP-060149 | 1573 | - | Correction to GCF WI14 test case 14.6.1 and 14.6.2 | F | 5.3.0 | 5.4.0 | R5s050560 |
| RP-31 | RP-060149 | 1574 | - | Summary of regression errors in the wk47 HS_ENH ATS | F | 5.3.0 | 5.4.0 | R5s050532 |
| RP-31 | RP-060149 | 1575 | - | Summary of regression errors in the wk47 HSDPA ATS | F | 5.3.0 | 5.4.0 | R5s050550 |
| RP-31 | RP-060149 | 1576 | - | Summary of regression errors in the HSENH_r5_wk42 ATS. | F | 5.3.0 | 5.4.0 | R5s050529 |
| RP-31 | RP-060149 | 1577 | - | Correction to GCF WI-014/2 test case 8.2.2.41 | F | 5.3.0 | 5.4.0 | R5s050525 |
| RP-31 | RP-060149 | 1578 | - | Summary of regression errors in the wk42 HS_ENH ATS | F | 5.3.0 | 5.4.0 | R5s050513 |
| RP-31 | RP-060149 | 1579 | - | Corrections to Testcase 8.3.1.35 | F | 5.3.0 | 5.4.0 | R5s050518 |
| RP-31 | RP-060149 | 1580 | - | Update to HS_ENH_r5 ATS to allow 64k uplink data rate to be tested for RRC Testcases. | F | 5.3.0 | 5.4.0 | R5s050519 |
| RP-31 | RP-060149 | 1581 | - | Errors identified in RAB HSDPA testcases in wk42 ATS. | F | 5.3.0 | 5.4.0 | R5s050520 |
| RP-31 | RP-060149 | 1582 | - | Summary of regression errors in the wk42 HSDPA ATS | F | 5.3.0 | 5.4.0 | R5s050503 |
| RP-31 | RP-060159 | 1583 | - | Correction to GCF WI-10 test case 8.4.1.14 | F | 5.3.0 | 5.4.0 | R5s050512 |
| RP-31 | RP-060159 | 1584 | - | TTCN correction to Approved RRC TCs 8.3.4.1, 8.3.4.2 and 8.3.4.3 | F | 5.3.0 | 5.4.0 | R5s060044 |
| RP-31 | RP-060159 | 1585 | - | Summary of regression errors in wk03 RRC and RAB ATS. | F | 5.3.0 | 5.4.0 | R5s060042 |
| RP-31 | RP-060159 | 1586 | - | Correction of GCF WI-10 RRC test case 8.4.1.2,8.4.1.24,8.4.1.25 | F | 5.3.0 | 5.4.0 | R5s060043 |
| RP-31 | RP-060159 | 1587 | - | Summary of regression errors in the wk03 GCF WI-10 and GCF WI-12 ATS | F | 5.3.0 | 5.4.0 | R5s060010 |
| RP-31 | RP-060159 | 1588 | - | Correction to GCF WI-10 RRC Test Case 6.1.1.4 | F | 5.3.0 | 5.4.0 | R5s060024 |
| RP-31 | RP-060159 | 1589 | - | Correction to GCF WI-12 Testcase 9.4.5.4.6 | F | 5.3.0 | 5.4.0 | R5s060025 |
| RP-31 | RP-060159 | 1590 | - | Correction to GCF WI-10 NAS Test Case 12.4.1.4a | F | 5.3.0 | 5.4.0 | R5s060040 |
| RP-31 | RP-060159 | 1591 | - | Correction of GCF WI-10 RRC test case 8.1.7.1d | F | 5.3.0 | 5.4.0 | R5s060039 |
| RP-31 | RP-060159 | 1592 | - | Corrections to approved GCF WI-12/1 Inter-RAT test case 8.4.1.48 | F | 5.3.0 | 5.4.0 | R5s060029 |
| RP-31 | RP-060159 | 1593 | - | Corrections to approved GCF WI-10/3 InterRAT test case 8.4.1.31 | F | 5.3.0 | 5.4.0 | R5s060028 |
| RP-31 | RP-060159 | 1594 | - | Corrections to GCF WI-012 GMM testcase 12.9.9 | F | 5.3.0 | 5.4.0 | R5s060037 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-31 | RP-060159 | 1595 | - | Corrections to Approved GCF WI-012 RRC testcases 8.2.1.24 & 8.2.1.34 | F | 5.3.0 | 5.4.0 | R5s060036 |
| RP-31 | RP-060159 | 1596 | - | Correction of GCF WI-10 RRC test case 8.4.1.26 | F | 5.3.0 | 5.4.0 | R5s060033 |
| RP-31 | RP-060159 | 1597 | - | Correction of GCF WI-12 MM test case 9.4.3.3 | F | 5.3.0 | 5.4.0 | R5s060032 |
| RP-31 | RP-060159 | 1598 | - | Summary of regression errors in wk49 ATS. | F | 5.3.0 | 5.4.0 | R5s060009 |
| RP-31 | RP-060159 | 1599 | - | Correction to GCF WI-12 RLC Test Case 7.2.3.35 | F | 5.3.0 | 5.4.0 | R5s060008 |
| RP-31 | RP-060159 | 1600 | - | Correction to GCF WI-10 test case 6.1.2.9 | F | 5.3.0 | 5.4.0 | R5s060007 |
| RP-31 | RP-060159 | 1601 | - | Correction to GCF WI-10 test case 8.1.3.9 | F | 5.3.0 | 5.4.0 | R5s060003 |
| RP-31 | RP-060159 | 1602 | - | Summary of regression errors in the wk49 IR_U ATS. | F | 5.3.0 | 5.4.0 | R5s060006 |
| RP-31 | RP-060160 | 1603 | - | Summary of regression errors in the wk47 ATS. | F | 5.3.0 | 5.4.0 | R5s050551 |
| RP-31 | RP-060160 | 1604 | - | TTCN correction to Approved GMM TC 12.4.2.4 | F | 5.3.0 | 5.4.0 | R5s060004 |
| RP-31 | RP-060160 | 1605 | - | Corrections to GCF WI-012 approved testcases 9.4.3.3 | F | 5.3.0 | 5.4.0 | R5s060002 |
| RP-31 | RP-060160 | 1606 | - | Correction to GCF WI-10 RRC Test Case 8.1.7.1c | F | 5.3.0 | 5.4.0 | R5s060001 |
| RP-31 | RP-060160 | 1607 | - | TTCN Correction for GCF WI-10 RRC test case 6.1.2.8 | F | 5.3.0 | 5.4.0 | R5s050586 |
| RP-31 | RP-060160 | 1608 | - | TTCN correction to Approved IRAT TCs 8.3.7.1, 8.3.7.2, 8.3.7.3, 8.3.7.4, 8.3.7.13, 8.3.7.16 and 8.3.11.1. | F | 5.3.0 | 5.4.0 | R5s050622 |
| RP-31 | RP-060160 | 1609 | - | Correction to approved RRC test cases 8.1.6.3, 8.4.1.1, 8.4.1.3 and 8.4.1.29 on Wk49 ATS | F | 5.3.0 | 5.4.0 | R5s050571 |
| RP-31 | RP-060160 | 1610 | - | Correction to GCF WI 10 RLC testcase 7.2.2.2 | F | 5.3.0 | 5.4.0 | R5s050583 |
| RP-31 | RP-060160 | 1611 | - | Summary of regression errors in the wk49 GCF WI-10 and GCF WI-12 ATS | F | 5.3.0 | 5.4.0 | R5s050580 |
| RP-31 | RP-060160 | 1612 | - | Corrections to approved GCF WI-010 / GCF WI-012 test cases 14.2.51b.1 and 14.2.58a | F | 5.3.0 | 5.4.0 | R5s050597 |
| RP-31 | RP-060160 | 1613 | - | TTCN correction to Approved IRAT TC 8.3.7.16 | F | 5.3.0 | 5.4.0 | R5s050552 |
| RP-31 | RP-060160 | 1614 | - | Correction to GCF WI-10 approved RRC Test Case 8.1.7.1d | F | 5.3.0 | 5.4.0 | R5s050582 |
| RP-31 | RP-060160 | 1615 | - | Correction to GCF Test Case 8.4.1.2, 8.4.1.24, 8.4.1.25, 8.4.1.6, 8.4.1.8 and HSDPA Test Cases | F | 5.3.0 | 5.4.0 | R5s050545 |
| RP-31 | RP-060160 | 1616 | - | Summary of regression errors in the wk47 GCF WI-10 and GCF WI-12 ATS | F | 5.3.0 | 5.4.0 | R5s050533 |
| RP-31 | RP-060160 | 1617 | - | Correction to the GCF WI 10 testcase 7.2.3.13 | F | 5.3.0 | 5.4.0 | R5s050538 |
| RP-31 | RP-060160 | 1618 | - | Correction to GCF WI 10 MAC test case 7.1.2.3.1 | F | 5.3.0 | 5.4.0 | R5s050539 |
| RP-31 | RP-060160 | 1619 | - | Correction to IR_U test cases 8.3.7.1, 8.3.7.2, 8.3.7.3, 8.3.7.12 and 8.3.7.16 | F | 5.3.0 | 5.4.0 | R5s050493 |
| RP-31 | RP-060160 | 1620 | - | Correction to GCF WI 10 test case 7.1.2.4a | F | 5.3.0 | 5.4.0 | R5s050555 |
| RP-31 | RP-060160 | 1621 | - | Corrections to GCF WI-012 approved test case 16.3 | F | 5.3.0 | 5.4.0 | R5s050554 |
| RP-31 | RP-060160 | 1622 | - | Correction to approved GCF WI-010 Test Case 16.1.1 | F | 5.3.0 | 5.4.0 | R5s050549 |
| RP-31 | RP-060161 | 1623 | - | TTCN correction to Approved RRC TC 8.1.2.7 | F | 5.3.0 | 5.4.0 | R5s050553 |
| RP-31 | RP-060161 | 1624 | - | Correction to GCF WI-10 RRC Test Case 8.3.1.18 | F | 5.3.0 | 5.4.0 | R5s050543 |
| RP-31 | RP-060161 | 1625 | - | Correction to GCF WI-10 RRC Test Case 8.1.1.9 | F | 5.3.0 | 5.4.0 | R5s050544 |
| RP-31 | RP-060161 | 1626 | - | Correction to GCF WI-12 test case 8.1.6.3 | F | 5.3.0 | 5.4.0 | R5s050531 |
| RP-31 | RP-060161 | 1627 | - | Summary of regression errors in the wk42 ATS. | F | 5.3.0 | 5.4.0 | R5s050528 |
| RP-31 | RP-060161 | 1628 | - | Correction to GCF WI-10/3 Testcase 12.4.2.4 | F | 5.3.0 | 5.4.0 | R5s050505 |
| RP-31 | RP-060161 | 1629 | - | Correction to test step ts_Exit_Testcase used in MultiRAB test cases | F | 5.3.0 | 5.4.0 | R5s050514 |
| RP-31 | RP-060161 | 1630 | - | Correction to GCF WI-010/1 test case 7.1.2.4a | F | 5.3.0 | 5.4.0 | R5s050524 |
| RP-31 | RP-060161 | 1631 | - | Correction to the GCF WI 12 NAS Test Case 9.4.3.3 | F | 5.3.0 | 5.4.0 | R5s050515 |
| RP-31 | RP-060161 | 1632 | - | Correction to GCF WI 10 and GCF WI 12 ATS to support IPv6 format for PDP Context | F | 5.3.0 | 5.4.0 | R5s050521 |
| RP-31 | RP-060161 | 1633 | - | Summary of regression errors in the wk42 GCF WI-10 and GCF WI-12 ATS | F | 5.3.0 | 5.4.0 | R5s050482 |
| RP-31 | RP-060161 | 1634 | - | Correction to GCF WI-13 test case 8.1.2.14 | F | 5.3.0 | 5.4.0 | R5s050526 |
| RP-31 | RP-060161 | 1635 | - | Correction to GCF WI-13 test case 8.1.2.15 | F | 5.3.0 | 5.4.0 | R5s050527 |
| RP-31 | RP-060161 | 1636 | - | Correction to GCF WI-12 test case 9.4.3.3 | F | 5.3.0 | 5.4.0 | R5s050509 |
| RP-31 | RP-060161 | 1637 | - | Correction to GCF WI-10 test case 8.1.3.9 | F | 5.3.0 | 5.4.0 | R5s050507 |
| RP-31 | RP-060161 | 1638 | - | Corrections of TC_16_2_1, TC_16_2_2, TC_16_1_9_1, TC_16_1_9_2 | F | 5.3.0 | 5.4.0 | R5s050506 |
| RP-31 | RP-060161 | 1639 | - | Correction to GCF WI-10 RAB Test Case 14.2.38c | F | 5.3.0 | 5.4.0 | R5s050504 |
| RP-31 | RP-060165 | 1640 | - | Correction to GCF WI 13/1 RRC testcases 8.3.1.38 and 8.3.1.39 | F | 5.3.0 | 5.4.0 | R5s060023 |
| RP-31 | RP-060165 | 1641 | - | Corrections to Approved GCF WI-013 RRC testcase 8_1_2_14 & WI-014 RRC testcase 8_2_2_42 | F | 5.3.0 | 5.4.0 | R5s060034 |
| RP-31 | RP-060165 | 1642 | - | Summary of regression errors in wk03 HSDPA ATS (GCF WI-13). | F | 5.3.0 | 5.4.0 | R5s060031 |
| RP-31 | RP-060165 | 1643 | - | Corrections to GCF WI-013 test cases 8.1.6.5 and 8.3.1.40 | F | 5.3.0 | 5.4.0 | R5s050523 |
| RP-31 | RP-060165 | 1644 | - | Correction to Rel-5 (HSENH) ATS to support IPv6 format for PDP Context. | F | 5.3.0 | 5.4.0 | R5s050522 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-31 | RP-060162 | 1645 | - | Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 5.3.0 | 5.4.0 | - |
| RP-31 | RP-060166 | 1646 | - | Introduce ASP for HSUPA in 34.123-3 | B | 5.3.0 | 5.4.0 | R5-060560 |
| RP-31 | RP-060147 | 1647 | - | Introduce ASP for HSDPA of LCR TDD | B | 5.3.0 | 5.4.0 | R5-060317 |
| RP-31 | RP-060147 | 1648 | - | Updating Information in section 8.2.4 (Table 35) | F | 5.3.0 | 5.4.0 | R5-060287 |
| RP-31 | RP-060154 | 1649 | - | Correction of default value for IXIT parameter 'px_CipherAlg'. | F | 5.3.0 | 5.4.0 | R5-060178 |
| RP-31 | RP-060154 | 1650 | - | New ASP for DTM and other corrections in 34.123-3 – Release 99 | F | 5.3.0 | 5.4.0 | R5-060505 |
| RP-31 | RP-060164 | 1651 | - | Update configurations, introduce frequency band indicator for SS in 34.123-3 - Release 5. | F | 5.3.0 | 5.4.0 | R5-060316 |
| RP-32 | RP-060338 | 1652 | - | Update HSDPA test configuration | F | 5.4.0 | 5.5.0 | R5-061004 |
| RP-32 | RP-060338 | 1653 | - | Change of ASP and IEs for LCR TDD | F | 5.4.0 | 5.5.0 | R5-061300 |
| RP-32 | RP-060333 | 1654 | - | Update E-DCH test model and ASP (CR to 34.123-3) | F | 5.4.0 | 5.5.0 | R5-061285 |
| RP-32 | RP-060324 | 1655 | - | Update PIXIT | F | 5.4.0 | 5.5.0 | R5-061003 |
| RP-32 | RP-060324 | 1656 | - | Correction to ASP CPHY_TFCI_Detected_IND | F | 5.4.0 | 5.5.0 | R5-061377 |
| RP-32 | RP-060321 | 1657 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 5.4.0 | 5.5.0 | - |
| RP-32 | RP-060339 | 1658 | - | Addition of GCF WI14 test case 8.2.6.48 to HSD_ENH ATS V5.4.0 | B | 5.4.0 | 5.5.0 | R5s060139 |
| RP-32 | RP-060327 | 1659 | - | Addition of GCF WI-12 test case 8.3.4.8 | B | 5.4.0 | 5.5.0 | R5s060019 |
| RP-32 | RP-060327 | 1660 | - | Addition of GCF WI12 RRC test case 8.2.2.43 to RRC ATS v5.3.0 | B | 5.4.0 | 5.5.0 | R5s060084 |
| RP-32 | RP-060327 | 1661 | - | Addition of GCF WI12 RRC test case 8.2.6.39 to RRC ATS v5.4.0 (Revision of R5s060076) | B | 5.4.0 | 5.5.0 | R5s060080 |
| RP-32 | RP-060327 | 1662 | - | Addition of GCF WI12 RRC test case 8.2.6.44 to RRC ATS v5.4.0 (Revision of R5s060078) | B | 5.4.0 | 5.5.0 | R5s060082 |
| RP-32 | RP-060327 | 1663 | - | Addition of GCF WI-10 MM test case 9.4.5.4.1 | B | 5.4.0 | 5.5.0 | R5s060066 |
| RP-32 | RP-060330 | 1664 | - | Addition of GCF WI-13 RRC test case 8.4.1.47 to HSD_ENH ATS v5.3.0 | B | 5.4.0 | 5.5.0 | R5s060070 |
| RP-32 | RP-060330 | 1665 | - | Addition of GCF WI13 Inter-RAT cell change order from UTRAN test case 8.3.11.12 to HSD_ENH ATS v5.4.0 (Revision of R5s060092) | B | 5.4.0 | 5.5.0 | R5s060094 |
| RP-32 | RP-060339 | 1666 | - | Correction to GCF WI14 RAB test case 14_6_1, 14_6_2, 14_6_3, 14_6_3a, 14_6_4, 14_6_4a, 14_6_5, 14_6_5a | F | 5.4.0 | 5.5.0 | R5s060059 |
| RP-32 | RP-060339 | 1667 | - | Correction to GCF WI14 test case 8_3_1_34 and 8_3_1_36 | F | 5.4.0 | 5.5.0 | R5s060061 |
| RP-32 | RP-060339 | 1668 | - | Change of the relative channel powers for HS-PDSCH and HS-SCCH | F | 5.4.0 | 5.5.0 | R5s060074 |
| RP-32 | RP-060339 | 1669 | - | Corrections to RAB testcase 14.6.3a | F | 5.4.0 | 5.5.0 | R5s060121 |
| RP-32 | RP-060339 | 1670 | - | Correction to teststep ts_RRC_MultiCallEstPS_MO_HSDPA, ts_RRC_NAS_SessionActPS_MO_P9_P10_HS | F | 5.4.0 | 5.5.0 | R5s060114 |
| RP-32 | RP-060339 | 1671 | - | Corrections to GCF WI 14 RRC test case 8.2.3.34 | F | 5.4.0 | 5.5.0 | R5s060115 |
| RP-32 | RP-060330 | 1672 | - | Revised summary of regression errors in IR_U and HSD_ENH_R5 ATS (wk03, 2006) | F | 5.4.0 | 5.5.0 | R5s060088 |
| RP-32 | RP-060330 | 1673 | - | Correction to GCF WI13 test case 6.1.2.10 | F | 5.4.0 | 5.5.0 | R5s060075 |
| RP-32 | RP-060330 | 1674 | - | Correction to GCF WI-13 Idle Mode test case 6.1.2.10 | F | 5.4.0 | 5.5.0 | R5s060089 |
| RP-32 | RP-060330 | 1675 | - | Corrections to Approved GCF WI-013 RRC testcases 8.4.1.47 | F | 5.4.0 | 5.5.0 | R5s060135 |
| RP-32 | RP-060330 | 1676 | - | Additional CR for agreed TC 8.3.11.12 (8.3.11.13 implicitly affected) | F | 5.4.0 | 5.5.0 | R5s060118 |
| RP-32 | RP-060325 | 1677 | - | Correction to GCF WI-10 RRC Test Case 6.2.2.2 | F | 5.4.0 | 5.5.0 | R5s060050 |
| RP-32 | RP-060325 | 1678 | - | Correction of GCF WI-10 test case 8.4.1.5 | F | 5.4.0 | 5.5.0 | R5s060049 |
| RP-32 | RP-060325 | 1679 | - | Summary of regression errors in the wk06 ATS. | F | 5.4.0 | 5.5.0 | R5s060056 |
| RP-32 | RP-060325 | 1680 | - | Corrections to Security procedure to make UL SRB3 ciphering preconfiguration optional | F | 5.4.0 | 5.5.0 | R5s060057 |
| RP-32 | RP-060325 | 1681 | - | Summary of regression errors in the wk06 GCF WI-10 and GCF WI-12 ATS | F | 5.4.0 | 5.5.0 | R5s060047 |
| RP-32 | RP-060325 | 1682 | - | Correction to the test step ts_DownlinkTBFEstablishment | F | 5.4.0 | 5.5.0 | R5s060060 |
| RP-32 | RP-060325 | 1683 | - | Change to expected value of Qos "DeliveryOrder" IE. | F | 5.4.0 | 5.5.0 | R5s060058 |
| RP-32 | RP-060325 | 1684 | - | Clarification of the usage of 4 PICS parameters | F | 5.4.0 | 5.5.0 | R5s060053 |
| RP-32 | RP-060325 | 1685 | - | Correction to approved GCF WI-10/2 InterRAT test case 6.2.2.2 | F | 5.4.0 | 5.5.0 | R5s060055 |
| RP-32 | RP-060325 | 1686 | - | Correction to approved GCF WI-10/2 InterRAT test case 6.2.2.1 | F | 5.4.0 | 5.5.0 | R5s060054 |
| RP-32 | RP-060325 | 1687 | - | Corrections to IRU Measurement test cases for handling of UL only and DL only compressed mode branches | F | 5.4.0 | 5.5.0 | R5s060051 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-32 | RP-060325 | 1688 | - | Generic correction to test step 'ts_MM_IMSI_Detach' | F | 5.4.0 | 5.5.0 | R5s060069 |
| RP-32 | RP-060325 | 1689 | - | Correction to GCF WI-12 RAB Test Case 14.2.9 | F | 5.4.0 | 5.5.0 | R5s060068 |
| RP-32 | RP-060325 | 1690 | - | Summary of regression errors in the wk09 GCF WI-10 and GCF WI-12 ATS | F | 5.4.0 | 5.5.0 | R5s060073 |
| RP-32 | RP-060325 | 1691 | - | Corrections to GCF WI-10 IR_U test case 6.2.1.7 and 6.2.1.8 | F | 5.4.0 | 5.5.0 | R5s060072 |
| RP-32 | RP-060325 | 1692 | - | Correction to RRC test cases 8.1.1.1 and 8.1.1.9 | F | 5.4.0 | 5.5.0 | R5s060086 |
| RP-32 | RP-060325 | 1693 | - | Correction to WI10 Idle Mode test case 6.1.2.6 | F | 5.4.0 | 5.5.0 | R5s060087 |
| RP-32 | RP-060325 | 1694 | - | Correction to the IR_U test case 6.2.2.3 | F | 5.4.0 | 5.5.0 | R5s060091 |
| RP-32 | RP-060325 | 1695 | - | Correction to SM GCF WI 10 test case 11.3.1 | F | 5.4.0 | 5.5.0 | R5s060090 |
| RP-32 | RP-060325 | 1696 | - | Correction to GCF WI-12 Testcase 9.4.3.3 | F | 5.4.0 | 5.5.0 | R5s060101 |
| RP-32 | RP-060326 | 1697 | - | Correction to GCF WI-12 Testcase 9.4.5.4.6 | F | 5.4.0 | 5.5.0 | R5s060102 |
| RP-32 | RP-060326 | 1698 | - | Correction to GCF WI-10 Testcase 8.1.7.1c | F | 5.4.0 | 5.5.0 | R5s060103 |
| RP-32 | RP-060326 | 1699 | - | Correction to GCF WI-15 Test Cases | F | 5.4.0 | 5.5.0 | R5s060104 |
| RP-32 | RP-060326 | 1700 | - | TTCN correction to Approved RRC TCs 8.3.4.1, 8.3.4.2 and 8.3.4.3 | F | 5.4.0 | 5.5.0 | R5s060096 |
| RP-32 | RP-060326 | 1701 | - | TTCN correction to Approved RRC TC 8.4.1.14 | F | 5.4.0 | 5.5.0 | R5s060095 |
| RP-32 | RP-060326 | 1702 | - | Correction of approved IR_U test case 8.3.11.1. | F | 5.4.0 | 5.5.0 | R5s060097 |
| RP-32 | RP-060326 | 1703 | - | Correction of approved HSD_ENH_R5 test cases 8.3.11.9, 8.3.11.13 and of 8.3.11.12 (under approval). | F | 5.4.0 | 5.5.0 | R5s060098 |
| RP-32 | RP-060326 | 1704 | - | Correction to GCF WI-10 GMM test case 12.4.2.4 | F | 5.4.0 | 5.5.0 | R5s060110 |
| RP-32 | RP-060326 | 1705 | - | Correction in TTCN for RLC Test cases 7.2.3.21, 7.2.3.22 and 7.2.3.24 | F | 5.4.0 | 5.5.0 | R5s060109 |
| RP-32 | RP-060326 | 1706 | - | Correction to RRC GCF WI 12 test case 8.3.1.30 | F | 5.4.0 | 5.5.0 | R5s060106 |
| RP-32 | RP-060326 | 1707 | - | Corrections to RAB testcase 14.2.41 | F | 5.4.0 | 5.5.0 | R5s060120 |
| RP-32 | RP-060326 | 1708 | - | Correction to GCF WI-10 RRC Test Case 8.1.1.9 | F | 5.4.0 | 5.5.0 | R5s060119 |
| RP-32 | RP-060326 | 1709 | - | Correction to the constraints used for the Radio Bearer Reconfiguration Message | F | 5.4.0 | 5.5.0 | R5s060113 |
| RP-32 | RP-060326 | 1710 | - | Correction to RRC test cases 8.3.1.21 and 8.3.2.11 | F | 5.4.0 | 5.5.0 | R5s060112 |
| RP-32 | RP-060326 | 1711 | - | Summary of regression errors in the wk11 ATS. | F | 5.4.0 | 5.5.0 | R5s060111 |
| RP-32 | RP-060326 | 1712 | - | Corrections to TTCN test cases due to the review of 34.123-2 and, related, the implementation of test case selection expressions in the TTCN. | F | 5.4.0 | 5.5.0 | R5s060116 |
| RP-32 | RP-060326 | 1713 | - | Empty all PCOs when TC begins | F | 5.4.0 | 5.5.0 | R5s060064 |
| RP-32 | RP-060326 | 1714 | - | Correction to QOS parameters for UMTS only mobiles | F | 5.4.0 | 5.5.0 | R5s060041 |
| RP-32 | RP-060326 | 1715 | - | Correction to GCF Test Case 8.4.1.25 | F | 5.4.0 | 5.5.0 | R5s060141 |
| RP-32 | RP-060326 | 1716 | - | Correction to GCF WI-10 Testcase 7.2.3.21 | F | 5.4.0 | 5.5.0 | R5s060126 |
| RP-32 | RP-060327 | 1717 | - | Correction to GCF WI-12 Testcase 9.4.3.3 | F | 5.4.0 | 5.5.0 | R5s060127 |
| RP-32 | RP-060327 | 1718 | - | Correction to GCF WI-10 IR-U Test Case 6.2.2.3 | F | 5.4.0 | 5.5.0 | R5s060128 |
| RP-32 | RP-060327 | 1719 | - | Correction to the RRC test case 6.1.2.8 | F | 5.4.0 | 5.5.0 | R5s060123 |
| RP-32 | RP-060327 | 1720 | - | Correction to GCF WI-12 NAS Test Case 9.4.3.3 | F | 5.4.0 | 5.5.0 | R5s060122 |
| RP-32 | RP-060327 | 1721 | - | Correction to GCF WI-10 SMS Test Case 16.x | F | 5.4.0 | 5.5.0 | R5s060136 |
| RP-32 | RP-060327 | 1722 | - | Correction to the IR_U test case 8.3.11.1 | F | 5.4.0 | 5.5.0 | R5s060130 |
| RP-32 | RP-060327 | 1723 | - | Correction to the approved IR_U test cases 8.3.7.1 and 8.3.7.3 | F | 5.4.0 | 5.5.0 | R5s060131 |
| RP-32 | RP-060327 | 1724 | - | Correction to the GCF WI-12 test case 8.4.1.48 | F | 5.4.0 | 5.5.0 | R5s060134 |
| RP-32 | RP-060327 | 1725 | - | Correction to the common security teststeps to add the default test step | F | 5.4.0 | 5.5.0 | R5s060133 |
| RP-32 | RP-060327 | 1726 | - | Correction to Cell Broadcast test case 16.3 | F | 5.4.0 | 5.5.0 | R5s060125 |
| RP-32 | RP-060327 | 1727 | - | Correction to the RRC test case 8.1.1.9 | F | 5.4.0 | 5.5.0 | R5s060124 |
| RP-32 | RP-060327 | 1728 | - | Correction to the RRC compressed mode testcases | F | 5.4.0 | 5.5.0 | R5s060132 |
| RP-32 | RP-060327 | 1729 | - | Correction of erroneous determination of OP-Mode in multiple ATSS | F | 5.4.0 | 5.5.0 | R5s060117 |
| RP-33 | RP-060548 | 1730 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 5.5.0 | 5.6.0 | - |
| RP-33 | RP-060555 | 1731 | - | Correction to the RRC testcase 8.4.1.23 | F | 5.5.0 | 5.6.0 | R5s060225 |
| RP-33 | RP-060555 | 1732 | - | Correction to the RRC testcase 8.4.1.25 | F | 5.5.0 | 5.6.0 | R5s060226 |
| RP-33 | RP-060555 | 1733 | - | Correction to the GMM test case 12.9.7b | F | 5.5.0 | 5.6.0 | R5s060223 |
| RP-33 | RP-060555 | 1734 | - | Correction of Inter RAT testcase 12.8 | F | 5.5.0 | 5.6.0 | R5s060222 |
| RP-33 | RP-060555 | 1735 | - | Summary of regression errors in wk29 GCF WI-10 ATS | F | 5.5.0 | 5.6.0 | R5s060227 |
| RP-33 | RP-060555 | 1736 | - | Correction to GCF WI-010/1 approved test case 7.2.3.27 | F | 5.5.0 | 5.6.0 | R5s060230 |
| RP-33 | RP-060555 | 1737 | - | Correction to GCF WI-12/1 approved test case 8.2.2.43 | F | 5.5.0 | 5.6.0 | R5s060231 |
| RP-33 | RP-060569 | 1738 | - | Correction to test cases 14.6.4 | F | 5.5.0 | 5.6.0 | R5s060229 |
| RP-33 | RP-060555 | 1739 | - | Correction to test cases 8.2.2.35 & tcv_BcapMmedia | F | 5.5.0 | 5.6.0 | R5s060232 |
| RP-33 | RP-060555 | 1740 | - | Correction to GCF WI10 RRC Test Case 8.4.1.5 | F | 5.5.0 | 5.6.0 | R5s060218 |
| RP-33 | RP-060555 | 1741 | - | Correction to approved GCF WI-12 RAB test case 14.2.58a | F | 5.5.0 | 5.6.0 | R5s060221 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-33 | RP-060555 | 1742 | - | Correction to approved GCF WI-12 RRC test cases 8.2.6.39 and 8.2.6.44 | F | 5.5.0 | 5.6.0 | R5s060220 |
| RP-33 | RP-060555 | 1743 | - | Correction to approved GCF WI-10 RLC test case 7.2.3.17 | F | 5.5.0 | 5.6.0 | R5s060219 |
| RP-33 | RP-060555 | 1744 | - | Summary of Regression Errors in NAS wk29 ATS | F | 5.5.0 | 5.6.0 | R5s060217 |
| RP-33 | RP-060569 | 1745 | - | Correction GCF WI-14 HSDPA Test Case 8.2.1.27 | F | 5.5.0 | 5.6.0 | R5s060214 |
| RP-33 | RP-060569 | 1746 | - | Correction to test cases 14.6.6 | F | 5.5.0 | 5.6.0 | R5s060215 |
| RP-33 | RP-060555 | 1747 | - | Summary of Regression Errors in WK29 ATS | F | 5.5.0 | 5.6.0 | R5s060212 |
| RP-33 | RP-060555 | 1748 | - | ASP enhancement for HSUPA testing | F | 5.5.0 | 5.6.0 | R5s060196 |
| RP-33 | RP-060569 | 1749 | - | Summary of regression errors in the wk27 HSD Suite | F | 5.5.0 | 5.6.0 | R5s060209 |
| RP-33 | RP-060555 | 1750 | - | Summary of regression errors in the wk27 RLC ATS | F | 5.5.0 | 5.6.0 | R5s060210 |
| RP-33 | RP-060555 | 1751 | - | Corrections to GCF WI-12/1 approved test case 7.1.3.2 | F | 5.5.0 | 5.6.0 | R5s060208 |
| RP-33 | RP-060554 | 1752 | - | Addition of GCF WI10 RRC test case 8.4.1.8 to RRC ATS v5.5.0 | B | 5.5.0 | 5.6.0 | R5s060201 |
| RP-33 | RP-060555 | 1753 | - | Corrections to GCF WI-12/1 approved test case 12.9.7a. | F | 5.5.0 | 5.6.0 | R5s060206 |
| RP-33 | RP-060569 | 1754 | - | Summary of Regression Errors in HSDPA ATS | F | 5.5.0 | 5.6.0 | R5s060207 |
| RP-33 | RP-060555 | 1755 | - | Summary of regression errors in the wk27 GCF WI-10 and GCF WI-12 ATS | F | 5.5.0 | 5.6.0 | R5s060205 |
| RP-33 | RP-060555 | 1756 | - | Correction to GCF WI-10 Idle Mode test case 6.1.2.5 | F | 5.5.0 | 5.6.0 | R5s060203 |
| RP-33 | RP-060556 | 1757 | - | Correction to GCF WI-10 RRC test case 8.3.4.3 | F | 5.5.0 | 5.6.0 | R5s060204 |
| RP-33 | RP-060556 | 1758 | - | Regression Error report for RRC & MAC ATS | F | 5.5.0 | 5.6.0 | R5s060199 |
| RP-33 | RP-060559 | 1759 | - | Regression Error report for HSD_ENH_r5 ATS | F | 5.5.0 | 5.6.0 | R5s060200 |
| RP-33 | RP-060559 | 1760 | - | Correction of CC procedure for multimedia calls | F | 5.5.0 | 5.6.0 | R5s060063 |
| RP-33 | RP-060556 | 1761 | - | Corrections to GCF WI-10 RRC Test Case 8.4.1.24 and 8.4.1.25 | F | 5.5.0 | 5.6.0 | R5s060198 |
| RP-33 | RP-060554 | 1762 | - | Addition of GCF WI-015 AGPS test case 17.2.3.7 to AGPS ATS V5.5.0 | B | 5.5.0 | 5.6.0 | R5s060193 |
| RP-33 | RP-060554 | 1763 | - | Addition of GCF WI-015 AGPS test case 17.2.3.6 to AGPS ATS V5.5.0 | B | 5.5.0 | 5.6.0 | R5s060192 |
| RP-33 | RP-060556 | 1764 | - | Correction to GCF WI-12 NAS Test Case 12.9.9 | F | 5.5.0 | 5.6.0 | R5s060197 |
| RP-33 | RP-060556 | 1765 | - | Correction to the RRC testcase 8.2.3.8 | F | 5.5.0 | 5.6.0 | R5s060190 |
| RP-33 | RP-060556 | 1766 | - | Correction to the RRC testcase 8.2.4.1 | F | 5.5.0 | 5.6.0 | R5s060191 |
| RP-33 | RP-060556 | 1767 | - | Correction of GCF WI-10 RRC Test Case 8.3.1.10 and 8.3.2.4 | F | 5.5.0 | 5.6.0 | R5s060186 |
| RP-33 | RP-060556 | 1768 | - | Correction to the Security procedure | F | 5.5.0 | 5.6.0 | R5s060189 |
| RP-33 | RP-060556 | 1769 | - | Correction to GCF WI-10 NAS Test Case 11.1.1.1 | F | 5.5.0 | 5.6.0 | R5s060178 |
| RP-33 | RP-060556 | 1770 | - | Correction to GCF WI-12 RRC Test Case 8.1.1.10 | F | 5.5.0 | 5.6.0 | R5s060187 |
| RP-33 | RP-060556 | 1771 | - | Correction to the test step ts_ToStateMOCompressMode_CS_6_9_PS_6_10 | F | 5.5.0 | 5.6.0 | R5s060188 |
| RP-33 | RP-060561 | 1772 | - | Moving baseline to the June 06, Rel-6 | F | 5.5.0 | 5.6.0 | R5s060183 |
| RP-33 | RP-060556 | 1773 | - | Corrections to GCF WI-10 SMS Test Cases 16.1.1 and 16.1.2 | F | 5.5.0 | 5.6.0 | R5s060185 |
| RP-33 | RP-060559 | 1774 | - | Corrections to GCF WI-13 Test Case 8.3.11.13 | F | 5.5.0 | 5.6.0 | R5s060184 |
| RP-33 | RP-060556 | 1775 | - | Correction GCF WI-12 Inter-RAT Test Case 8.4.1.48 | F | 5.5.0 | 5.6.0 | R5s060182 |
| RP-33 | RP-060569 | 1776 | - | Corrections to GCF WI 14 test case 14.6.4 | F | 5.5.0 | 5.6.0 | R5s060181 |
| RP-33 | RP-060556 | 1777 | - | Correction of GCF WI-10 Idle Mode Testcase 6.1.2.6 | F | 5.5.0 | 5.6.0 | R5s060180 |
| RP-33 | RP-060556 | 1778 | - | Correction of value for t_IdlePageTimer timer | F | 5.5.0 | 5.6.0 | R5s060175 |
| RP-33 | RP-060556 | 1779 | - | Correction to GCF WI-12 NAS Test Case 12.9.9 | F | 5.5.0 | 5.6.0 | R5s060176 |
| RP-33 | RP-060556 | 1780 | - | Correction to Approved GCF WI-10 NAS test case 12.9.6 | F | 5.5.0 | 5.6.0 | R5s060179 |
| RP-33 | RP-060556 | 1781 | - | Summary of regression errors in wk23 GCF WI-10 and GCF WI-12 ATS | F | 5.5.0 | 5.6.0 | R5s060177 |
| RP-33 | RP-060556 | 1782 | - | Correction to the test step ts_U2GCellChange_RAUpdate | F | 5.5.0 | 5.6.0 | R5s060174 |
| RP-33 | RP-060556 | 1783 | - | Corrections to GCF WI 12/1 IR_U test case 8_4_1_48 | F | 5.5.0 | 5.6.0 | R5s060173 |
| RP-33 | RP-060569 | 1784 | - | Correction to test case 8.2.6.48 | F | 5.5.0 | 5.6.0 | R5s060170 |
| RP-33 | RP-060559 | 1785 | - | Correction to test case 8.1.6.5 | F | 5.5.0 | 5.6.0 | R5s060171 |
| RP-33 | RP-060557 | 1786 | - | Correction to test step ts_SS_Rel | F | 5.5.0 | 5.6.0 | R5s060172 |
| RP-33 | RP-060557 | 1787 | - | Correction to the GCF WI-12 RRC testcase 8.1.6.3 | F | 5.5.0 | 5.6.0 | R5s060169 |
| RP-33 | RP-060557 | 1788 | - | Correction to the GCF WI-10 NAS test case 12.4.2.4 | F | 5.5.0 | 5.6.0 | R5s060166 |
| RP-33 | RP-060557 | 1789 | - | Correction to the GCF WI-10 RRC test case 8.4.1.2 | F | 5.5.0 | 5.6.0 | R5s060167 |
| RP-33 | RP-060557 | 1790 | - | Summary of regression errors in the wk21 GCF WI-10 and WI-12 ATS | F | 5.5.0 | 5.6.0 | R5s060168 |
| RP-33 | RP-060569 | 1791 | - | Summary of regression errors in the wk21 HSD_ENH ATS | F | 5.5.0 | 5.6.0 | R5s060165 |
| RP-33 | RP-060569 | 1792 | - | Correction to GCF WI14 test case 8.2.6.39a and 8.2.6.39b | F | 5.5.0 | 5.6.0 | R5s060164 |
| RP-33 | RP-060557 | 1793 | - | Correction of GCF WI-12 and 10 NAS Test cases 9.4.5.4.6 and 9.4.5.4.1 | F | 5.5.0 | 5.6.0 | R5s060163 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-33 | RP-060554 | 1794 | - | Addition of GCF WI-012 MAC test case 7.1.3.2 to MAC ATS V5.4.0 | B | 5.5.0 | 5.6.0 | R5s060161 |
| RP-33 | RP-060557 | 1795 | - | Correction of GCF WI-10 IR_U Testcase 8.3.11.4 | F | 5.5.0 | 5.6.0 | R5s060158 |
| RP-33 | RP-060569 | 1796 | - | Addition of GCF WI14/3 test case 14.6.6 to HSD_ENH ATS V5.4.0 | B | 5.5.0 | 5.6.0 | R5s060159 |
| RP-33 | RP-060569 | 1797 | - | Correction of GCF WI-14 HSDPA Testcase 8.3.11.10 | F | 5.5.0 | 5.6.0 | R5s060156 |
| RP-33 | RP-060557 | 1798 | - | Correction of GCF WI-12 RRC Testcase 8.3.1.30 | F | 5.5.0 | 5.6.0 | R5s060157 |
| RP-33 | RP-060569 | 1799 | - | Addition of GCF WI14/3 test case 14.6.1a to HSD_ENH ATS V5.4.0 | B | 5.5.0 | 5.6.0 | R5s060154 |
| RP-33 | RP-060557 | 1800 | - | Summary of regression errors in the wk18 GCF WI-10 and GCF WI-12 ATS | F | 5.5.0 | 5.6.0 | R5s060148 |
| RP-33 | RP-060557 | 1801 | - | Correction to common teststeps ts_RRC_ReceiveUE_CapabilityInfo and ts_Check_UE_Capability | F | 5.5.0 | 5.6.0 | R5s060146 |
| RP-33 | RP-060557 | 1802 | - | Correction to the constraint cbr_108_RRC_SecModeCmpl in approved teststep ts_RRC_Security | F | 5.5.0 | 5.6.0 | R5s060147 |
| RP-33 | RP-060569 | 1803 | - | Correction to test step ts_RRC_ConnRel_AfterSwitchOff_r5 | F | 5.5.0 | 5.6.0 | R5s060153 |
| RP-33 | RP-060569 | 1804 | - | Correction of GCF WI-14 HSDPA MAC test case 7.1.5.4 | F | 5.5.0 | 5.6.0 | R5s060149 |
| RP-33 | RP-060557 | 1805 | - | Proposed enhancement for calculation of DPCH Frame Offset | F | 5.5.0 | 5.6.0 | R5s060150 |
| RP-33 | RP-060557 | 1806 | - | Correction of PLMN presentation in test step ts_MMI_PLMN_SelPerf | F | 5.5.0 | 5.6.0 | R5s060152 |
| RP-33 | RP-060557 | 1807 | - | Correction to InterRAT Idle Mode frequency lists | F | 5.5.0 | 5.6.0 | R5s060151 |
| RP-33 | RP-060557 | 1808 | - | Correction to GCF WI-10 Idle Mode test case 6.1.2.3 | F | 5.5.0 | 5.6.0 | R5s060144 |
| RP-33 | RP-060557 | 1809 | - | Correction of integrity error in TC 8.1.7.1d | F | 5.5.0 | 5.6.0 | R5s060145 |
| RP-33 | RP-060569 | 1810 | - | TTCN correction to MAC-hs testcase 7.1.5.6 | F | 5.5.0 | 5.6.0 | R5s060143 |
| RP-33 | RP-060558 | 1811 | - | Summary of regression errors in wk29 IRAT ATSS. | F | 5.5.0 | 5.6.0 | R5s060236 |
| RP-33 | RP-060558 | 1812 | - | Correction to Approved GCF WI-10 NAS test case 12.4.1.1a | F | 5.5.0 | 5.6.0 | R5s060243 |
| RP-33 | RP-060558 | 1813 | - | Summary of Regression Errors in RRC wk34 ATS | F | 5.5.0 | 5.6.0 | R5s060248 |
| RP-33 | RP-060558 | 1814 | - | Summary of Regression Errors in NAS wk34 ATS | F | 5.5.0 | 5.6.0 | R5s060249 |
| RP-33 | RP-060558 | 1815 | - | Summary of Regression Errors in SMS wk34 ATS | F | 5.5.0 | 5.6.0 | R5s060250 |
| RP-33 | RP-060559 | 1816 | - | Summary of Regression Errors in HSD_ENH wk34 ATS | F | 5.5.0 | 5.6.0 | R5s060256 |
| RP-33 | RP-060558 | 1817 | - | Correction to GCF WI-12 IR_U Test Case 8.4.1.48 | F | 5.5.0 | 5.6.0 | R5s060253 |
| RP-33 | RP-060558 | 1818 | - | Summary of regression errors in wk34 GCF WI-10 and GCF WI-12 ATS | F | 5.5.0 | 5.6.0 | R5s060255 |
| RP-33 | RP-060558 | 1819 | - | Correction to UE capability constraints | F | 5.5.0 | 5.6.0 | R5s060254 |
| RP-33 | RP-060558 | 1820 | - | Addition of GCF WI-017 test case 8.3.7.17 to IR_U_r3 ATS V5.5.0. | B | 5.5.0 | 5.6.0 | R5s060234 |
| RP-33 | RP-060564 | 1821 | - | CR to 34.123-3: ASP changes for EDCH test | F | 5.5.0 | 5.6.0 | R5-062325 |
| RP-33 | RP-060551 | 1822 | - | New ASP and updated ASP to resolve SRB3 UL ciphering | F | 5.5.0 | 5.6.0 | R5-062534 |
| RP-33 | RP-060553 | 1823 | - | Production of pointer version 5.6.0 of TS 34.123-3 with no technical contents | F | 5.5.0 | 5.6.0 | R5-062535 |
| RP-33 | RP-060560 | 1824 | - | Upgrade TS 34.123-3 to version 6.0.0 | F | 5.5.0 | 6.0.0 | R5-062536 |
| RP-33 | RP-060551 | 1825 | - | CR to 34.123-3: Update TSO and PIXIT | F | 5.5.0 | 5.6.0 | R5-062395 |
| RP-33 | RP-060551 | 1826 | - | CR to 34.123-3: SFN offset issue in the CFN timing-maintained test | F | 5.5.0 | 5.6.0 | R5-062046 |
| RP-33 | RP-060560 | 1827 | - | CR to 34.123-3: GERAN additional bands for interRAT test | F | 5.5.0 | 5.6.0 | R5-062537 |
| RP-34 | RP-060744 | 1828 | - | CR to 34.123-3, Corrections of ASP and EDCH configurations | F | 6.0.0 | 6.1.0 | R5-063063 |
| RP-34 | RP-060734 | 1829 | - | CR to 34.123-3: New PIXIT for band VI test | F | 6.0.0 | 6.1.0 | R5-063375 |
| RP-34 | RP-060734 | 1830 | - | CR to 34.123-3: New annex guidance to TC executions | F | 6.0.0 | 6.1.0 | R5-063546 |
| RP-34 | RP-060741 | 1831 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 6.0.0 | 6.1.0 | - |
| RP-34 | RP-060745 | 1832 | - | Addition of E-DCH MAC test case 7.1.6.2.3 to HSU_ENH ATS v5.5.0 | B | 6.0.0 | 6.1.0 | R5s060311 |
| RP-34 | RP-060745 | 1833 | - | Addition of EDCH test case 8.2.6.50 to HSU ATS v5.5.0 | B | 6.0.0 | 6.1.0 | R5s060304 |
| RP-34 | RP-060745 | 1834 | - | Addition of E-DCH RRC test case 8.3.1.41 to HSU_ENH ATS v5.5.0 | B | 6.0.0 | 6.1.0 | R5s060286 |
| RP-34 | RP-060745 | 1835 | - | Addition of E-DCH InterRAT test case 8.3.11.14 to HSU_ENH_r6 ATS. | B | 6.0.0 | 6.1.0 | R5s060272 |
| RP-34 | RP-060745 | 1836 | - | Addition of GCF WI-25 E-DCH test case 14.7.1 to HSU_ENH_r6 ATS. | B | 6.0.0 | 6.1.0 | R5s060259 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-34 | RP-060745 | 1837 | - | Addition of GCF WI-25 E-DCH test case 8.2.1.35 to HSU_ENH_r6 ATS. | B | 6.0.0 | 6.1.0 | R5s060270 |
| RP-34 | RP-060736 | 1838 | - | Addition of GCF WI10 RRC test case 8.2.6.38 to RRC ATS v6.0.0 | B | 6.0.0 | 6.1.0 | R5s060295 |
| RP-34 | RP-060736 | 1839 | - | Addition of GCF WI10 RRC test case 8.4.1.28 to RRC ATS v6.0.0 | B | 6.0.0 | 6.1.0 | R5s060265 |
| RP-34 | RP-060736 | 1840 | - | Addition of GCF WI10 RRC test case 6.1.2.4 to RRC ATS v6.0.0 | B | 6.0.0 | 6.1.0 | R5s060257 |
| RP-34 | RP-060738 | 1841 | - | Addition of HSDPA RAB test case 14.6.7 to HSD_ENH ATS v5.5.0 | B | 6.0.0 | 6.1.0 | R5s060313 |
| RP-34 | RP-060740 | 1842 | - | Addition of DSAC test case 8.1.2.16 to HSU_ENH_r6 ATS. | B | 6.0.0 | 6.1.0 | R5s060288 |
| RP-34 | RP-060740 | 1843 | - | Addition of DSAC test case 12.4.2.12 to HSU_ENH_r6 ATS | B | 6.0.0 | 6.1.0 | R5s060283 |
| RP-34 | RP-060740 | 1844 | - | Addition of DSAC test case 12.4.2.11 to HSU_ENH_r6 ATS. | B | 6.0.0 | 6.1.0 | R5s060281 |
| RP-34 | RP-060740 | 1845 | - | Addition of GCF WI-24 DSAC test case 12.9.15 to HSU ATS v6.0.0 | B | 6.0.0 | 6.1.0 | R5s060263 |
| RP-34 | RP-060740 | 1846 | - | Addition of DSAC test case 9.4.3.6 to HSU_ENH_ATS V5.5.0 | B | 6.0.0 | 6.1.0 | R5s060251 |
| RP-34 | RP-060740 | 1847 | - | Addition of DSAC test case 12.2.1.12 to HSU_ENH_ATS V6.0.0 | B | 6.0.0 | 6.1.0 | R5s060246 |
| RP-34 | RP-060740 | 1848 | - | Addition of DSAC test case 9.5.9 to HSU_ENH_ATS V6.0.0 | B | 6.0.0 | 6.1.0 | R5s060244 |
| RP-34 | RP-060736 | 1849 | - | Correction to GCF WI-10 IR-U Test Case 8.3.7.1 | F | 6.0.0 | 6.1.0 | R5s060338 |
| RP-34 | RP-060736 | 1850 | - | Summary of regression errors in wk38 GCF WI-10 and WI-12 ATS | F | 6.0.0 | 6.1.0 | R5s060337 |
| RP-34 | RP-060736 | 1851 | - | Correction to SMS testcase 16.2.1 | F | 6.0.0 | 6.1.0 | R5s060320 |
| RP-34 | RP-060736 | 1852 | - | Correction to the NAS Test Case 12.9.12 and 12.9.13 | F | 6.0.0 | 6.1.0 | R5s060334 |
| RP-34 | RP-060736 | 1853 | - | Corrections to GCF WI-10 Test Cases 8.1.10.1 and 7.1.1.8 | F | 6.0.0 | 6.1.0 | R5s060332 |
| RP-34 | RP-060736 | 1854 | - | Introduction of Band 6 to test cases | F | 6.0.0 | 6.1.0 | R5s060324 |
| RP-34 | RP-060736 | 1855 | - | Summary of Regression Errors in RLC wk38 ATS | F | 6.0.0 | 6.1.0 | R5s060331 |
| RP-34 | RP-060736 | 1856 | - | Corrections to GCF WI-12 RRC Test Cases 8.2.6.39 & 8.2.6.44 | F | 6.0.0 | 6.1.0 | R5s060330 |
| RP-34 | RP-060736 | 1857 | - | Correction to GCF WI-10 RRC Test Case 6.1.1.7 | F | 6.0.0 | 6.1.0 | R5s060325 |
| RP-34 | RP-060736 | 1858 | - | Correction to approved GCF WI-12/1 RAB test case 14.2.58a | F | 6.0.0 | 6.1.0 | R5s060321 |
| RP-34 | RP-060736 | 1859 | - | Summary of regression errors in the wk38 InterRAT ATSS. | F | 6.0.0 | 6.1.0 | R5s060315 |
| RP-34 | RP-060736 | 1860 | - | Summary of regression errors in wk38 GCF WI-10 and GCF WI-12 ATS | F | 6.0.0 | 6.1.0 | R5s060309 |
| RP-34 | RP-060736 | 1861 | - | Correction to the RRC test case 8.4.1.8 | F | 6.0.0 | 6.1.0 | R5s060307 |
| RP-34 | RP-060736 | 1862 | - | Corrections to GCF WI-10 RAB testcases 14.4.2.3 and 14.4.2a.3 | F | 6.0.0 | 6.1.0 | R5s060308 |
| RP-34 | RP-060736 | 1863 | - | Correction to IR_U testcase 8.4.1.48 | F | 6.0.0 | 6.1.0 | R5s060302 |
| RP-34 | RP-060736 | 1864 | - | Correction of GCF WI-10 RRC testcase 8.1.10.1 | F | 6.0.0 | 6.1.0 | R5s060303 |
| RP-34 | RP-060736 | 1865 | - | Correction to GCF WI-12 RRC Test Case 8.3.1.30 | F | 6.0.0 | 6.1.0 | R5s060306 |
| RP-34 | RP-060737 | 1866 | - | Correction to IR_U testcases for XID negotiation | F | 6.0.0 | 6.1.0 | R5s060298 |
| RP-34 | RP-060737 | 1867 | - | Correction to RRC testcase 8.2.2.9 | F | 6.0.0 | 6.1.0 | R5s060299 |
| RP-34 | RP-060737 | 1868 | - | Correction to RRC testcase 8.3.1.30 | F | 6.0.0 | 6.1.0 | R5s060300 |
| RP-34 | RP-060737 | 1869 | - | iWD_wk36 ATS Regression Errors Corrections | F | 6.0.0 | 6.1.0 | R5s060294 |
| RP-34 | RP-060737 | 1870 | - | Summary of regression errors in the wk36 IR_U_r3 ATS. | F | 6.0.0 | 6.1.0 | R5s060290 |
| RP-34 | RP-060737 | 1871 | - | TTCN Correction to GCF WI-10 RRC Test Cases 8.1.1.4, 8.1.1.5 and 8.1.1.6 | F | 6.0.0 | 6.1.0 | R5s060292 |
| RP-34 | RP-060737 | 1872 | - | TTCN correction to GCF WI-10 RRC Test Cases 8.1.2.2 and 8.1.2.9 | F | 6.0.0 | 6.1.0 | R5s060293 |
| RP-34 | RP-060737 | 1873 | - | Correction to WI 10/2 RRC testcase 8.4.1.8 | F | 6.0.0 | 6.1.0 | R5s060285 |
| RP-34 | RP-060737 | 1874 | - | Summary of regression errors in wk36 GCF WI-10 and GCF WI-12 ATS | F | 6.0.0 | 6.1.0 | R5s060274 |
| RP-34 | RP-060737 | 1875 | - | Summary of Regression Errors in wk36 ATS | F | 6.0.0 | 6.1.0 | R5s060280 |
| RP-34 | RP-060737 | 1876 | - | Correction to approved GCF WI-010 Test Case 16.2.1 | F | 6.0.0 | 6.1.0 | R5s060278 |
| RP-34 | RP-060737 | 1877 | - | Correction to GCF WI-12 RRC Test Case 8.2.2.43 | F | 6.0.0 | 6.1.0 | R5s060279 |
| RP-34 | RP-060737 | 1878 | - | Correction to testcase 14.2.58 | F | 6.0.0 | 6.1.0 | R5s060267 |
| RP-34 | RP-060737 | 1879 | - | TTCN CR to extend Guard Timer for GCF WI-10 and 12 RRC & RAB Test Cases | F | 6.0.0 | 6.1.0 | R5s060261 |
| RP-34 | RP-060738 | 1880 | - | Correction to testcase 8.2.6.48 | F | 6.0.0 | 6.1.0 | R5s060335 |
| RP-34 | RP-060738 | 1881 | - | Correction of PDP_Context_Status mandatory IE for Rel 5 and above | F | 6.0.0 | 6.1.0 | R5s060333 |
| RP-34 | RP-060738 | 1882 | - | Corrections to GCF WI-14/1 test case 8.3.11.9 | F | 6.0.0 | 6.1.0 | R5s060323 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-34 | RP-060738 | 1883 | - | Corrections to GCF WI 14/1 test case 8.2.3.35 | F | 6.0.0 | 6.1.0 | R5s060310 |
| RP-34 | RP-060738 | 1884 | - | Correction to GCF WI 14 RRC testcases in Non Ciphering path. | F | 6.0.0 | 6.1.0 | R5s060301 |
| RP-34 | RP-060738 | 1885 | - | Correction to HSDPA MRAT testcase 8.3.7.14 | F | 6.0.0 | 6.1.0 | R5s060297 |
| RP-34 | RP-060738 | 1886 | - | Summary of regression errors in wk36 HSD_ENH ATS | F | 6.0.0 | 6.1.0 | R5s060277 |
| RP-34 | RP-060738 | 1887 | - | TTCN CR to extend Guard Timer for GCF WI-14 RAB Test Case | F | 6.0.0 | 6.1.0 | R5s060262 |
| RP-34 | RP-060745 | 1888 | - | Addition of E-DCH MAC test case 7.1.6.2.7 to HSU_ENH ATS v6.0.0 | B | 6.0.0 | 6.1.0 | R5s060343 |
| RP-34 | RP-060745 | 1889 | - | Addition of E-DCH MAC test case 7.1.6.2.4 to HSU_ENH ATS v6.0.0 | B | 6.0.0 | 6.1.0 | R5s060347 |
| RP-34 | RP-060737 | 1890 | - | Correction to approved GCF WI-10/3 RRC test case 6.1.2.6 | F | 6.0.0 | 6.1.0 | R5s060339 |
| RP-34 | RP-060737 | 1891 | - | Correction to GCF WI-10 Idle Mode Test Case 6.1.2.8 | F | 6.0.0 | 6.1.0 | R5s060340 |
| RP-34 | RP-060737 | 1892 | - | Correction to GCF WI-10 RRC Test Case 8.3.1.31 | F | 6.0.0 | 6.1.0 | R5s060342 |
| RP-34 | RP-060737 | 1896 | - | Corrections of approved GCF WI-12 test case 8.2.2.43. | F | 6.0.0 | 6.1.0 | R5s060317 |
| RP-34 | RP-060737 | 1897 | - | Correction to GCF WI-10 RRC Test Case 8.4.1.8 | F | 6.0.0 | 6.1.0 | R5s060322 |
| RP-35 | RP-070099 | 1898 | | Addition of GCF WI-25 HSUPA MAC Test Case 7.1.6.4.3 | B | 6.1.0 | 6.2.0 | R5s060401 |
| RP-35 | RP-070099 | 1899 | | Addition of GCF WI-25 RAB Test Case 14.7.4 | B | 6.1.0 | 6.2.0 | R5s060399 |
| RP-35 | RP-070099 | 1900 | | Addition of GCF WI-25 HSUPA Test Case 7.1.6.2.10 | B | 6.1.0 | 6.2.0 | R5s060378 |
| RP-35 | RP-070099 | 1901 | | Addition of GCF WI-25 HSUPA MAC Test Case 7.1.6.4.2 | B | 6.1.0 | 6.2.0 | R5s060395 |
| RP-35 | RP-070099 | 1902 | | Addition of GCF WI-25 HSUPA Test Case 8.2.2.45 | B | 6.1.0 | 6.2.0 | R5s060384 |
| RP-35 | RP-070099 | 1903 | | Addition of GCF WI-25 HSUPA MAC Test Case 7.1.6.1.3 | B | 6.1.0 | 6.2.0 | R5s060380 |
| RP-35 | RP-070099 | 1904 | | Addition of GCF WI-25 HSUPA MAC Test Case 7.1.6.2.8 | B | 6.1.0 | 6.2.0 | R5s060376 |
| RP-35 | RP-070099 | 1905 | | Addition of GCF WI-25 HSUPA Test Case 7.1.6.2.9 | B | 6.1.0 | 6.2.0 | R5s060381 |
| RP-35 | RP-070106 | 1906 | | Addition of GCF WI-10 Idle mode test case 6.1.2.9a | B | 6.1.0 | 6.2.0 | R5s070027 |
| RP-35 | RP-070106 | 1907 | | Addition of GCF WI-10 Idle mode test case 6.1.2.9b | B | 6.1.0 | 6.2.0 | R5s070029 |
| RP-35 | RP-070110 | 1908 | | Addition of WB-AMR RAB test case 14.2.4b to HSD_ENH_r5 ATS V6.1.0 | B | 6.1.0 | 6.2.0 | R5s070033 |
| RP-35 | RP-070099 | 1909 | | Addition of E-DCH RAB test case 14.7.5 to HSU_ENH_r6 ATS V6.0.0 | B | 6.1.0 | 6.2.0 | R5s060328 |
| RP-35 | RP-070099 | 1910 | | Addition of E-DCH RAB test case 14.7.2 to HSU_ENH_r6 ATS V6.0.0 | B | 6.1.0 | 6.2.0 | R5s060326 |
| RP-35 | RP-070099 | 1911 | | Addition of E-DCH MAC test case 7.1.6.3.1 to HSU_ENH_r6 ATS V6.0.0 | B | 6.1.0 | 6.2.0 | R5s060364 |
| RP-35 | RP-070099 | 1912 | | Addition of E-DCH MAC test case 7.1.6.1.2 to HSU_ENH_r6 ATS V6.0.0 | B | 6.1.0 | 6.2.0 | R5s060362 |
| RP-35 | RP-070099 | 1913 | | Addition of E-DCH MAC test case 7.1.6.1.1 to HSU_ENH_r6 ATS V6.0.0 | B | 6.1.0 | 6.2.0 | R5s060360 |
| RP-35 | RP-070099 | 1914 | | Correction to GCF WI-025 test case 8.3.1.41 | F | 6.1.0 | 6.2.0 | R5s060404 |
| RP-35 | RP-070099 | 1915 | | Correction to GCF WI-25 RAB Test Case 14.7.5 | F | 6.1.0 | 6.2.0 | R5s060408 |
| RP-35 | RP-070106 | 1916 | | Summary of Regression Errors in NAS wk49 ATS | F | 6.1.0 | 6.2.0 | R5s060406 |
| RP-35 | RP-070106 | 1917 | | Summary of regression errors in wk49 ATS | F | 6.1.0 | 6.2.0 | R5s060405 |
| RP-35 | RP-070106 | 1918 | | Correction to GCF WI-10 SMS test case 16.3 | F | 6.1.0 | 6.2.0 | R5s070005 |
| RP-35 | RP-070106 | 1919 | | Correction to GCF WI-10 SMS test cases 16.1.1 and 16.1.2 | F | 6.1.0 | 6.2.0 | R5s070006 |
| RP-35 | RP-070106 | 1920 | | Correction to GCF WI-10 RRC test case 6.1.2.3 | F | 6.1.0 | 6.2.0 | R5s070007 |
| RP-35 | RP-070106 | 1921 | | Summary of regression errors in wk49 IRAT ATSSs. | F | 6.1.0 | 6.2.0 | R5s070004 |
| RP-35 | RP-070106 | 1922 | | Correction to GCF WI-10 NAS Test Case 12.9.12 | F | 6.1.0 | 6.2.0 | R5s070001 |
| RP-35 | RP-070106 | 1923 | | Correction to GCF WI-10 RRC Test Case 8.4.1.25 and 8.4.1.48 | F | 6.1.0 | 6.2.0 | R5s070002 |
| RP-35 | RP-070106 | 1924 | | Correction to GCF WI-10 RAB Test Case 14.2.58 | F | 6.1.0 | 6.2.0 | R5s070003 |
| RP-35 | RP-070099 | 1925 | | Correction to GCF WI-025 test case 14.7.4 | F | 6.1.0 | 6.2.0 | R5s070019 |
| RP-35 | RP-070106 | 1926 | | Correction to GCF WI-10 RRC Test Case 8.4.1.2 | F | 6.1.0 | 6.2.0 | R5s070026 |
| RP-35 | RP-070106 | 1927 | | Correction to GCF WI-10 IR-U Test Case 12.8 | F | 6.1.0 | 6.2.0 | R5s070025 |
| RP-35 | RP-070106 | 1928 | | Corrections to GCF WI-17 DTM test case 8.3.7.17 | F | 6.1.0 | 6.2.0 | R5s070023 |
| RP-35 | RP-070106 | 1929 | | Correction to approved test case 8.4.1.8 | F | 6.1.0 | 6.2.0 | R5s070020 |
| RP-35 | RP-070106 | 1930 | | Correction to approved test case 8.2.6.38 | F | 6.1.0 | 6.2.0 | R5s070021 |
| RP-35 | RP-070106 | 1931 | | Correction to the NAS test case 9.2.2 | F | 6.1.0 | 6.2.0 | R5s070011 |
| RP-35 | RP-070106 | 1932 | | Correction to NAS test cases 12.4.1.1b and 12.9.9 | F | 6.1.0 | 6.2.0 | R5s070012 |
| RP-35 | RP-070106 | 1933 | | Correction to RRC testcase 8.4.1.2 | F | 6.1.0 | 6.2.0 | R5s070013 |
| RP-35 | RP-070106 | 1934 | | Correction to DSAC testcases 12.9.15, 12.4.2.11 and 12.4.2.12 | F | 6.1.0 | 6.2.0 | R5s070014 |
| RP-35 | RP-070107 | 1935 | | Correction to AGPS ASP Retri_GPS_AssistanceData_CNF | F | 6.1.0 | 6.2.0 | R5s070015 |
| RP-35 | RP-070107 | 1936 | | Correction to the RRC testcase 8.3.4.8 | F | 6.1.0 | 6.2.0 | R5s070017 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-35 | RP-070107 | 1937 | | Summary of Regression Errors in wk49 ATSS | F | 6.1.0 | 6.2.0 | R5s070018 |
| RP-35 | RP-070107 | 1938 | | Introduction of Band 8 | F | 6.1.0 | 6.2.0 | R5s070008 |
| RP-35 | RP-070107 | 1939 | | Correction of CC procedure for multimedia calls | F | 6.1.0 | 6.2.0 | R5s070010 |
| RP-35 | RP-070110 | 1940 | | Correction to RRC TC 8.3.4.9 to avoid possible radio link failure. | F | 6.1.0 | 6.2.0 | R5s070022 |
| RP-35 | RP-070110 | 1941 | | Correction to GCF WI-14 HSDPA Test Case 14.6.4a | F | 6.1.0 | 6.2.0 | R5s070024 |
| RP-35 | RP-070107 | 1942 | | Step enhancement for the introduction of InterBand Test cases | F | 6.1.0 | 6.2.0 | R5s070031 |
| RP-35 | RP-070107 | 1943 | | Correction to GCF WI-10 RRC Test Case 8.3.1.5 | F | 6.1.0 | 6.2.0 | R5s070039 |
| RP-35 | RP-070107 | 1944 | | Correction to Inter-RAT testcase 8.3.7.3 | F | 6.1.0 | 6.2.0 | R5s070038 |
| RP-35 | RP-070110 | 1945 | | Correction to GCF WI-13 Test Case 8.3.1.40 | F | 6.1.0 | 6.2.0 | R5s070040 |
| RP-35 | RP-070110 | 1946 | | Correction to Idle mode testcase 6.1.2.10 | F | 6.1.0 | 6.2.0 | R5s070036 |
| RP-35 | RP-070112 | 1947 | | Correction to DSAC RRC testcase 8.1.2.16 | F | 6.1.0 | 6.2.0 | R5s070037 |
| RP-35 | RP-070110 | 1948 | | Correction to test case 8.2.6.39b & 8.3.4.9 | F | 6.1.0 | 6.2.0 | R5s070041 |
| RP-35 | RP-070107 | 1949 | | Correction to the NAS Test Case 12.3.2.1 | F | 6.1.0 | 6.2.0 | R5s060352 |
| RP-35 | RP-070107 | 1950 | | Correction to GCF WI-012 test case 12.3.2.7 | F | 6.1.0 | 6.2.0 | R5s060351 |
| RP-35 | RP-070107 | 1951 | | Correction to approved GCF WI-10 test case 8.3.7.1. | F | 6.1.0 | 6.2.0 | R5s060345 |
| RP-35 | RP-070107 | 1952 | | Correction of approved GCF WI-010 test case 8.1.7.1c | F | 6.1.0 | 6.2.0 | R5s060316 |
| RP-35 | RP-070107 | 1953 | | Correction to GCF WI-12 MAC Test Case 7.1.3.2 | F | 6.1.0 | 6.2.0 | R5s060354 |
| RP-35 | RP-070107 | 1954 | | Correction to QOS checking for UE not support AT commands to start MO PS call | F | 6.1.0 | 6.2.0 | R5s060353 |
| RP-35 | RP-070112 | 1955 | | Correction to GCF WI-24 DSAC Test Case 12.4.2.11 | F | 6.1.0 | 6.2.0 | R5s060355 |
| RP-35 | RP-070107 | 1956 | | Summary of regression errors in wk43 ATS | F | 6.1.0 | 6.2.0 | R5s060341 |
| RP-35 | RP-070107 | 1957 | | Correction to GCF WI 10/2 RRC testcase 8.4.1.8 | F | 6.1.0 | 6.2.0 | R5s060389 |
| RP-35 | RP-070107 | 1958 | | TTCN correction to GMM Test Case 12.4.1.4b | F | 6.1.0 | 6.2.0 | R5s060357 |
| RP-35 | RP-070107 | 1959 | | Summary of regression errors in wk47 IRAT ATSS. | F | 6.1.0 | 6.2.0 | R5s060372 |
| RP-35 | RP-070107 | 1960 | | Change of PDU type definition REGISTER used in MM test cases | F | 6.1.0 | 6.2.0 | R5s060388 |
| RP-35 | RP-070107 | 1961 | | Correction to GCF WI-10 RRC Test Case 8.4.1.25 | F | 6.1.0 | 6.2.0 | R5s060374 |
| RP-35 | RP-070108 | 1962 | | Summary of Regression Errors in NAS wk47 ATS – Batch2 | F | 6.1.0 | 6.2.0 | R5s060371 |
| RP-35 | RP-070108 | 1963 | | Summary of Regression Errors in NAS wk47 ATS | F | 6.1.0 | 6.2.0 | R5s060369 |
| RP-35 | RP-070108 | 1964 | | Summary of Regression Errors in RAB wk47 ATS | F | 6.1.0 | 6.2.0 | R5s060370 |
| RP-35 | RP-070108 | 1965 | | Correction to GCF WI-10 RRC Test Case 8.1.2.4 | F | 6.1.0 | 6.2.0 | R5s060367 |
| RP-35 | RP-070108 | 1966 | | Correction to GCF WI-10 RRC Test Case 6.1.2.1 | F | 6.1.0 | 6.2.0 | R5s060366 |
| RP-35 | RP-070110 | 1967 | | TTCN correction to GCF WI-014 RRC HSDPA Test Case 8.3.1.35 | F | 6.1.0 | 6.2.0 | R5s060359 |
| RP-35 | RP-070110 | 1968 | | Summary of Regression Errors in HSDPA wk47 ATS | F | 6.1.0 | 6.2.0 | R5s060368 |
| RP-35 | RP-070099 | 1969 | | Corrections to E-DCH test case 14.7.1 | F | 6.1.0 | 6.2.0 | R5s060403 |
| RP-35 | RP-070099 | 1970 | | Corrections to E-DCH test case 7.1.6.2.3 and 7.1.6.2.7 | F | 6.1.0 | 6.2.0 | R5s060394 |
| RP-35 | RP-070099 | 1971 | | Summary of Regression Errors in HSU wk47 ATS | F | 6.1.0 | 6.2.0 | R5s060375 |
| RP-35 | RP-070108 | 1972 | | Correction to approved test case 8.4.1.2, 8.4.1.6, 8.4.1.24 | F | 6.1.0 | 6.2.0 | R5s060391 |
| RP-35 | RP-070110 | 1973 | | Summary of regression errors in wk47 ATS | F | 6.1.0 | 6.2.0 | R5s060393 |
| RP-35 | RP-070110 | 1974 | | Correction to approved GCF WI-014 test case 8.2.6.48 | F | 6.1.0 | 6.2.0 | R5s060392 |
| RP-35 | RP-070108 | 1975 | | Correction to RRC constraint 'cr_RRC_RrcConnSetupCmplRadioCap_BandList2' for Band VIII | F | 6.1.0 | 6.2.0 | R5s070035 |
| RP-35 | RP-070108 | 1976 | | Addition of GCF WI-010 P4 test case 8.2.6.37 to RRC ATS V6.1.0 | B | 6.1.0 | 6.2.0 | R5s070050 |
| RP-35 | RP-070108 | 1977 | | Correction to GCF WI-10 NAS test cases using SETUP ul constraints | F | 6.1.0 | 6.2.0 | R5s070043 |
| RP-35 | RP-070108 | 1978 | | Correction to GCF WI-10 NAS test cases 9.1 and 12.9.7c | F | 6.1.0 | 6.2.0 | R5s070044 |
| RP-35 | RP-070108 | 1979 | | Correction to GCF WI-10 NAS test case 9.4.2.2 Procedure 2 | F | 6.1.0 | 6.2.0 | R5s070045 |
| RP-35 | RP-070100 | 1981 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 6.1.0 | 6.2.0 | - |
| RP-35 | RP-070108 | 1982 | | Correction to the MAC suite for Band VI | F | 6.1.0 | 6.2.0 | R5s070052 |
| RP-35 | RP-070108 | 1983 | | Summary of regression errors in 07wk03 ATSS | F | 6.1.0 | 6.2.0 | R5s070053 |
| RP-35 | RP-070108 | 1984 | | Cell setup issue in 15 Idle Mode, RRC and NAS test cases | F | 6.1.0 | 6.2.0 | R5s070054 |
| RP-35 | RP-070108 | 1985 | | Correction to RRC testcase 6.1.2.6 | F | 6.1.0 | 6.2.0 | R5s070059 |
| RP-35 | RP-070108 | 1986 | | Correction to constraint cr_UE_CapabilityInfoAM_BandList2 for Band VIII | F | 6.1.0 | 6.2.0 | R5s070061 |
| RP-35 | RP-070108 | 1987 | | Corrections to wk03 AGPS ATS | F | 6.1.0 | 6.2.0 | R5s070032 |
| RP-35 | RP-070108 | 1988 | | Recovering LAI checking in RRC CONNECTION REQUEST in 8.1.2.x. test cases | F | 6.1.0 | 6.2.0 | R5s070057 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|--|-----|-------------|-------------|-----------|
| RP-35 | RP-070108 | 1989 | | Correction to RRC testcase 8.4.1.2 | F | 6.1.0 | 6.2.0 | R5s070056 |
| RP-35 | RP-070108 | 1990 | | Cleaning of UE capability check procedure and band PICS | F | 6.1.0 | 6.2.0 | R5s070042 |
| RP-35 | RP-070109 | 1991 | | Correction to remove dependency on px_CipheringOnOff in L2 test cases | F | 6.1.0 | 6.2.0 | R5s070055 |
| RP-35 | RP-070110 | 1992 | | Correction to HSDPA testcase 8.2.4.36 | F | 6.1.0 | 6.2.0 | R5s070060 |
| RP-35 | RP-070099 | 1993 | | Addition of GCF WI 25 RRC test case 8.2.3.36 to HSU_ENH_r6 ATS V6.1.0. | B | 6.1.0 | 6.2.0 | R5s070062 |
| RP-35 | RP-070099 | 1994 | | Addition of GCF WI-25 EDCH RRC test case 8.2.2.46 | B | 6.1.0 | 6.2.0 | R5s070064 |
| RP-35 | RP-070109 | 1995 | | Correction to RLC Test case 7.2.3.35 | F | 6.1.0 | 6.2.0 | R5s070058 |
| RP-35 | RP-070098 | 1996 | | Activation time in EDCH ASP and ASP order | F | 6.1.0 | 6.2.0 | R5-070033 |
| RP-35 | RP-070087 | 1997 | | MBMS test model and ASP | F | 6.1.0 | 6.2.0 | R5-070460 |
| RP-35 | RP-070103 | 1998 | | Correction of Band VIII test and Max. number of Almanac data | F | 6.1.0 | 6.2.0 | R5-070400 |
| RP-35 | RP-070105 | 1999 | | Documentation of a test configuration and other corrections | F | 6.1.0 | 6.2.0 | R5-070401 |
| RP-35 | RP-070103 | 2000 | | Corrections to AGPS asn.1 module | F | 6.1.0 | 6.2.0 | R5-070091 |
| RP-36 | RP-070359 | 2001 | | Addition of GCF WI 25 test case 8.3.4.10 to HSU_ENH_r6 ATS V6.1.0. | B | 6.2.0 | 6.3.0 | R5s070047 |
| RP-36 | RP-070359 | 2002 | | Addition of RRC test case 8.2.6.54 to HSD_ENH_r5 ATS V6.1.0 | B | 6.2.0 | 6.3.0 | R5s070112 |
| RP-36 | RP-070359 | 2003 | | Addition of GCF WI-25 EDCH test case 8.2.2.48 | B | 6.2.0 | 6.3.0 | R5s070079 |
| RP-36 | RP-070359 | 2004 | | Addition of GCF WI-25 EDCH test case 8.2.6.51 | B | 6.2.0 | 6.3.0 | R5s070140 |
| RP-36 | RP-070359 | 2005 | | Addition of E-DCH test case 7.1.6.2.2 to HSUPA ATS v6.1.0 | B | 6.2.0 | 6.3.0 | R5s070103 |
| RP-36 | RP-070347 | 2006 | | Addition of GCF WI-047 test case 8.4.1.25A to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070126 |
| RP-36 | RP-070347 | 2007 | | Addition of GCF WI-047 test case 8.4.1.2B to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070122 |
| RP-36 | RP-070347 | 2008 | | Addition of GCF WI-047 test case 8.2.1.34a to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070120 |
| RP-36 | RP-070347 | 2009 | | Addition of GCF WI-047 test case 8.2.1.24a to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070118 |
| RP-36 | RP-070347 | 2010 | | Addition of GCF WI-047 test case 6.1.2.10a to HSDPA ATS. | B | 6.2.0 | 6.3.0 | R5s070085 |
| RP-36 | RP-070347 | 2011 | | Addition of GCF WI-047 test case 8.1.2.10a to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070083 |
| RP-36 | RP-070347 | 2012 | | Addition of GCF WI-047 test case 6.1.2.1a to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070081 |
| RP-36 | RP-070347 | 2013 | | Addition of GCF WI10 RRC test case 8.4.1.42 to RRC ATS v6.1.0 | B | 6.2.0 | 6.3.0 | R5s070109 |
| RP-36 | RP-070352 | 2014 | | Addition of WB-AMR RAB test case 14.6.8 to HSD_ENH_r5 ATS V6.1.0 | B | 6.2.0 | 6.3.0 | R5s070072 |
| RP-36 | RP-070352 | 2015 | | Addition of WB-AMR RAB test case 14.2.62 to HSD_ENH_r5 ATS V6.1.0 | B | 6.2.0 | 6.3.0 | R5s070077 |
| RP-36 | RP-070359 | 2016 | | Summary of regression errors in 07wk08 HSUPA ATS | F | 6.2.0 | 6.3.0 | R5s070069 |
| RP-36 | RP-070359 | 2017 | | Correction to E-DCH testcases using rv0 | F | 6.2.0 | 6.3.0 | R5s070071 |
| RP-36 | RP-070359 | 2018 | | Correction to approved 8.3.1.41 test case | F | 6.2.0 | 6.3.0 | R5s070130 |
| RP-36 | RP-070359 | 2019 | | Correction to test steps ts_InitVariablesHSU & ts_SS_RelDPCH_E_HS | F | 6.2.0 | 6.3.0 | R5s070098 |
| RP-36 | RP-070359 | 2020 | | Correction to E-DCH testcases 7.1.6.4.3 | F | 6.2.0 | 6.3.0 | R5s070095 |
| RP-36 | RP-070359 | 2021 | | Correction to GCF WI-25 test case 7.1.6.2.2 | F | 6.2.0 | 6.3.0 | R5s070138 |
| RP-36 | RP-070359 | 2022 | | Correction to E-DCH testcases 8.2.2.46 & 8.2.3.36 | F | 6.2.0 | 6.3.0 | R5s070115 |
| RP-36 | RP-070347 | 2023 | | Correction to GCF WI-10 NAS Test Case 12.4.1.4a | F | 6.2.0 | 6.3.0 | R5s070128 |
| RP-36 | RP-070347 | 2024 | | Correction to GCF WI-10 Test Cases 9.4.5.4.1, 6.1.2.9a and 6.1.2.9b | F | 6.2.0 | 6.3.0 | R5s070129 |
| RP-36 | RP-070347 | 2025 | | Summary of regression errors in wk11 ATS | F | 6.2.0 | 6.3.0 | R5s070111 |
| RP-36 | RP-070347 | 2026 | | Summary of regression errors in wk08 ATS | F | 6.2.0 | 6.3.0 | R5s070090 |
| RP-36 | RP-070347 | 2027 | | Correction to GCF WI-10 RRC Test Case 12.9.6 , 12.4.2.4 , 12.2.1.4.1 | F | 6.2.0 | 6.3.0 | R5s070092 |
| RP-36 | RP-070347 | 2028 | | Summary of Regression Errors in wk08 ATSS | F | 6.2.0 | 6.3.0 | R5s070087 |
| RP-36 | RP-070347 | 2029 | | Improvement on Guard Timer Timeout Handling | F | 6.2.0 | 6.3.0 | R5s070093 |
| RP-36 | RP-070347 | 2030 | | Summary of Regression errors in wk 11 IR_U ATS | F | 6.2.0 | 6.3.0 | R5s070134 |
| RP-36 | RP-070347 | 2031 | | Correction to GCF WI-10 NAS test case 9.4.2.2 Procedure 2 | F | 6.2.0 | 6.3.0 | R5s070100 |
| RP-36 | RP-070347 | 2032 | | Correction to RRC testcase 8.4.1.8 & 8.4.1.28 | F | 6.2.0 | 6.3.0 | R5s070097 |
| RP-36 | RP-070348 | 2033 | | Correction to RRC testcase 8.4.1.2 & 8.4.1.6 | F | 6.2.0 | 6.3.0 | R5s070096 |
| RP-36 | RP-070348 | 2034 | | Removal of pc_MS_ClsmkFreqCap | F | 6.2.0 | 6.3.0 | R5s070094 |
| RP-36 | RP-070348 | 2035 | | Summary of regression errors in 07wk03 IRAT ATSS | F | 6.2.0 | 6.3.0 | R5s070049 |
| RP-36 | RP-070348 | 2036 | | Alignment of TTCN implementation of default radio configurations | F | 6.2.0 | 6.3.0 | R5s070135 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-36 | RP-070348 | 2037 | | Corrections to AGPS test cases 17.2.x (GCF WI-015) | F | 6.2.0 | 6.3.0 | R5s070075 |
| RP-36 | RP-070348 | 2038 | | Correction to RAB Test cases 14.4.2.1 and 14.4.2a.1 | F | 6.2.0 | 6.3.0 | R5s070099 |
| RP-36 | RP-070348 | 2039 | | Correction to MRAT Idle mode testcases 6.2.1.1 and 6.2.1.6 | F | 6.2.0 | 6.3.0 | R5s070066 |
| RP-36 | RP-070348 | 2040 | | Further correction to QOS checking for UE not support AT commands to start MO PS call | F | 6.2.0 | 6.3.0 | R5s070139 |
| RP-36 | RP-070348 | 2041 | | Rel-6 baseline upgrade | F | 6.2.0 | 6.3.0 | R5s070132 |
| RP-36 | RP-070348 | 2042 | | Summary of regression errors in wk11 ATS | F | 6.2.0 | 6.3.0 | R5s070142 |
| RP-36 | RP-070348 | 2043 | | Summary of regression errors in the wk08 HSDPA InterRAT ATS | F | 6.2.0 | 6.3.0 | R5s070067 |
| RP-36 | RP-070348 | 2044 | | Correction to GCF WI-10 Idle Mode test case 6.1.1.7 | F | 6.2.0 | 6.3.0 | R5s070114 |
| RP-36 | RP-070348 | 2045 | | Correction to GCF WI-10 NAS Test Case 12.2.1.6 Proc 1 and 2 | F | 6.2.0 | 6.3.0 | R5s070107 |
| RP-36 | RP-070348 | 2046 | | Correction to GCF WI-10 SMS Test Case 16.2.1 | F | 6.2.0 | 6.3.0 | R5s070117 |
| RP-36 | RP-070348 | 2047 | | Corrections to the GCF WI-010 P4 test case 8.2.6.37 | F | 6.2.0 | 6.3.0 | R5s070074 |
| RP-36 | RP-070352 | 2048 | | Correction to UM constraints used with type CRLC_Config_Req | F | 6.2.0 | 6.3.0 | R5s070070 |
| RP-36 | RP-070352 | 2049 | | Summary of regression errors in wk-11 MAC ATS | F | 6.2.0 | 6.3.0 | R5s070131 |
| RP-36 | RP-070352 | 2050 | | Correction to approved 8.2.6.39a and 8.2.6.39b test cases | F | 6.2.0 | 6.3.0 | R5s070076 |
| RP-36 | RP-070352 | 2051 | | Correction to WB-AMR RAB test cases 14.2.62, 14.2.4b and 14.6.8 | F | 6.2.0 | 6.3.0 | R5s070136 |
| RP-36 | RP-070352 | 2052 | | Correction of approved GCF WI14 test case 8.3.7.14. | F | 6.2.0 | 6.3.0 | R5s070105 |
| RP-36 | RP-070352 | 2053 | | Corrections to WB-AMR RAB test cases 14.2.4b and 14.2.62 | F | 6.2.0 | 6.3.0 | R5s070108 |
| RP-36 | RP-070348 | 2054 | | Correction to GCF WI-10 NAS Test Case 12.8 | F | 6.2.0 | 6.3.0 | R5s070143 |
| RP-36 | RP-070348 | 2055 | | Correction to GCF WI-10 RRC test case 8.2.6.8 | F | 6.2.0 | 6.3.0 | R5s070137 |
| RP-36 | RP-070359 | 2056 | | Correction to GCF WI-25 test case 7.1.6.2.2 | F | 6.2.0 | 6.3.0 | R5s070144 |
| RP-36 | RP-070348 | 2057 | | Correction to GCF WI-10 Test Case 8.2.6.37 , 8.2.6.38 | F | 6.2.0 | 6.3.0 | R5s070145 |
| RP-36 | RP-070347 | 2058 | | Addition of GCF WI-047 test case 8.4.1.24A to RRC ATS. | B | 6.2.0 | 6.3.0 | R5s070124 |
| RP-36 | RP-070348 | 2059 | | Correction to GCF WI-10 Idle Mode Test Case 6.1.2.6 | F | 6.2.0 | 6.3.0 | R5s070146 |
| RP-36 | RP-070347 | 2060 | | Addition of GCF WI-047 test case 8.2.6.37b to RRC ATS | B | 6.2.0 | 6.3.0 | R5s070149 |
| RP-36 | RP-070359 | 2061 | | Correction to approved 7.1.6.4.3 test case | F | 6.2.0 | 6.3.0 | R5s070148 |
| RP-36 | RP-070352 | 2062 | | Corrections to GCF WI-13 and WI-14 WB-AMR Test Cases 14.2.4b, 14.2.62 and 14.6.8 | F | 6.2.0 | 6.3.0 | R5s070147 |
| RP-36 | RP-070355 | 2063 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 6.2.0 | 6.3.0 | - |
| RP-36 | RP-070358 | 2064 | | ASP enhancement for configuration of stand-alone UL-DPCH | F | 6.2.0 | 6.3.0 | R5-071030 |
| RP-36 | RP-070346 | 2065 | | Documentation of TSO and recovering erroneously removed IE in ASP | F | 6.2.0 | 6.3.0 | R5-071433 |
| RP-36 | RP-070354 | 2066 | | Editorial corrections in the reference list | F | 6.2.0 | 6.3.0 | R5-071445 |
| RP-36 | RP-070361 | 2067 | | Allocation of channel Id for MBMS test | F | 6.2.0 | 6.3.0 | R5-071461 |
| RP-36 | RP-070346 | 2068 | | Guideline on MCC setting for the Primary band cell | F | 6.2.0 | 6.3.0 | R5-071478 |
| RP-37 | RP-070605 | 2069 | - | Add a new ASP for MBMS test | F | 6.3.0 | 6.4.0 | R5-072050 |
| RP-37 | RP-070593 | 2070 | - | RoHC test model and ASP | F | 6.3.0 | 6.4.0 | R5-072051 |
| RP-37 | RP-070589 | 2071 | - | Addition of ASP for FMO & addition of IE paging cycle splitting | F | 6.3.0 | 6.4.0 | R5-072466 |
| RP-37 | RP-070593 | 2072 | - | Correction to RB identities mapping | F | 6.3.0 | 6.4.0 | R5-072337 |
| RP-37 | RP-070598 | 2073 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 6.3.0 | 6.4.0 | - |
| RP-37 | RP-070590 | 2074 | - | TTCN Correction in testcases 8.3.7.16, 8.3.7.17 | F | 6.3.0 | 6.4.0 | R5s070209 |
| RP-37 | RP-070590 | 2075 | - | Correction to GCF WI-10 RRC test case 8.4.1.14 | F | 6.3.0 | 6.4.0 | R5s070199 |
| RP-37 | RP-070595 | 2076 | - | Corrections to GCF WI-14 HSD Test Cases 8.3.1.40 | F | 6.3.0 | 6.4.0 | R5s070179 |
| RP-37 | RP-070590 | 2077 | - | TTCN Correction in testcases 8.1.7.1c, 8.2.6.39, 8.2.6.44, 8.3.1.25, 8.3.1.30 | F | 6.3.0 | 6.4.0 | R5s070187 |
| RP-37 | RP-070590 | 2078 | - | Correction to RRC testcase 8.2.6.37 & 8.2.6.38 | F | 6.3.0 | 6.4.0 | R5s070198 |
| RP-37 | RP-070590 | 2079 | - | Correction to IR_U and IR_G test suites to support split paging cycle on CCCH | F | 6.3.0 | 6.4.0 | R5s070190 |
| RP-37 | RP-070603 | 2080 | - | Correction to GCF WI-25 HSUPA test case 8.2.6.54 | F | 6.3.0 | 6.4.0 | R5s070173 |
| RP-37 | RP-070590 | 2081 | - | Correction to test step "ts_AT_CmdCBST" for setting correct speed in case of 3G324M Call. | F | 6.3.0 | 6.4.0 | R5s070200 |
| RP-37 | RP-070590 | 2082 | - | Correction to the test cases to enable Fach Measurement Occasion in the SS | F | 6.3.0 | 6.4.0 | R5s070189 |
| RP-37 | RP-070590 | 2083 | - | Corrections to GCF WI-10 Test Cases 8.4.1.14 | F | 6.3.0 | 6.4.0 | R5s070172 |
| RP-37 | RP-070590 | 2084 | - | Corrections to GCF WI-14 RAB Testcase 14.6.3, 14.6.3a, 14.6.4, 14.6.4a, 14.6.7, 14.6.8 | F | 6.3.0 | 6.4.0 | R5s070195 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-37 | RP-070590 | 2085 | - | Correction to PDU loopback control timer used in RAB test cases | F | 6.3.0 | 6.4.0 | R5s070197 |
| RP-37 | RP-070590 | 2086 | - | TTCN Correction in SMS testcase 16.1.1 | F | 6.3.0 | 6.4.0 | R5s070188 |
| RP-37 | RP-070606 | 2087 | - | Enhancement for new MBMS cells | F | 6.3.0 | 6.4.0 | R5s070184 |
| RP-37 | RP-070590 | 2088 | - | Correction to GCF WI-15 AGPS test cases (17.2.4.1 to 9) | F | 6.3.0 | 6.4.0 | R5s070196 |
| RP-37 | RP-070590 | 2089 | - | Corrections to GCF Interband Test Cases 6.1.2.1a and 6.1.2.10a for Band9 | F | 6.3.0 | 6.4.0 | R5s070191 |
| RP-37 | RP-070590 | 2090 | - | Corrections to GCF WI-10 Test Cases 8.4.1.8 | F | 6.3.0 | 6.4.0 | R5s070180 |
| RP-37 | RP-070590 | 2091 | - | Correction to Interband Test Cases 8.4.1.24A | F | 6.3.0 | 6.4.0 | R5s070177 |
| RP-37 | RP-070590 | 2092 | - | Corrections to GCF WI-12 Test Case 8.2.2.43 | F | 6.3.0 | 6.4.0 | R5s070192 |
| RP-37 | RP-070590 | 2093 | - | Summary of Regression Errors in wk23 ATSS | F | 6.3.0 | 6.4.0 | R5s070183 |
| RP-37 | RP-070590 | 2094 | - | Summary of regression errors in wk23 ATS | F | 6.3.0 | 6.4.0 | R5s070166 |
| RP-37 | RP-070590 | 2095 | - | TTCN Correction in testcases 8.2.2.41, 8.2.2.42, 8.2.3.31, 8.2.3.32, 8.2.3.33, 8.2.3.34, 8.2.3.35 | F | 6.3.0 | 6.4.0 | R5s070175 |
| RP-37 | RP-070590 | 2096 | - | Summary of regression errors in the wk23 IR_U ATS. | F | 6.3.0 | 6.4.0 | R5s070171 |
| RP-37 | RP-070591 | 2097 | - | Correction to MAC testcase 7.1.3.2 | F | 6.3.0 | 6.4.0 | R5s070167 |
| RP-37 | RP-070603 | 2098 | - | Correction to E-DCH RRC testcase 8.3.4.10 | F | 6.3.0 | 6.4.0 | R5s070170 |
| RP-37 | RP-070591 | 2099 | - | Correction to RRC testcase 8.2.6.37, 8.2.6.37b & 8.4.1.14 | F | 6.3.0 | 6.4.0 | R5s070169 |
| RP-37 | RP-070595 | 2100 | - | Correction to RRC testcase 8.4.1.47 | F | 6.3.0 | 6.4.0 | R5s070168 |
| RP-37 | RP-070595 | 2101 | - | Correction to DSAC test cases | F | 6.3.0 | 6.4.0 | R5s070165 |
| RP-37 | RP-070595 | 2102 | - | Summary of Regression Errors in wk21 ATSS | F | 6.3.0 | 6.4.0 | R5s070164 |
| RP-37 | RP-070591 | 2103 | - | Summary of regression errors in wk21 ATS | F | 6.3.0 | 6.4.0 | R5s070163 |
| RP-37 | RP-070591 | 2104 | - | Summary of Regression Errors in wk17 ATSS | F | 6.3.0 | 6.4.0 | R5s070157 |
| RP-37 | RP-070591 | 2105 | - | Corrections to GCF WI-10 Test Cases 8.4.1.8 | F | 6.3.0 | 6.4.0 | R5s070161 |
| RP-37 | RP-070591 | 2106 | - | Correction of approved GCF WI12 test case 8.2.6.44. | F | 6.3.0 | 6.4.0 | R5s070162 |
| RP-37 | RP-070603 | 2107 | - | Addition of GCF WI-25 HSUPA test case 7.1.6.2.1 to HSU ATS v6.2.0 | B | 6.3.0 | 6.4.0 | R5s070158 |
| RP-37 | RP-070603 | 2108 | - | Addition of WB-AMR RAB test case 14.7.8 to HSU_ENH_r6 ATS V6.1.0 | B | 6.3.0 | 6.4.0 | R5s070151 |
| RP-37 | RP-070591 | 2109 | - | Summary of regression errors in wk18 ATS | F | 6.3.0 | 6.4.0 | R5s070154 |
| RP-37 | RP-070591 | 2110 | - | Corrections to GCF WI-10 NAS Test Cases 9.4.8 | F | 6.3.0 | 6.4.0 | R5s070155 |
| RP-37 | RP-070591 | 2111 | - | Correction to BMC Test Cases 16.3 and 14.4.4 | F | 6.3.0 | 6.4.0 | R5s070156 |
| RP-37 | RP-070591 | 2112 | - | Correction of approved GCF WI12 test case 8.1.2.13. | F | 6.3.0 | 6.4.0 | R5s070153 |
| RP-37 | RP-070591 | 2113 | - | Corrections to GCF WI-10 NAS Test Cases 8.3.9.1 | F | 6.3.0 | 6.4.0 | R5s070213 |
| RP-37 | RP-070591 | 2114 | - | Corrections to GCF WI-10 RRC test case 8.4.1.28 | F | 6.3.0 | 6.4.0 | R5s070214 |
| RP-37 | RP-070591 | 2115 | - | Cell setup issue in 16 Idle Mode, RRC and NAS test cases | F | 6.3.0 | 6.4.0 | R5s070210 |
| RP-37 | RP-070591 | 2116 | - | Summary of regression errors in wk28 ATS | F | 6.3.0 | 6.4.0 | R5s070215 |
| RP-37 | RP-070591 | 2117 | - | Addition of GCF WI-047 test case 8.3.1.1a to RRC ATS. | B | 6.3.0 | 6.4.0 | R5s070185 |
| RP-37 | RP-070591 | 2118 | - | TTCN Correction in testcase 6.2.2.2 | F | 6.3.0 | 6.4.0 | R5s070216 |
| RP-37 | RP-070591 | 2119 | - | Addition of GCF WI-047 test case 8.3.2.1a to RRC ATS. | B | 6.3.0 | 6.4.0 | R5s070193 |
| RP-37 | RP-070603 | 2120 | - | Addition of GCF WI-25 HSUPA test case 8.4.1.49 to HSU ATS v6.3.0 | B | 6.3.0 | 6.4.0 | R5s070202 |
| RP-38 | RP-070873 | 2121 | | Correction of max bit rate in QoS and AT commands for different UE categories and other maintenance | F | 6.4.0 | 6.5.0 | R5-073030 |
| RP-38 | RP-070873 | 2122 | | Application of synchronized data sending on MTCH and other maintenance for MBMS | F | 6.4.0 | 6.5.0 | R5-073032 |
| RP-38 | RP-070860 | 2123 | | Handling RLP XID in CSD call | F | 6.4.0 | 6.5.0 | R5-073467 |
| RP-38 | RP-070860 | 2124 | | R99 routine maintenance for PIXIT etc | F | 6.4.0 | 6.5.0 | R5-073435 |
| RP-38 | RP-070864 | 2125 | | To add new RRC test case 8.2.1.8 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070283 |
| RP-38 | RP-070864 | 2126 | | To add new GMM test case 12.7 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070444 |
| RP-38 | RP-070864 | 2127 | | To add new RRC test case 8.1.1.1 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070281 |
| RP-38 | RP-070864 | 2128 | | To add new GMM test case 12.2.1.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070291 |
| RP-38 | RP-070864 | 2129 | | To add new test case 16.1.1 to the LCR TDD SMS ATS | B | 6.4.0 | 6.5.0 | R5s070293 |
| RP-38 | RP-070864 | 2130 | | To add new SM test case 11.1.1.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070301 |
| RP-38 | RP-070864 | 2131 | | To add new test case 18.1.2.6 to the LCR TDD RAB ATS | B | 6.4.0 | 6.5.0 | R5s070295 |
| RP-38 | RP-070864 | 2132 | | To add new test case 7.1.1.1 to the LCR TDD MAC ATS | B | 6.4.0 | 6.5.0 | R5s070297 |
| RP-38 | RP-070864 | 2133 | | To add new test case 7.2.3.12 to the LCR TDD RLC ATS | B | 6.4.0 | 6.5.0 | R5s070299 |
| RP-38 | RP-070864 | 2134 | | To add new test case 13.2.1.1 to the LCR TDD NAS | B | 6.4.0 | 6.5.0 | R5s070303 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| | | | | ATS | | | | |
| RP-38 | RP-070864 | 2135 | | To add new RRC test case 8.1.1.4 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070309 |
| RP-38 | RP-070864 | 2136 | | To add new RRC test case 8.1.12 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070307 |
| RP-38 | RP-070864 | 2137 | | To add new RRC test case 8.1.5.4 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070323 |
| RP-38 | RP-070864 | 2138 | | To add new RRC test case 8.1.9 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070325 |
| RP-38 | RP-070864 | 2139 | | To add new RRC test case 8.2.2.11 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070331 |
| RP-38 | RP-070864 | 2140 | | To add new RRC test case 8.1.5.1 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070321 |
| RP-38 | RP-070864 | 2141 | | To add new RRC test case 8.2.2.9 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070329 |
| RP-38 | RP-070864 | 2142 | | To add new RRC test case 8.2.2.8 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070327 |
| RP-38 | RP-070864 | 2143 | | To add new RRC test case 8.2.3.7 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070335 |
| RP-38 | RP-070864 | 2144 | | To add new RRC test case 8.2.3.11 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070339 |
| RP-38 | RP-070865 | 2145 | | To add new RRC test case 8.2.3.9 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070337 |
| RP-38 | RP-070865 | 2146 | | To add new RRC test case 8.2.2.17 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070333 |
| RP-38 | RP-070865 | 2147 | | To add new RRC test case 8.2.6.7 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070347 |
| RP-38 | RP-070865 | 2148 | | To add new RRC test case 8.2.3.29 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070345 |
| RP-38 | RP-070865 | 2149 | | To add new RRC test case 8.2.6.11 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070349 |
| RP-38 | RP-070865 | 2150 | | To add new RRC test case 8.2.3.15 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070341 |
| RP-38 | RP-070865 | 2151 | | To add new RRC test case 8.4.1.17 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070353 |
| RP-38 | RP-070865 | 2152 | | To add new MM test case 9.2.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070358 |
| RP-38 | RP-070865 | 2153 | | To add new RRC test case 8.2.6.20 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070351 |
| RP-38 | RP-070865 | 2154 | | To add new RRC test case 8.4.1.24 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070355 |
| RP-38 | RP-070865 | 2155 | | To add new MM test case 9.5.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070362 |
| RP-38 | RP-070865 | 2156 | | To add new MM test case 9.4.4 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070360 |
| RP-38 | RP-070865 | 2157 | | To add new CC test case 10.1.2.2.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070368 |
| RP-38 | RP-070865 | 2158 | | To add new CC test case 10.1.2.2.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070370 |
| RP-38 | RP-070865 | 2159 | | To add new test case 13.2.2.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070480 |
| RP-38 | RP-070865 | 2160 | | To add new RRC test case 8.4.1.16 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070285 |
| RP-38 | RP-070865 | 2161 | | To add new CC test case 10.1.2.2.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070366 |
| RP-38 | RP-070865 | 2162 | | To add new CC test case 10.1.2.4.6 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070384 |
| RP-38 | RP-070865 | 2163 | | To add new CC test case 10.1.2.7.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070408 |
| RP-38 | RP-070865 | 2164 | | To add new GMM test case 12.4.3.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070440 |
| RP-38 | RP-070866 | 2165 | | To add new GMM test case 12.5 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070442 |
| RP-38 | RP-070866 | 2166 | | To add new test case 7.1.1.8 to the LCR TDD MAC ATS | B | 6.4.0 | 6.5.0 | R5s070470 |
| RP-38 | RP-070866 | 2167 | | To add new test case 7.2.3.34 to the LCR TDD RLC ATS | B | 6.4.0 | 6.5.0 | R5s070474 |
| RP-38 | RP-070866 | 2168 | | To add new CC test case 10.1.3.3.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070412 |
| RP-38 | RP-070866 | 2169 | | To add new GMM test case 12.3.1.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070428 |
| RP-38 | RP-070866 | 2170 | | To add new RRC test case 8.1.1.7 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070311 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-38 | RP-070866 | 2171 | | To add new MM test case 9.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070287 |
| RP-38 | RP-070866 | 2172 | | To add new CC test case 10.1.2.4.8 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070388 |
| RP-38 | RP-070866 | 2173 | | To add new GMM test case 12.4.1.1b to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070436 |
| RP-38 | RP-070866 | 2174 | | To add new SM test case 11.3.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070476 |
| RP-38 | RP-070866 | 2175 | | To add new GMM test case 12.3.1.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070430 |
| RP-38 | RP-070866 | 2176 | | To add new test case 16.1.9.2 to the LCR TDD SMS ATS | B | 6.4.0 | 6.5.0 | R5s070458 |
| RP-38 | RP-070866 | 2177 | | To add new CC test case 10.1.2.3.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070376 |
| RP-38 | RP-070866 | 2178 | | To add new CC test case 10.1.2.3.7 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070378 |
| RP-38 | RP-070866 | 2179 | | To add new CC test case 10.1.2.3.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070374 |
| RP-38 | RP-070866 | 2180 | | To add new CC test case 10.1.2.7.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070406 |
| RP-38 | RP-070866 | 2181 | | To add new GMM test case 12.9.4 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070452 |
| RP-38 | RP-070866 | 2182 | | To add new GMM test case 12.9.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070448 |
| RP-38 | RP-070866 | 2183 | | To add new CC test case 10.1.3.3.4 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070416 |
| RP-38 | RP-070866 | 2184 | | To add new RRC test case 8.1.3.3 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070319 |
| RP-38 | RP-070867 | 2185 | | To add new CC test case 10.1.3.3.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070414 |
| RP-38 | RP-070867 | 2186 | | To add new GMM test case 12.4.2.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070438 |
| RP-38 | RP-070867 | 2187 | | To add new CC test case 10.1.2.4.9 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070390 |
| RP-38 | RP-070867 | 2188 | | To add new test case 18.1.2.13.2 to the LCR TDD RAB ATS | B | 6.4.0 | 6.5.0 | R5s070462 |
| RP-38 | RP-070867 | 2189 | | To add new CC test case 10.1.2.4.10 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070392 |
| RP-38 | RP-070867 | 2190 | | To add new CC test case 10.1.2.4.7 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070386 |
| RP-38 | RP-070867 | 2191 | | To add new RRC test case 8.1.3.1 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070317 |
| RP-38 | RP-070867 | 2192 | | To add new CC test case 10.1.2.1.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070289 |
| RP-38 | RP-070867 | 2193 | | To add new CC test case 10.1.2.4.4 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070382 |
| RP-38 | RP-070867 | 2194 | | To add new test case 18.1.2.7 to the LCR TDD RAB ATS | B | 6.4.0 | 6.5.0 | R5s070460 |
| RP-38 | RP-070867 | 2195 | | To add new CC test case 10.1.2.6.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070398 |
| RP-38 | RP-070867 | 2196 | | To add new GMM test case 12.2.1.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070422 |
| RP-38 | RP-070867 | 2197 | | To add new GMM test case 12.9.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070446 |
| RP-38 | RP-070867 | 2198 | | To add new CC test case 10.1.2.5.2 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070394 |
| RP-38 | RP-070867 | 2199 | | To add new CC test case 10.1.2.6.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070400 |
| RP-38 | RP-070867 | 2200 | | To add new CC test case 10.1.2.6.6 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070402 |
| RP-38 | RP-070867 | 2201 | | To add new CC test case 10.1.2.9.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070410 |
| RP-38 | RP-070867 | 2202 | | To add new MM test case 9.5.4 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070364 |
| RP-38 | RP-070867 | 2203 | | To add new CC test case 10.1.2.4.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070380 |
| RP-38 | RP-070867 | 2204 | | To add new CC test case 10.1.2.3.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070372 |
| RP-38 | RP-070868 | 2205 | | To add new CC test case 10.1.2.5.5 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070396 |
| RP-38 | RP-070868 | 2206 | | To add new test case 18.1.2.15 to the LCR TDD RAB ATS | B | 6.4.0 | 6.5.0 | R5s070464 |
| RP-38 | RP-070868 | 2207 | | To add new RRC test case 8.1.1.8 to the LCR TDD | B | 6.4.0 | 6.5.0 | R5s070313 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| | | | | RRC ATS | | | | |
| RP-38 | RP-070868 | 2208 | | To add new GMM test case 12.9.14 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070454 |
| RP-38 | RP-070868 | 2209 | | To add new test case 13.2.2.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070478 |
| RP-38 | RP-070868 | 2210 | | To add new RRC test case 8.2.3.19 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070343 |
| RP-38 | RP-070868 | 2211 | | To add new test case 16.1.2 to the LCR TDD SMS ATS | B | 6.4.0 | 6.5.0 | R5s070456 |
| RP-38 | RP-070868 | 2212 | | To add new CC test case 10.1.2.7.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070404 |
| RP-38 | RP-070868 | 2213 | | To add new GMM test case 12.2.1.7 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070424 |
| RP-38 | RP-070868 | 2214 | | To add new test case 18.1.2.26 to the LCR TDD RAB ATS | B | 6.4.0 | 6.5.0 | R5s070466 |
| RP-38 | RP-070868 | 2215 | | To add new CC test case 10.1.3.5.6 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070420 |
| RP-38 | RP-070868 | 2216 | | To add new test case 7.1.3.1 to the LCR TDD MAC ATS | B | 6.4.0 | 6.5.0 | R5s070472 |
| RP-38 | RP-070868 | 2217 | | To add new GMM test case 12.9.3 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070450 |
| RP-38 | RP-070868 | 2218 | | To add new RRC test case 8.1.2.7 to the LCR TDD RRC ATS | B | 6.4.0 | 6.5.0 | R5s070315 |
| RP-38 | RP-070868 | 2219 | | To add new CC test case 10.1.3.4.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070418 |
| RP-38 | RP-070868 | 2220 | | To add new GMM test case 12.2.2.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070426 |
| RP-38 | RP-070868 | 2221 | | To add new test case 7.1.1.2 to the LCR TDD MAC ATS | B | 6.4.0 | 6.5.0 | R5s070468 |
| RP-38 | RP-070868 | 2222 | | To add new GMM test case 12.3.2.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070434 |
| RP-38 | RP-070868 | 2223 | | To add new GMM test case 12.3.1.5 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070432 |
| RP-38 | RP-070868 | 2224 | | To add new NAS test case 9.3.1 to the LCR TDD NAS ATS | B | 6.4.0 | 6.5.0 | R5s070217 |
| RP-38 | RP-070890 | 2225 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 6.4.0 | 6.5.0 | - |
| RP-38 | RP-070862 | 2226 | | Corrections to GCF WI-10 and Interband RRC testcase 8.2.6.37 and 8.2.6.37b | F | 6.4.0 | 6.5.0 | R5s070357 |
| RP-38 | RP-070861 | 2227 | | Correction to testcase 8.4.1.49 & 8.3.4.10 | F | 6.4.0 | 6.5.0 | R5s070483 |
| RP-38 | RP-070861 | 2228 | | Correction to GCF WI-010 RRC test case 8.3.1.6 | F | 6.4.0 | 6.5.0 | R5s070482 |
| RP-38 | RP-070861 | 2229 | | Handling of A5_1 for UE not supporting GSM. | F | 6.4.0 | 6.5.0 | R5s070484 |
| RP-38 | RP-070862 | 2230 | | TTCN Correction in HSUPA testcases | F | 6.4.0 | 6.5.0 | R5s070276 |
| RP-38 | RP-070861 | 2231 | | Corrections to GCF WI-10 RRC test case 6.1.2.1 | F | 6.4.0 | 6.5.0 | R5s070225 |
| RP-38 | RP-070861 | 2232 | | Introduction of wait timer for RRC Connection Request in preamble | F | 6.4.0 | 6.5.0 | R5s070221 |
| RP-38 | RP-070861 | 2233 | | Correction to GCF WI-013 InterRAT test case 8.3.11.13 | F | 6.4.0 | 6.5.0 | R5s070222 |
| RP-38 | RP-070870 | 2234 | | Corrections to GCF WI-014 WB-AMR test case 14.6.8 | F | 6.4.0 | 6.5.0 | R5s070224 |
| RP-38 | RP-070861 | 2235 | | Corrections to GCF WI-10 IR_U test cases 6.2.1.X, 8.3.7.1, 8.3.7.3 | F | 6.4.0 | 6.5.0 | R5s070219 |
| RP-38 | RP-070861 | 2236 | | Correction to AGPS test cases 17.2.3.2, 17.2.3.3, 17.2.3.4, 17.2.3.8, 17.2.3.9 | F | 6.4.0 | 6.5.0 | R5s070220 |
| RP-38 | RP-070861 | 2237 | | Correction to the RRC test case 8.2.2.43, 8.2.6.39 and 8.2.6.44 | F | 6.4.0 | 6.5.0 | R5s070226 |
| RP-38 | RP-070875 | 2238 | | Addition of GCF WI-25 EDCH RRC test case 8.2.1.36 | B | 6.4.0 | 6.5.0 | R5s070248 |
| RP-38 | RP-070875 | 2239 | | Addition of GCF WI-25 HSUPA test case 8.2.2.44 to HSU ATS v6.3.0 | B | 6.4.0 | 6.5.0 | R5s070245 |
| RP-38 | RP-070875 | 2240 | | Addition of GCF WI-25 EDCH RRC test case 8.2.2.47 | B | 6.4.0 | 6.5.0 | R5s070243 |
| RP-38 | RP-070861 | 2241 | | Wk36 Regression errors in testcase 6.2.1.8 | F | 6.4.0 | 6.5.0 | R5s070257 |
| RP-38 | RP-070861 | 2242 | | Summary of regression errors in wk36 ATS | F | 6.4.0 | 6.5.0 | R5s070255 |
| RP-38 | RP-070875 | 2243 | | Modification of UL and DL max bit rate in QoS for HSPA | F | 6.4.0 | 6.5.0 | R5s070254 |
| RP-38 | RP-070875 | 2244 | | Addition of GCF WI-024 test case 6.2.2.4 to HSU_ENH_r6 ATS V6.3.0. | B | 6.4.0 | 6.5.0 | R5s070227 |
| RP-38 | RP-070875 | 2245 | | Modification of Logical Channel Id for RB25 in multical scenario | F | 6.4.0 | 6.5.0 | R5s070256 |
| RP-38 | RP-070875 | 2246 | | Addition of GCF WI-024 test case 6.2.2.5 to HSU_ENH_r6 ATS V6.3.0. | B | 6.4.0 | 6.5.0 | R5s070235 |
| RP-38 | RP-070861 | 2247 | | Addition of RRC test case 8.2.2.50 | B | 6.4.0 | 6.5.0 | R5s070263 |
| RP-38 | RP-070875 | 2248 | | Asn.1 6d0 patch for the support of F-DPCH Support | F | 6.4.0 | 6.5.0 | R5s070223 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-------------|
| | | | | Indicator | | | | |
| RP-38 | RP-070861 | 2249 | | Summary of regression errors in wk38 ATS | F | 6.4.0 | 6.5.0 | R5s070258 |
| RP-38 | RP-070870 | 2250 | | Correction to GCF WI-14 Test Case 8.2.6.48 | F | 6.4.0 | 6.5.0 | R5s070267 |
| RP-38 | RP-070861 | 2251 | | Corrections to GCF WI-10 RRC test case 6.1.2.1 | F | 6.4.0 | 6.5.0 | R5s070266 |
| RP-38 | RP-070875 | 2252 | | TTCN Correction in GMM testcase 12.9.15 | F | 6.4.0 | 6.5.0 | R5s070269 |
| RP-38 | RP-070861 | 2253 | | TTCN Correction in testcases 9.5.4, 9.5.5, 9.5.7.1 | F | 6.4.0 | 6.5.0 | R5s070268 |
| RP-38 | RP-070875 | 2254 | | Introduce a more strict detection of the usage of RACH TF2 for UL CCCH transmission | F | 6.4.0 | 6.5.0 | R5s070270 |
| RP-38 | RP-070875 | 2255 | | Correction to GCF WI-25 test cases 8.3.1.41 and 8.2.6.50 | F | 6.4.0 | 6.5.0 | R5s070272 |
| RP-38 | RP-070875 | 2256 | | Removal of GSM ciphering algorithm A5/2 | F | 6.4.0 | 6.5.0 | R5s070275 |
| RP-38 | RP-070861 | 2257 | | Correction to RRC testcase 8.4.1.42 | F | 6.4.0 | 6.5.0 | R5s070306 |
| RP-38 | RP-070861 | 2258 | | Correction to GCF Testcase 8.1.2.1, 8.1.2.7, 8.1.2.11, 8.1.5.1, 8.1.5.4, 8.1.7.1, 8.1.7.1b, 8.1.7.1c, 8.1.7.2, 8.1.12 | F | 6.4.0 | 6.5.0 | R5s070279 |
| RP-38 | RP-070861 | 2259 | | Correction to RRC testcase 8.1.10.1 | F | 6.4.0 | 6.5.0 | R5s070305 |
| RP-38 | RP-070861 | 2260 | | Summary of regression errors in wk38 ATS | F | 6.4.0 | 6.5.0 | R5s070271 |
| RP-38 | RP-070861 | 2261 | | Correction to the TTCN to Handle optional Packet Resource Request message | F | 6.4.0 | 6.5.0 | R5s070277 |
| RP-38 | RP-070862 | 2262 | | Summary of regression errors in wk38 ATS | F | 6.4.0 | 6.5.0 | R5s070278 |
| RP-39 | RP-080097 | 2263 | | Update RLP and MBMS RLC test models | F | 6.5.0 | 6.6.0 | R5-080364 |
| RP-39 | RP-080098 | 2264 | | Correction to AT commands used in 3GPP ATSS | F | 6.5.0 | 6.6.0 | R5-080218 |
| RP-39 | RP-080091 | 2265 | | Corrections to the PIXIT items | F | 6.5.0 | 6.6.0 | R5-080269 |
| RP-39 | RP-080098 | 2266 | | Removal of PDF version in formal deliveries | F | 6.5.0 | 6.6.0 | R5-080566 |
| RP-39 | RP-080110 | 2267 | | Introducing Rel-7 test model | F | 6.5.0 | 6.6.0 | R5-080044r3 |
| RP-39 | RP-080090 | 2269 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 6.5.0 | 6.6.0 | - |
| RP-39 | RP-080099 | 2270 | | Summary of regression errors in MBMS wk03 ATS | F | 6.5.0 | 6.6.0 | R5s080013 |
| RP-39 | RP-080092 | 2271 | | Correction to GCF WI-010 RRC test case 8.3.3.1 | F | 6.5.0 | 6.6.0 | R5s080007 |
| RP-39 | RP-080094 | 2272 | | Correction to testcase 7.1.5.6 | F | 6.5.0 | 6.6.0 | R5s080005 |
| RP-39 | RP-080099 | 2273 | | Upgrade RRC asn.1 for tc 8.5.2.1 – UE supporting MBMS service change for a ptp RB | F | 6.5.0 | 6.6.0 | R5s080012 |
| RP-39 | RP-080092 | 2274 | | Summary of regression errors in wk49 ATS | F | 6.5.0 | 6.6.0 | R5s080002 |
| RP-39 | RP-080092 | 2275 | | Correction to PDU definition DTMINFORMATION in IRU ATS | F | 6.5.0 | 6.6.0 | R5s080003 |
| RP-39 | RP-080099 | 2276 | | Correction to SIB5 in MBMS ATS | F | 6.5.0 | 6.6.0 | R5s080006 |
| RP-39 | RP-080099 | 2277 | | Addition of GCF WI 49 MBMS RRC test case 8.5.3.2 | B | 6.5.0 | 6.6.0 | R5s070571 |
| RP-39 | RP-080099 | 2278 | | Addition of GCF WI 49 MBMS RRC test case 8.5.5.2 | B | 6.5.0 | 6.6.0 | R5s070584 |
| RP-39 | RP-080099 | 2279 | | Addition to MBMS RRC test case 8.5.5.1 | B | 6.5.0 | 6.6.0 | R5s070596 |
| RP-39 | RP-080099 | 2280 | | Addition of GCF WI 49 MBMS RRC test case 8.5.5.3 | B | 6.5.0 | 6.6.0 | R5s070586 |
| RP-39 | RP-080099 | 2281 | | Corrections to GCF WI-24 Network Sharing test case 6.2.2.4 | F | 6.5.0 | 6.6.0 | R5s070592 |
| RP-39 | RP-080099 | 2282 | | Addition of RRC test case 6.1.1.9 to HSU_ENH_r6 ATS V6.4.0 | B | 6.5.0 | 6.6.0 | R5s070526 |
| RP-39 | RP-080092 | 2283 | | TTCN Correction in 8.3.1.30 | F | 6.5.0 | 6.6.0 | R5s070593 |
| RP-39 | RP-080099 | 2284 | | Addition of RRC test case 6.1.1.8 to HSU_ENH_r6 ATS V6.4.0 | B | 6.5.0 | 6.6.0 | R5s070524 |
| RP-39 | RP-080092 | 2285 | | Summary of regression errors in wk49 ATS | F | 6.5.0 | 6.6.0 | R5s070562 |
| RP-39 | RP-080092 | 2286 | | Summary of regression errors in wk49 ATS | F | 6.5.0 | 6.6.0 | R5s070600 |
| RP-39 | RP-080099 | 2287 | | Addition of RRC test case 8.3.3.4 to HSU_ENH_r6 ATS | B | 6.5.0 | 6.6.0 | R5s070508 |
| RP-39 | RP-080099 | 2288 | | Addition of GCF WI-25 EDCH RRC test case 8.2.2.49 | B | 6.5.0 | 6.6.0 | R5s070504 |
| RP-39 | RP-080099 | 2289 | | Addition of GCF WI-024 test case 6.2.1.10 to HSU_ENH_r6 ATS V6.5.0. | B | 6.5.0 | 6.6.0 | R5s070273 |
| RP-39 | RP-080099 | 2290 | | Addition to MBMS RRC test case 8.5.5.7 | B | 6.5.0 | 6.6.0 | R5s070598 |
| RP-39 | RP-080099 | 2291 | | Addition of GCF WI 49 MBMS RRC test case 8.5.1.12 | B | 6.5.0 | 6.6.0 | R5s070563 |
| RP-39 | RP-080099 | 2292 | | Addition of GCF WI 49 MBMS RRC test case 8.5.1.2 | B | 6.5.0 | 6.6.0 | R5s070569 |
| RP-39 | RP-080092 | 2293 | | Summary of regression errors in wk49 ATS | F | 6.5.0 | 6.6.0 | R5s070591 |
| RP-39 | RP-080099 | 2294 | | Addition of GCF WI-25 EDCH RRC test case 8.2.1.36a | B | 6.5.0 | 6.6.0 | R5s070594 |
| RP-39 | RP-080099 | 2295 | | Addition of RRC test case 8.1.1.11 to HSU_ENH_r6 ATS | B | 6.5.0 | 6.6.0 | R5s070530 |
| RP-39 | RP-080099 | 2296 | | Addition of GCF WI 49 MBMS NAS test case 12.9.17 | B | 6.5.0 | 6.6.0 | R5s070528 |
| RP-39 | RP-080099 | 2297 | | Addition of GCF WI 49 MBMS RRC test case 8.5.4.1 | B | 6.5.0 | 6.6.0 | R5s070573 |
| RP-39 | RP-080100 | 2298 | | Addition of GCF WI-25 EDCH RRC test case 8.2.6.52 | B | 6.5.0 | 6.6.0 | R5s070522 |
| RP-39 | RP-080100 | 2299 | | Addition of GCF WI 49 MBMS RRC test case 8.5.5.4 | B | 6.5.0 | 6.6.0 | R5s070588 |
| RP-39 | RP-080100 | 2300 | | Addition of GCF WI 49 MBMS RRC test case 8.5.1.13 | B | 6.5.0 | 6.6.0 | R5s070565 |
| RP-39 | RP-080100 | 2301 | | Addition of GCF WI 49 MBMS RRC test case 8.5.1.9 | B | 6.5.0 | 6.6.0 | R5s070582 |
| RP-39 | RP-080100 | 2302 | | Addition of GCF WI-25 EDCH RRC Testcase 8.1.2.18 to HSU_ENH_r6 ATS v6.5.0 | B | 6.5.0 | 6.6.0 | R5s070575 |
| RP-39 | RP-080092 | 2303 | | Summary of regression errors in wk47 ATS | F | 6.5.0 | 6.6.0 | R5s070520 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|---------------------------|
| RP-39 | RP-080100 | 2304 | | Addition of GCF WI 49 MBMS RRC test case 8.5.1.11 | B | 6.5.0 | 6.6.0 | R5s070567 |
| RP-39 | RP-080100 | 2305 | | Addition of GCF WI 49 MBMS RRC test case 8.5.1.3 | B | 6.5.0 | 6.6.0 | R5s070516 |
| RP-39 | RP-080100 | 2306 | | Correction to GCF WI-25 Test Case 8.2.2.47 | F | 6.5.0 | 6.6.0 | R5s070521 |
| RP-39 | RP-080100 | 2307 | | Addition of GCF WI 25 EDCH RRC test case 8.3.1.42a | B | 6.5.0 | 6.6.0 | R5s070510 |
| RP-39 | RP-080100 | 2308 | | Addition of GCF WI-25 EDCH RRC test case 8.3.1.43 | B | 6.5.0 | 6.6.0 | R5s070512 |
| RP-39 | RP-080100 | 2309 | | Addition of GCF WI 25 EDCH RAB test case 14.7.3 | B | 6.5.0 | 6.6.0 | R5s070559 |
| RP-39 | RP-080100 | 2310 | | Addition of GCF WI 25 EDCH RRC test case 8.2.2.47a | B | 6.5.0 | 6.6.0 | R5s070557 |
| RP-39 | RP-080100 | 2311 | | Addition of GCF WI-25 EDCH RRC test case 8.3.1.42 | B | 6.5.0 | 6.6.0 | R5s070499 |
| RP-39 | RP-080094 | 2312 | | TTCN Correction in testcase 8.3.1.34 | F | 6.5.0 | 6.6.0 | R5s070497 |
| RP-39 | RP-080100 | 2313 | | Addition of GCF WI-25 EDCH RRC Testcase 8.1.2.17 to HSU_ENH_r6 ATS v6.4.0 | B | 6.5.0 | 6.6.0 | R5s070514 |
| RP-39 | RP-080100 | 2314 | | Addition of GCF WI 49 MBMS RRC test case 14.4.5 | B | 6.5.0 | 6.6.0 | R5s070518 |
| RP-39 | RP-080100 | 2315 | | Addition of GCF WI-24 Network Sharing test case 6.1.2.11 to HSU_ENH_r6 ATS v6.4.0 | B | 6.5.0 | 6.6.0 | R5s070501 |
| RP-39 | RP-080100 | 2316 | | Addition of GCF WI-25 EDCH RRC test case 8.2.2.44a | B | 6.5.0 | 6.6.0 | R5s070506 |
| RP-39 | RP-080100 | 2317 | | Summary of regression errors in the wk43 InterRAT ATSS. | F | 6.5.0 | 6.6.0 | R5s070486 |
| RP-39 | RP-080092 | 2318 | | TTCN Correction in testcase 8.4.1.42 | F | 6.5.0 | 6.6.0 | R5s070498 |
| RP-39 | RP-080092 | 2319 | | Correction to the TTCN to update ASP G_CL1_ComingFN_REQ | F | 6.5.0 | 6.6.0 | R5s070496 |
| RP-39 | RP-080092 | 2320 | | Summary of regression errors in wk43 ATS | F | 6.5.0 | 6.6.0 | R5s070280 |
| RP-39 | RP-080100 | 2321 | | Corrections to GCF WI-24 Network Sharing test case 6.2.2.4 | F | 6.5.0 | 6.6.0 | R5s070494 |
| RP-39 | RP-080092 | 2322 | | Summary of regression errors in wk43 ATS | F | 6.5.0 | 6.6.0 | R5s070495 |
| RP-39 | RP-080092 | 2323 | | Correction to testcase 8.2.6.37, 8.2.6.37b & 8.3.4.3 | F | 6.5.0 | 6.6.0 | R5s070485 |
| RP-39 | RP-080100 | 2324 | | Addition of MBMS RAB test case 14.4.7 | B | 6.5.0 | 6.6.0 | R5s070233 |
| RP-39 | RP-080101 | 2325 | | Addition of MBMS RAB test case 14.4.6 | B | 6.5.0 | 6.6.0 | R5s070241 |
| RP-39 | RP-080101 | 2326 | | Addition of MBMS RRC test case 8.5.1.5 | B | 6.5.0 | 6.6.0 | R5s070252 |
| RP-39 | RP-080101 | 2327 | | Addition of MBMS RRC test case 8.5.1.4 | B | 6.5.0 | 6.6.0 | R5s070250 |
| RP-39 | RP-080101 | 2328 | | Addition of MBMS RRC test case 8_5_4_3 | B | 6.5.0 | 6.6.0 | R5s080010 |
| RP-39 | RP-080101 | 2329 | | Addition of GCF WI 49 RRC MBMS test case 8.5.2.2 | B | 6.5.0 | 6.6.0 | R5s080008 |
| RP-39 | RP-080092 | 2330 | | Summary of regression errors in wk03 ATS | F | 6.5.0 | 6.6.0 | R5s080035 |
| RP-39 | RP-080092 | 2331 | | Correction to GCF WI-10 RRC Testcase 8.4.1.42 | F | 6.5.0 | 6.6.0 | R5s080023 |
| RP-39 | RP-080101 | 2332 | | Addition of GCF WI 25 HSUPA RAB test case 14.7.7 | B | 6.5.0 | 6.6.0 | R5s080033 |
| RP-39 | RP-080101 | 2333 | | Addition of GCF WI 25 HSUPA RAB test case 14.7.6 | B | 6.5.0 | 6.6.0 | R5s080031 |
| RP-39 | RP-080092 | 2334 | | TTCN Correction in testcase 8.1.1.9 | F | 6.5.0 | 6.6.0 | R5s080028 |
| RP-39 | RP-080094 | 2335 | | TTCN Correction in testcase 8.1.6.5 | F | 6.5.0 | 6.6.0 | R5s080024 |
| RP-39 | RP-080092 | 2336 | | Correction to testcase 8.4.1.42 | F | 6.5.0 | 6.6.0 | R5s080027 |
| RP-39 | RP-080092 | 2337 | | Correction to testcase 8.3.4.1 & 8.3.4.2 | F | 6.5.0 | 6.6.0 | R5s080026 |
| RP-39 | RP-080092 | 2338 | | Correction to Interband Testcase 8.3.1.1a | F | 6.5.0 | 6.6.0 | R5s080022 |
| RP-39 | RP-080092 | 2339 | | Correction to testcase 12.4.1.4c2 | F | 6.5.0 | 6.6.0 | R5s080025 |
| RP-39 | RP-080098 | 2268 | | Production of pointer version 6.6.0 of TS 34.123-3 with no technical contents | F | 6.5.0 | 6.6.0 | R5-080554 |
| RP-39 | | | | Upgraded to Rel-7 without technical change (on request of RAN5) | | 6.6.0 | 7.0.0 | |
| RP-40 | RP-080430 | 2381 | | ASP corrections for Rel-7 test model | | 7.0.0 | 7.1.0 | R5-081510 |
| RP-40 | RP-080429 | 2382 | | ASP improvement when configuring MICH and PICH | | 7.0.0 | 7.1.0 | R5-081523 |
| RP-40 | RP-080363 | 2383 | | R99 TSO routine maintenance | | 7.0.0 | 7.1.0 | R5-081058 |
| RP-40 | RP-080430 | 2384 | | PIXIT for UE LCS Notification timeout timer added | | 7.0.0 | 7.1.0 | R5-081571 |
| RP-40 | RP-080370 | 2385 | | Guidance of test execution when Introducing Operating Bands XII, XIII and XIV | | 7.0.0 | 7.1.0 | R5-081536 |
| RP-40 | RP-080366 | 2340 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | | 7.0.0 | 7.1.0 | - |
| RP-40 | RP-080367 | 2341 | | Addition of GCF WI 49 RRC MBMS test case 8.5.2.3 | | 7.0.0 | 7.1.0 | R5s080016 |
| RP-40 | RP-080367 | 2342 | | Addition of GCF WI 49 MBMS RRC test case 8.5.5.8 | | 7.0.0 | 7.1.0 | R5s080018 |
| RP-40 | RP-080367 | 2343 | | Addition of GCF WI 49 MBMS test case 7.2.4.2 | | 7.0.0 | 7.1.0 | R5s080020 |
| RP-40 | RP-080367 | 2344 | | Addition to MBMS RLC test case 7.2.4.3 | | 7.0.0 | 7.1.0 | R5s080029 |
| RP-40 | RP-080367 | 2345 | | Addition of GCF WI 49 MBMS RRC test case 8.5.4.2 | | 7.0.0 | 7.1.0 | R5s080038 |
| RP-40 | RP-080367 | 2346 | | Addition of GCF WI 49 RRC MBMS test case 12.9.16 | | 7.0.0 | 7.1.0 | R5s080041 |
| RP-40 | RP-080367 | 2347 | | Addition of GCF WI 49 MBMS RRC test case 8.5.3.1 | | 7.0.0 | 7.1.0 | R5s080043 |
| RP-40 | RP-080367 | 2348 | | Addition of GCF WI 24 RRC test case 8.1.1.6a | | 7.0.0 | 7.1.0 | R5s080050 |
| RP-40 | RP-080367 | 2349 | | Addition of InterRAT test case 8.3.7.1a | | 7.0.0 | 7.1.0 | R5s080053 |
| RP-40 | RP-080367 | 2350 | | Addition of GCF WI-49-MBMS RRC test case 8.5.6.1 | | 7.0.0 | 7.1.0 | R5s080047 |
| RP-40 | RP-080367 | 2351 | | Addition of E-DCH MAC test case 7.1.6.4.1 to HSU_ENH_r6 ATS | | 7.0.0 | 7.1.0 | R5s080060 |
| RP-40 | RP-080367 | 2352 | | Addition of GCF WI 49 MBMS NAS test case 11.8.2 | | 7.0.0 | 7.1.0 | R5s080065 |
| RP-40 | RP-080367 | 2353 | | Addition of GCF WI 49 RRC MBMS test case 8.5.3.3 | | 7.0.0 | 7.1.0 | R5s080080 |
| RP-40 | RP-080367 | 2354 | | Addition of GCF WI 49 MBMS RRC test case 8.5.2.4 | | 7.0.0 | 7.1.0 | R5s080083 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-40 | RP-080367 | 2355 | | Addition of MBMS RAB test case 14.6.10 | | 7.0.0 | 7.1.0 | R5s080088 |
| RP-40 | RP-080367 | 2356 | | Addition of MBMS RAB test case 14.6.9 and 14.6.10 | | 7.0.0 | 7.1.0 | R5s080086 |
| RP-40 | RP-080367 | 2357 | | Correction to Selection Expression for test cases 16.1.9.1 and 16.1.9.2 | | 7.0.0 | 7.1.0 | R5s080037 |
| RP-40 | RP-080367 | 2358 | | Correction to Testcase selection expressions of 8.1.7.1c, 8.2.6.39, 8.2.6.44, 8.3.1.25, 8.3.1.30, 8.2.3.36 | | 7.0.0 | 7.1.0 | R5s080040 |
| RP-40 | RP-080367 | 2359 | | Correction to GCF WI-14 HSDPA RRC Testcase 8.2.2.42 | | 7.0.0 | 7.1.0 | R5s080045 |
| RP-40 | RP-080367 | 2360 | | Correction to GCF WI-14 HSDPA RRC Testcase 8.2.3.33 | | 7.0.0 | 7.1.0 | R5s080046 |
| RP-40 | RP-080368 | 2361 | | TTCN Correction in testcases 8.1.1.7, 8.1.1.8, 8.1.1.10 | | 7.0.0 | 7.1.0 | R5s080049 |
| RP-40 | RP-080368 | 2362 | | Correction to Rel-5 RAB test cases | | 7.0.0 | 7.1.0 | R5s080052 |
| RP-40 | RP-080368 | 2363 | | Summary of regression errors in wk07 ATS | | 7.0.0 | 7.1.0 | R5s080055 |
| RP-40 | RP-080368 | 2364 | | Correction to GCF WI-49 MBMS RRC test case 8.5.1.5 | | 7.0.0 | 7.1.0 | R5s080057 |
| RP-40 | RP-080368 | 2365 | | Summary of regression errors in wk07 MBMS ATS | | 7.0.0 | 7.1.0 | R5s080058 |
| RP-40 | RP-080368 | 2366 | | Correction to E-DCH RRC testcase 8.2.6.52 | | 7.0.0 | 7.1.0 | R5s080059 |
| RP-40 | RP-080368 | 2367 | | Summary of regression errors in MBMS wk10 ATS | | 7.0.0 | 7.1.0 | R5s080064 |
| RP-40 | RP-080368 | 2368 | | Summary of regression errors in wk10 ATS | | 7.0.0 | 7.1.0 | R5s080062 |
| RP-40 | RP-080368 | 2369 | | Correction of UE radio access capability extension | | 7.0.0 | 7.1.0 | R5s080070 |
| RP-40 | RP-080368 | 2370 | | Summary of regression errors in 08wk10 MBMS ATS | | 7.0.0 | 7.1.0 | R5s080071 |
| RP-40 | RP-080368 | 2371 | | Correction to Selection Expression for test cases 9.4.5.2, 9.5.2, 9.5.4, 9.5.5 and 9.5.7.1 | | 7.0.0 | 7.1.0 | R5s080075 |
| RP-40 | RP-080368 | 2372 | | ASP update for Explicit TFC restriction | | 7.0.0 | 7.1.0 | R5s080068 |
| RP-40 | RP-080368 | 2373 | | Correction to RAB test cases | | 7.0.0 | 7.1.0 | R5s080056 |
| RP-40 | RP-080368 | 2374 | | Correction of handling of Structured Type- and Tabular Pdu types constraints in all 3GPP UMTS ATSS. | | 7.0.0 | 7.1.0 | R5s080069 |
| RP-40 | RP-080368 | 2375 | | Configuration of associated physical channels. | | 7.0.0 | 7.1.0 | R5s080074 |
| RP-40 | RP-080368 | 2376 | | Correction to MICH configuration. | | 7.0.0 | 7.1.0 | R5s080076 |
| RP-40 | RP-080368 | 2377 | | Summary of regression errors in D08wk10 for GCF WI-025 | | 7.0.0 | 7.1.0 | R5s080082 |
| RP-40 | RP-080368 | 2378 | | Baseline upgrade to March-08 Rel-7 | | 7.0.0 | 7.1.0 | R5s080067 |
| RP-40 | RP-080368 | 2379 | | Correction to GCF WI-49 MBMS RRC test case 7.2.4.3 | | 7.0.0 | 7.1.0 | R5s080090 |
| RP-40 | RP-080368 | 2380 | | Correction to SMS test cases 16.2.1 and 16.2.2 | | 7.0.0 | 7.1.0 | R5s080079 |
| RP-41 | RP-080613 | 2386 | - | Documentation of TTCN routine maintenance | F | 7.1.0 | 7.2.0 | R5-083585 |
| RP-41 | RP-080613 | 2387 | - | ASP corrections for Rel-7 | F | 7.1.0 | 7.2.0 | R5-083637 |
| RP-41 | RP-080653 | 2388 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 7.1.0 | 7.2.0 | - |
| RP-41 | RP-080613 | 2389 | | Correction to the HSDPA RRC testcase 8.2.1.29, 8.2.1.31 and 8.2.1.32 | F | 7.1.0 | 7.2.0 | R5s080102 |
| RP-41 | RP-080613 | 2390 | | Summary of regression errors in wk17 ATS | F | 7.1.0 | 7.2.0 | R5s080092 |
| RP-41 | RP-080613 | 2391 | - | Correction to Selection Expression for test case 12.3.1.5 | F | 7.1.0 | 7.2.0 | R5s080103 |
| RP-41 | RP-080613 | 2392 | - | Correction to RRC test case 8.3.2.1a | F | 7.1.0 | 7.2.0 | R5s080094 |
| RP-41 | RP-080613 | 2393 | - | Correction to RAB "Combinations on SCCPCH" Test Cases | F | 7.1.0 | 7.2.0 | R5s080099 |
| RP-41 | RP-080613 | 2394 | - | Regression CR for Wk16 on IR_U Test cases | F | 7.1.0 | 7.2.0 | R5s080091 |
| RP-41 | RP-080613 | 2395 | - | Correction to the IR_U test case 6.2.2.3 | F | 7.1.0 | 7.2.0 | R5s080097 |
| RP-41 | RP-080613 | 2396 | - | Correction to the RRC testcase 8.3.1.18 | F | 7.1.0 | 7.2.0 | R5s080095 |
| RP-41 | RP-080613 | 2397 | - | Correction to RLP implementation in wk17 ATS. | F | 7.1.0 | 7.2.0 | R5s080098 |
| RP-41 | RP-080613 | 2398 | - | Corrections to GCF WI-010 RRC test cases 8_1_7_1 | F | 7.1.0 | 7.2.0 | R5s080100 |
| RP-41 | RP-080613 | 2399 | - | Upgrade RRC asn.1 for Rel-7 | F | 7.1.0 | 7.2.0 | R5s080093 |
| RP-41 | RP-080613 | 2400 | - | Correction to test cases 8.3.1.34, 8.3.1.35, 8.3.1.36 and 8.3.1.37 | F | 7.1.0 | 7.2.0 | R5s080104 |
| RP-41 | RP-080613 | 2401 | - | Correction to GCF testcase 8.4.1.2 | F | 7.1.0 | 7.2.0 | R5s080072 |
| RP-41 | RP-080613 | 2402 | - | Addition of GCF WI-24 Network Sharing test case 6.2.1.11 to HSU_ENH_r6 ATS v7.0.0 | F | 7.1.0 | 7.2.0 | R5s080077 |
| RP-41 | RP-080613 | 2403 | - | TTCN Correction in test cases 8.1.1.7, 8.1.1.8, 8.1.1.10, 8.1.2.16 | F | 7.1.0 | 7.2.0 | R5s080105 |
| RP-41 | RP-080613 | 2404 | - | Correction to HSUPA RRC Test case 8.3.1.42a | F | 7.1.0 | 7.2.0 | R5s080108 |
| RP-41 | RP-080613 | 2405 | - | Summary of regression errors in wk21 ATS | F | 7.1.0 | 7.2.0 | R5s080110 |
| RP-41 | RP-080613 | 2406 | - | Addition of GCF WI-025 EDCH MAC test case 7.1.6.2.5 to HSU_ENH_r6 ATS v7.0.0 | F | 7.1.0 | 7.2.0 | R5s080106 |
| RP-41 | RP-080613 | 2407 | - | Renaming of test suite parameter pc_MS_ClsmkA5_3 to pc_MS_ClsmkA5_3_Boot | F | 7.1.0 | 7.2.0 | R5s080112 |
| RP-41 | RP-080613 | 2408 | - | Correction to E-DCH GCF WI-25 test case 8.2.2.45 | F | 7.1.0 | 7.2.0 | R5s080113 |
| RP-41 | RP-080614 | 2409 | - | Correction to GCF WI-10 RAB test cases | F | 7.1.0 | 7.2.0 | R5s080118 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-41 | RP-080614 | 2410 | - | Correction to common test steps used in HSD ATS | F | 7.1.0 | 7.2.0 | R5s080129 |
| RP-41 | RP-080614 | 2411 | - | Addition of GCF WI-068 Enhanced Layer2 MAC-ehs test case 7.1.5a.3 to HS_ENH_r7 ATS v7.1.0 | F | 7.1.0 | 7.2.0 | R5s080126 |
| RP-41 | RP-080614 | 2412 | - | Addition of GCF WI-068 Enhanced Layer2 MAC-ehs test case 7.1.5a.2 to HS_ENH_r7 ATS v7.1.0 | F | 7.1.0 | 7.2.0 | R5s080124 |
| RP-41 | RP-080614 | 2413 | - | Addition of GCF WI-068 Enhanced Layer2 MAC-ehs test case 7.1.5a.1 to HS_ENH_r7 ATS v7.1.0 | F | 7.1.0 | 7.2.0 | R5s080122 |
| RP-41 | RP-080614 | 2414 | - | Correction to testcase 8.2.2.18 | F | 7.1.0 | 7.2.0 | R5s080132 |
| RP-41 | RP-080614 | 2415 | - | Correction to RLP handling in default procedures | F | 7.1.0 | 7.2.0 | R5s080133 |
| RP-41 | RP-080614 | 2416 | - | Corrections to GCF WI-024 Network Sharing test case 6.2.1.11 | F | 7.1.0 | 7.2.0 | R5s080131 |
| RP-41 | RP-080614 | 2417 | - | Correction to the definition of the structure "SI6RO". | F | 7.1.0 | 7.2.0 | R5s080128 |
| RP-41 | RP-080614 | 2418 | - | ASP update for Rel-7 test model | F | 7.1.0 | 7.2.0 | R5s080121 |
| RP-41 | RP-080614 | 2419 | - | Correction of Traffic Volume Measurement Procedure for GCF WI-010 RRC TCs | F | 7.1.0 | 7.2.0 | R5s080120 |
| RP-41 | RP-080614 | 2420 | - | TTCN Correction in test case 8.2.2.43 | F | 7.1.0 | 7.2.0 | R5s080141 |
| RP-41 | RP-080614 | 2421 | - | Correction to Test cases tc_16_1_1,tc_16_1_2,tc_16_1_9_2,tc_9_5_7_2,tc_10_1_2_6_6,tc_10_1_2_7_1,tc_10_1_2_7_2,tc_10_1_2_7_3 | F | 7.1.0 | 7.2.0 | R5s080136 |
| RP-41 | RP-080614 | 2422 | - | TTCN Correction in test case 8.1.1.11 | F | 7.1.0 | 7.2.0 | R5s080140 |
| RP-41 | RP-080614 | 2423 | - | Addition of GCF Enhanced Layer2 MAC-ehs test case 7.1.5a.4 to HS_ENH_r7 ATS v7.1.0 | F | 7.1.0 | 7.2.0 | R5s080134 |
| RP-41 | RP-080614 | 2424 | - | Summary of regression errors in wk27 ATS | F | 7.1.0 | 7.2.0 | R5s080142 |
| RP-41 | RP-080614 | 2425 | - | Correction to Test cases tc_8_3_7_2 and tc_8_3_7_3 | F | 7.1.0 | 7.2.0 | R5s080147 |
| RP-41 | RP-080614 | 2426 | - | Correction to TTCN for the RRC test cases 8.1.3.9, 8.2.6.37, 8.2.6.37b | F | 7.1.0 | 7.2.0 | R5s080149 |
| RP-41 | RP-080614 | 2427 | - | Correction to HSUPA test case 14.7.6 and 14.7.7 | F | 7.1.0 | 7.2.0 | R5s080150 |
| RP-42 | RP-080960 | 2428 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 7.2.0 | 7.3.0 | - |
| RP-42 | RP-080957 | 2429 | - | Summary of regression errors in MBMS wk21 ATS | F | 7.2.0 | 7.3.0 | R5s080111 |
| RP-42 | RP-080957 | 2430 | - | Correction to GCF WI 10 and WI 14 RRC test cases | F | 7.2.0 | 7.3.0 | R5s080156 |
| RP-42 | RP-080957 | 2431 | - | Summary of regression errors in wk27 ATSS | F | 7.2.0 | 7.3.0 | R5s080154 |
| RP-42 | RP-080957 | 2432 | - | Correction to RRC test case 8.4.1.2 | F | 7.2.0 | 7.3.0 | R5s080155 |
| RP-42 | RP-080957 | 2433 | - | Correction to RAB R5 test cases | F | 7.2.0 | 7.3.0 | R5s080153 |
| RP-42 | RP-080957 | 2434 | - | Correction to the test step ts_TestPointExecute_Rb25 | F | 7.2.0 | 7.3.0 | R5s080157 |
| RP-42 | RP-080957 | 2435 | - | Correction to Rel-7 MAC test case 7.1.5a.4 | F | 7.2.0 | 7.3.0 | R5s080159 |
| RP-42 | RP-080957 | 2436 | - | Correction to Rel-7 MAC test cases 7.1.5a.1 and 7.1.5a.2 | F | 7.2.0 | 7.3.0 | R5s080160 |
| RP-42 | RP-080957 | 2437 | - | Correction to RAB Test cases | F | 7.2.0 | 7.3.0 | R5s080158 |
| RP-42 | RP-080957 | 2438 | - | Addition of GCF WI-025 HSUPA testcase 7.1.6.2.6 to HSU_ENH_r6 ATS v7.1.0 | B | 7.2.0 | 7.3.0 | R5s080161 |
| RP-42 | RP-080957 | 2439 | - | Summary of regression errors in wk36 ATS | F | 7.2.0 | 7.3.0 | R5s080163 |
| RP-42 | RP-080957 | 2440 | - | Correction to testcase 14.7.6 & 14.7.7 | F | 7.2.0 | 7.3.0 | R5s080166 |
| RP-42 | RP-080957 | 2441 | - | Correction to testcase 8.4.1.27 | F | 7.2.0 | 7.3.0 | R5s080164 |
| RP-42 | RP-080957 | 2442 | - | Summary of regression errors in wk36 ATS | F | 7.2.0 | 7.3.0 | R5s080173 |
| RP-42 | RP-080957 | 2443 | - | TTCN Correction in test cases 8.2.6.39,8.2.6.44,8.3.1.25 and 8.3.1.30 | F | 7.2.0 | 7.3.0 | R5s080170 |
| RP-42 | RP-080957 | 2444 | - | Correction to GCF WI-10 IR_U Testcase 8.3.9.1 | F | 7.2.0 | 7.3.0 | R5s080172 |
| RP-42 | RP-080957 | 2445 | - | Correction to GCF WI 25 HSUPA MAC test case 7.1.6.2.9 | F | 7.2.0 | 7.3.0 | R5s080169 |
| RP-42 | RP-080957 | 2446 | - | Addition of Rel7 CPC RRC testcase 8.2.1.38 to HS_ENH_r6 ATS v7.1.0 | B | 7.2.0 | 7.3.0 | R5s080174 |
| RP-42 | RP-080957 | 2447 | - | Addition of Rel7 CPC RRC testcase 8.1.2.19 to HS_ENH_r7 ATS v7.2.0 | B | 7.2.0 | 7.3.0 | R5s080178 |
| RP-42 | RP-080957 | 2448 | - | Correction to GCF WI 25 HSUPA RRC test cases | F | 7.2.0 | 7.3.0 | R5s080181 |
| RP-42 | RP-080958 | 2449 | - | Correction to No. of HARQ Process in RAB test cases for HSDPA CAT 10 UE | F | 7.2.0 | 7.3.0 | R5s080183 |
| RP-42 | RP-080958 | 2450 | - | Correction in the preamble test step ts_GMM_IdleUpdated to include USIM insertion related MMI command. | F | 7.2.0 | 7.3.0 | R5s080184 |
| RP-42 | RP-080958 | 2451 | - | Correction to RRC test cases for RLP | F | 7.2.0 | 7.3.0 | R5s080182 |
| RP-42 | RP-080958 | 2452 | - | Addition of Rel7 CPC RRC testcase 8.2.2.56 to HS_ENH_r7 ATS v7.2.0 | B | 7.2.0 | 7.3.0 | R5s080176 |
| RP-42 | RP-080958 | 2453 | - | TTCN Correction to Test case tc_8_4_1_42 | F | 7.2.0 | 7.3.0 | R5s080185 |
| RP-42 | RP-080958 | 2454 | - | TTCN Correction to Test cases tc_8_2_6_39 and tc_8_2_6_44 | F | 7.2.0 | 7.3.0 | R5s080180 |
| RP-42 | RP-080958 | 2455 | - | Correction to the test step used to send CLOSE UE TEST LOOP in MBMS testcases | F | 7.2.0 | 7.3.0 | R5s080287 |
| RP-42 | RP-080958 | 2456 | - | Correction to GCF WI 14 HSDPA RRC test case 8.3.1.34 | F | 7.2.0 | 7.3.0 | R5s080290 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-42 | RP-080958 | 2457 | - | Addition of Rel7 CPC RRC InterRAT testcase 8.3.11.15 to HS_ENH_r7 ATS v7.2.0 | B | 7.2.0 | 7.3.0 | R5s080291 |
| RP-42 | RP-080958 | 2458 | - | Addition of Rel7 CPC RRC testcase 8.2.2.54 to HS_ENH_r7 ATS v7.2.0 | B | 7.2.0 | 7.3.0 | R5s080295 |
| RP-42 | RP-080958 | 2459 | - | Correction to the CPC testcase 8.2.1.38 | F | 7.2.0 | 7.3.0 | R5s080297 |
| RP-42 | RP-080958 | 2460 | - | Correction to the CPC testcase 8.1.2.19 | F | 7.2.0 | 7.3.0 | R5s080298 |
| RP-42 | RP-080958 | 2461 | - | Addition of Rel7 CPC RRC testcase 8.2.2.52 to HS_ENH_r7 ATS v7.2.0 | B | 7.2.0 | 7.3.0 | R5s080288 |
| RP-42 | RP-080958 | 2462 | - | New PIXIT for RAB test cases execution | F | 7.2.0 | 7.3.0 | R5-085056 |
| RP-42 | RP-080958 | 2463 | - | Rel-7 test model enhancement for LCR TDD | F | 7.2.0 | 7.3.0 | R5-085436 |
| RP-42 | RP-080958 | 2464 | - | Rel-7 test model routine maintenance | F | 7.2.0 | 7.3.0 | R5-085437 |
| RP-42 | RP-081067 | 2465 | | To add new RAB test case 18.1.2.13.1 to the LCR TDD RAB ATS | B | 7.2.0 | 7.3.0 | R5s080232 |
| RP-42 | RP-081067 | 2466 | | To add new HSD_ENH test case 8.3.1.37 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080284 |
| RP-42 | RP-081067 | 2467 | | To add new HSD_ENH test case 8.3.1.36 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080282 |
| RP-42 | RP-081067 | 2468 | | To add new HSD_ENH test case 8.3.1.35 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080280 |
| RP-42 | RP-081067 | 2469 | | To add new HSD_ENH test case 8.3.1.34 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080278 |
| RP-42 | RP-081067 | 2470 | | To add new HSD_ENH test case 8.3.1.32 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080276 |
| RP-42 | RP-081067 | 2471 | | To add new HSD_ENH test case 8.2.6.49 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080274 |
| RP-42 | RP-081067 | 2472 | | To add new HSD_ENH test case 8.2.6.46 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080272 |
| RP-42 | RP-081067 | 2473 | | To add new HSD_ENH test case 8.2.6.42 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080270 |
| RP-42 | RP-081067 | 2474 | | To add new HSD_ENH test case 8.2.6.40a to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080268 |
| RP-42 | RP-081067 | 2475 | | To add new HSD_ENH test case 8.2.6.39b to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080266 |
| RP-42 | RP-081067 | 2476 | | To add new HSD_ENH test case 8.2.3.35 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080264 |
| RP-42 | RP-081067 | 2477 | | To add new HSD_ENH test case 8.2.3.34 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080262 |
| RP-42 | RP-081067 | 2478 | | To add new HSD_ENH test case 8.2.3.33 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080260 |
| RP-42 | RP-081067 | 2479 | | To add new HSD_ENH test case 8.2.3.32 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080258 |
| RP-42 | RP-081067 | 2480 | | To add new HSD_ENH test case 8.2.3.30 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080256 |
| RP-42 | RP-081067 | 2481 | | To add new HSD_ENH test case 8.2.2.42 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080254 |
| RP-42 | RP-081067 | 2482 | | To add new HSD_ENH test case 8.2.2.41 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080252 |
| RP-42 | RP-081067 | 2483 | | To add new HSD_ENH test case 8.2.2.40 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080250 |
| RP-42 | RP-081067 | 2484 | | To add new HSD_ENH test case 8.2.2.39 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080248 |
| RP-42 | RP-081067 | 2485 | | To add new HSD_ENH test case 8.2.2.38 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080246 |
| RP-42 | RP-081067 | 2486 | | To add new HSD_ENH test case 8.2.1.32 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080244 |
| RP-42 | RP-081067 | 2487 | | To add new HSD_ENH test case 8.2.1.31 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080242 |
| RP-42 | RP-081067 | 2488 | | To add new HSD_ENH test case 8.2.1.30 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080240 |
| RP-42 | RP-081067 | 2489 | | To add new HSD_ENH test case 8.2.1.29 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080238 |
| RP-42 | RP-081068 | 2490 | | To add new HSD_ENH test case 8.2.1.28 to the LCR TDD HSD_ENH ATS | B | 7.2.0 | 7.3.0 | R5s080236 |
| RP-42 | RP-081068 | 2491 | | To add new RAB test case 18.1.2.27 to the LCR TDD RAB ATS | B | 7.2.0 | 7.3.0 | R5s080234 |
| RP-42 | RP-081068 | 2492 | | To add new NAS test case 12.9.9 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080230 |
| RP-42 | RP-081068 | 2493 | | To add new NAS test case 12.9.8 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080228 |
| RP-42 | RP-081068 | 2494 | | To add new NAS test case 12.6.1.3.2 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080226 |
| RP-42 | RP-081068 | 2495 | | To add new NAS test case 12.6.1.3.1 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080224 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-42 | RP-081068 | 2496 | | To add new NAS test case 12.6.1.2 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080222 |
| RP-42 | RP-081068 | 2497 | | To add new NAS test case 12.6.1.1 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080220 |
| RP-42 | RP-081068 | 2498 | | To add new NAS test case 12.2.1.6.2 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080218 |
| RP-42 | RP-081068 | 2499 | | To add new NAS test case 12.2.1.6.1 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080216 |
| RP-42 | RP-081068 | 2500 | | To add new NAS test case 12.2.1.5a.2 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080214 |
| RP-42 | RP-081068 | 2501 | | To add new NAS test case 11.3.2 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080212 |
| RP-42 | RP-081068 | 2502 | | To add new NAS test case 9.5.5 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080210 |
| RP-42 | RP-081068 | 2503 | | To add new NAS test case 9.2.4 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080206 |
| RP-42 | RP-081068 | 2504 | | To add new NAS test case 9.2.3 to the LCR TDD NAS ATS | B | 7.2.0 | 7.3.0 | R5s080204 |
| RP-42 | RP-081068 | 2505 | | To add new RRC test case 8.2.2.7 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080202 |
| RP-42 | RP-081068 | 2506 | | To add new RRC test case 8.2.2.4 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080200 |
| RP-42 | RP-081068 | 2507 | | To add new RRC test case 8.2.1.24 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080198 |
| RP-42 | RP-081068 | 2508 | | To add new RRC test case 8.2.1.10 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080196 |
| RP-42 | RP-081068 | 2509 | | To add new RRC test case 8.2.1.7 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080194 |
| RP-42 | RP-081068 | 2510 | | To add new RRC test case 8.2.1.4 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080192 |
| RP-42 | RP-081068 | 2511 | | To add new RRC test case 8.2.1.1 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080190 |
| RP-42 | RP-081068 | 2512 | | To add new RRC test case 8.1.6.1 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080188 |
| RP-42 | RP-081068 | 2513 | | To add new RRC test case 8.1.2.9 to the LCR TDD RRC ATS | B | 7.2.0 | 7.3.0 | R5s080186 |
| SP-42 | - | | | Update of TS 34.123-3 from Rel-7 to Rel-8 | | 7.3.0 | 8.0.0 | - |
| RP-43 | RP-090205 | 2514 | | Update of TS 34.123-3 from Rel-7 to Rel-8 | F | 8.0.0 | 8.1.0 | R5-090767 |
| RP-43 | RP-090206 | 2515 | | Correction to Rel-7 CPC test cases 8.3.1.44 | F | 8.0.0 | 8.1.0 | R5s090016 |
| RP-43 | RP-090206 | 2516 | | Correction of GCF WI-068 Improved L2 Flexible RLC AM test case 7.2.3.36 | F | 8.0.0 | 8.1.0 | R5s090008 |
| RP-43 | RP-090206 | 2517 | | Addition of GCF WI-070 CPC RRC testcase 8.2.6.61 to HS_ENH_r7 ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s090002 |
| RP-43 | RP-090206 | 2518 | | Correction to the GCF WI 25 HSUPA RRC test case 8.2.6.52 | F | 8.0.0 | 8.1.0 | R5s090001 |
| RP-43 | RP-090206 | 2519 | | Correction to RRC test cases 8.2.6.39 and 8.2.6.44 | F | 8.0.0 | 8.1.0 | R5s090015 |
| RP-43 | RP-090206 | 2520 | | Addition of GCF WI-068 RAB test case 14.6.1b to HS_ENH_r7 ATS | B | 8.0.0 | 8.1.0 | R5s090009 |
| RP-43 | RP-090206 | 2521 | | Summary of Regressions Error for HS_ENH_r7 wk50 | F | 8.0.0 | 8.1.0 | R5s090011 |
| RP-43 | RP-090206 | 2522 | | Addition of GCF WI 70 CPC RRC test case 8.2.6.59 | B | 8.0.0 | 8.1.0 | R5s090006 |
| RP-43 | RP-090206 | 2523 | | Correction to Rel-7 CPC testcase 8.3.1.46 | F | 8.0.0 | 8.1.0 | R5s090013 |
| RP-43 | RP-090206 | 2524 | | Correction to GCF WI-24 HSU_ENH Testcase 6.2.1.11 | F | 8.0.0 | 8.1.0 | R5s090012 |
| RP-43 | RP-090206 | 2525 | | Addition of GCF WI 70 CPC RRC test case 8.3.1.46 | B | 8.0.0 | 8.1.0 | R5s080328 |
| RP-43 | RP-090206 | 2526 | | Corrections to HS-ENH-R7 wk48 ATS | F | 8.0.0 | 8.1.0 | R5s080323 |
| RP-43 | RP-090206 | 2527 | | Addition of GCF WI-068 Improved L2 Flexible RLC AM test case 7.2.3.36 to HS_ENH_r7ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s080311 |
| RP-43 | RP-090206 | 2528 | | Addition of Rel7 Improved L2 Flexible RLC UM testcase 7.2.2.14 to HS_ENH_r7 ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s080309 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-43 | RP-090206 | 2529 | | Correction to the test case 8.3.1.40 | F | 8.0.0 | 8.1.0 | R5s080325 |
| RP-43 | RP-090206 | 2530 | | Addition of HSDPA SM test case 11.1.1.1a | B | 8.0.0 | 8.1.0 | R5s080326 |
| RP-43 | RP-090206 | 2531 | | Addition of Rel7 CPC RRC testcase 8.2.6.57 to HS_ENH_r7 ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s080319 |
| RP-43 | RP-090206 | 2532 | | Addition of GCF WI-070 CPC RRC testcase 8.3.1.44 to HS_ENH_r7 ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s080321 |
| RP-43 | RP-090206 | 2533 | | Correction to NAS test case 12_4_1_4a | F | 8.0.0 | 8.1.0 | R5s080324 |
| RP-43 | RP-090206 | 2534 | | Summary of Regression Errors in HS_ENH_r7 wk48 | F | 8.0.0 | 8.1.0 | R5s080318 |
| RP-43 | RP-090206 | 2535 | | Correction to the Rel-7 CPC testcases | F | 8.0.0 | 8.1.0 | R5s080305 |
| RP-43 | RP-090206 | 2536 | | Addition of Rel7 CPC RRC testcase 8.2.2.51 to HS_ENH_r7 ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s080303 |
| RP-43 | RP-090206 | 2537 | | Correction to SIB5 and SIB5bis for IE "Frequency Band Indicator" for band VIII and higher | F | 8.0.0 | 8.1.0 | R5s080306 |
| RP-43 | RP-090206 | 2538 | | Correction in the preamble test steps for the automation of the majority of 34.123-1 test cases when the USIM removal without powering down is supported by the UE under test. | F | 8.0.0 | 8.1.0 | R5s080308 |
| RP-43 | RP-090206 | 2539 | | Correction to MBMS test step ts_TriggerRequestPTPRB | F | 8.0.0 | 8.1.0 | R5s080301 |
| RP-43 | RP-090206 | 2540 | | Corrections to HS-ENH-R7 wk43 ATS | F | 8.0.0 | 8.1.0 | R5s080302 |
| RP-43 | RP-090206 | 2541 | | Addition of Rel7 CPC RRC testcase 8.2.6.60 to HS_ENH_r7 ATS v7.2.0 | B | 8.0.0 | 8.1.0 | R5s080293 |
| RP-43 | RP-090206 | 2542 | | Correction to NAS test case 12_4_1_4b | F | 8.0.0 | 8.1.0 | R5s080300 |
| RP-43 | RP-090206 | 2543 | | LCR TDD: Addition of new test cases 12.2.1.2 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080450 |
| RP-43 | RP-090206 | 2544 | | LCR TDD: Addition of new test cases 18.1.2.4 to RAB ATS | B | 8.0.0 | 8.1.0 | R5s080448 |
| RP-43 | RP-090206 | 2545 | | LCR TDD: Addition of new test cases 16.2.2 to SMS ATS | B | 8.0.0 | 8.1.0 | R5s080446 |
| RP-43 | RP-090206 | 2546 | | LCR TDD: Addition of new test cases 16.2.1 to SMS ATS | B | 8.0.0 | 8.1.0 | R5s080444 |
| RP-43 | RP-090206 | 2547 | | LCR TDD: Addition of new test cases 16.1.9.1 to SMS ATS | B | 8.0.0 | 8.1.0 | R5s080442 |
| RP-43 | RP-090206 | 2548 | | LCR TDD: Addition of new test cases 12.9.7c to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080440 |
| RP-43 | RP-090206 | 2549 | | LCR TDD: Addition of new test cases 12.9.7b to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080438 |
| RP-43 | RP-090206 | 2550 | | LCR TDD: Addition of new test cases 12.9.7a to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080436 |
| RP-43 | RP-090206 | 2551 | | LCR TDD: Addition of new test cases 12.9.6 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080434 |
| RP-43 | RP-090206 | 2552 | | LCR TDD: Addition of new test cases 12.4.3.4 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080432 |
| RP-43 | RP-090206 | 2553 | | LCR TDD: Addition of new test cases 12.4.2.5a.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080430 |
| RP-43 | RP-090206 | 2554 | | LCR TDD: Addition of new test cases 12.4.2.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080428 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|--|-----|----------|----------|-----------|
| RP-43 | RP-090206 | 2555 | | LCR TDD: Addition of new test cases 12.4.1.4d.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080426 |
| RP-43 | RP-090206 | 2556 | | LCR TDD: Addition of new test cases 12.4.1.4c.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080424 |
| RP-43 | RP-090206 | 2557 | | LCR TDD: Addition of new test cases 12.4.1.3 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080422 |
| RP-43 | RP-090206 | 2558 | | LCR TDD: Addition of new test cases 12.4.1.2 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080420 |
| RP-43 | RP-090206 | 2559 | | LCR TDD: Addition of new test cases 12.4.1.1a to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080416 |
| RP-43 | RP-090206 | 2560 | | LCR TDD: Addition of new test cases 12.3.2.7 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080414 |
| RP-43 | RP-090206 | 2561 | | LCR TDD: Addition of new test cases 12.2.1.11 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080412 |
| RP-43 | RP-090206 | 2562 | | LCR TDD: Addition of new test cases 12.2.1.10 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080410 |
| RP-43 | RP-090206 | 2563 | | LCR TDD: Addition of new test cases 12.2.1.5d to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080408 |
| RP-43 | RP-090206 | 2564 | | LCR TDD: Addition of new test cases 12.2.1.5b to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080406 |
| RP-43 | RP-090206 | 2565 | | LCR TDD: Addition of new test cases 12.2.1.5a.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080404 |
| RP-43 | RP-090206 | 2566 | | LCR TDD: Addition of new test cases 9.4.5.2 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080402 |
| RP-43 | RP-090206 | 2567 | | LCR TDD: Addition of new test cases 9.4.2.4.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080400 |
| RP-43 | RP-090206 | 2568 | | LCR TDD: Addition of new test cases 9.4.1 to NAS ATS | B | 8.0.0 | 8.1.0 | R5s080398 |
| RP-43 | RP-090206 | 2569 | | LCR TDD: Addition of new test cases 8.4.1.8A to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080396 |
| RP-43 | RP-090206 | 2570 | | LCR TDD: Addition of new test cases 8.4.1.6A to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080394 |
| RP-43 | RP-090206 | 2571 | | LCR TDD: Addition of new test cases 8.4.1.5A to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080392 |
| RP-43 | RP-090206 | 2572 | | LCR TDD: Addition of new test cases 8.4.1.3A to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080390 |
| RP-43 | RP-090206 | 2573 | | LCR TDD: Addition of new test cases 8.4.1.2A to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080388 |
| RP-43 | RP-090206 | 2574 | | LCR TDD: Addition of new test cases 8.4.1.1A to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080386 |
| RP-43 | RP-090206 | 2575 | | LCR TDD: Addition of new test cases 8.3.3.1 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080384 |
| RP-43 | RP-090206 | 2576 | | LCR TDD: Addition of new test cases 8.3.2.1 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080382 |
| RP-43 | RP-090206 | 2577 | | LCR TDD: Addition of new test cases 8.3.1.25 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080380 |
| RP-43 | RP-090206 | 2578 | | LCR TDD: Addition of new test cases 8.3.1.17 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080378 |
| RP-43 | RP-090206 | 2579 | | LCR TDD: Addition of new test cases 8.3.1.6 to RRC | B | 8.0.0 | 8.1.0 | R5s080376 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|---------|----|-----|---------|-----|-------------|-------------|--------|
| | | | | ATS | | | | |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-43 | RP-090206 | 2580 | | LCR TDD: Addition of new test cases 8.3.1.5 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080374 |
| RP-43 | RP-090206 | 2581 | | LCR TDD: Addition of new test cases 8.3.1.2 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080372 |
| RP-43 | RP-090206 | 2582 | | LCR TDD: Addition of new test cases 8.2.6.19 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080370 |
| RP-43 | RP-090206 | 2583 | | LCR TDD: Addition of new test cases 8.2.6.12 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080368 |
| RP-43 | RP-090206 | 2584 | | LCR TDD: Addition of new test cases 8.2.6.9 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080366 |
| RP-43 | RP-090206 | 2585 | | LCR TDD: Addition of new test cases 8.2.6.8 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080364 |
| RP-43 | RP-090206 | 2586 | | LCR TDD: Addition of new test cases 8.2.6.2 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080362 |
| RP-43 | RP-090206 | 2587 | | LCR TDD: Addition of new test cases 8.2.6.1 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080360 |
| RP-43 | RP-090206 | 2588 | | LCR TDD: Addition of new test cases 8.2.4.10a to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080358 |
| RP-43 | RP-090206 | 2589 | | LCR TDD: Addition of new test cases 8.2.4.4a to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080356 |
| RP-43 | RP-090206 | 2590 | | LCR TDD: Addition of new test cases 8.2.4.3 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080354 |
| RP-43 | RP-090206 | 2591 | | LCR TDD: Addition of new test cases 8.2.3.18 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080352 |
| RP-43 | RP-090206 | 2592 | | LCR TDD: Addition of new test cases 8.2.3.1 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080350 |
| RP-43 | RP-090206 | 2593 | | LCR TDD: Addition of new test cases 8.2.2.23 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080348 |
| RP-43 | RP-090206 | 2594 | | LCR TDD: Addition of new test cases 8.2.2.19 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080346 |
| RP-43 | RP-090206 | 2595 | | LCR TDD: Addition of new test cases 8.2.2.1 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080344 |
| RP-43 | RP-090206 | 2596 | | LCR TDD: Addition of new test cases 8.2.1.9 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080342 |
| RP-43 | RP-090206 | 2597 | | LCR TDD: Addition of new test cases 8.1.2.10 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080338 |
| RP-43 | RP-090206 | 2598 | | LCR TDD: Addition of new test cases 8.1.2.4 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080336 |
| RP-43 | RP-090206 | 2599 | | LCR TDD: Addition of new test cases 8.1.1.5 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080334 |
| RP-43 | RP-090206 | 2600 | | LCR TDD: Addition of new test cases 8.1.1.3 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080332 |
| RP-43 | RP-090206 | 2601 | | LCR TDD: Addition of new test cases 8.1.1.2 to RRC ATS | B | 8.0.0 | 8.1.0 | R5s080330 |
| RP-43 | RP-090206 | 2602 | | TTCN Correction to testcases 8.3.11.9,8.3.11.10,8.3.7.14,8.3.11.14 | F | 8.0.0 | 8.1.0 | R5s090020 |
| RP-43 | RP-090206 | 2603 | | Corrections to GCF WI-014 HSD Test Case 8.3.1.34 | F | 8.0.0 | 8.1.0 | R5s090014 |
| RP-43 | RP-090211 | 2604 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.0.0 | 8.1.0 | - |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-43 | RP-090205 | 2605 | | Cleanup USIM parameters for Idle mode test | F | 8.0.0 | 8.1.0 | R5-090057 |
| RP-43 | RP-090205 | 2608 | | Test model enhancement for CS Voice over HSPA and Enhanced FACH | F | 8.0.0 | 8.1.0 | R5-090752 |
| RP-44 | RP-090436 | 2609 | | UTRA ASP enhancement for Rel-8 | F | 8.1.0 | 8.2.0 | R5-092565 |
| RP-44 | RP-090436 | 2610 | | TTCN correction to the test cases 8.1.7.1d. | F | 8.1.0 | 8.2.0 | R5s090062 |
| RP-44 | RP-090436 | 2611 | | Addition of GCF WI 70 CPC RRC test case 8.3.1.45 | B | 8.1.0 | 8.2.0 | R5s090058 |
| RP-44 | RP-090436 | 2612 | | Correction to HSDPA RAB testcases (CAT 1 to 5 & 11) | F | 8.1.0 | 8.2.0 | R5s090064 |
| RP-44 | RP-090436 | 2613 | | Corrections to GCF WI-025 HSUPA TC 7.1.6.2.2 | F | 8.1.0 | 8.2.0 | R5s090063 |
| RP-44 | RP-090436 | 2614 | | TTCN Correction to test steps in UE capability testcases which use the constraints cr_UE_CapabilityInfoAM_BandList2_r6 and cr_RRC_RrcConnSetupCmplRadioCap_BandList2_r6 | F | 8.1.0 | 8.2.0 | R5s090065 |
| RP-44 | RP-090436 | 2615 | | Summary of regression errors in wk16 ATS | F | 8.1.0 | 8.2.0 | R5s090073 |
| RP-44 | RP-090436 | 2616 | | Correction to HSUPA test case 6.1.2.11 | F | 8.1.0 | 8.2.0 | R5s090027 |
| RP-44 | RP-090436 | 2617 | | Correction to RRC test cases 8.1.3.4 and 8.3.1.15 | F | 8.1.0 | 8.2.0 | R5s090025 |
| RP-44 | RP-090436 | 2618 | | Corrections to GCF WI-070 CPC Test Cases 8.2.6.69 | F | 8.1.0 | 8.2.0 | R5s090026 |
| RP-44 | RP-090436 | 2619 | | Correction to HSD MAC test case 7.1.5.6 | F | 8.1.0 | 8.2.0 | R5s090024 |
| RP-44 | RP-090436 | 2620 | | Corrections to GCF WI-010 RLC Test Case 7.2.3.24 | F | 8.1.0 | 8.2.0 | R5s090034 |
| RP-44 | RP-090436 | 2621 | | Addition of GCF WI-070 CPC RRC testcase 8.2.6.55 to HS_ENH_r7 ATS v8.0.0 | B | 8.1.0 | 8.2.0 | R5s090035 |
| RP-44 | RP-090436 | 2622 | | Correction to GCF WI-010 Test Case 14.2.57 | F | 8.1.0 | 8.2.0 | R5s090032 |
| RP-44 | RP-090436 | 2623 | | Correction to RRC test cases 8.2.6.37 and 8.2.6.37b | F | 8.1.0 | 8.2.0 | R5s090029 |
| RP-44 | RP-090436 | 2624 | | Corrections to GCF WI-024 Network Sharing Test Cases 6.1.1.8 and 6.1.1.9 | F | 8.1.0 | 8.2.0 | R5s090031 |
| RP-44 | RP-090436 | 2625 | | Corrections to MAC_eHS_PDU & ReorderingPDU definitions | F | 8.1.0 | 8.2.0 | R5s090030 |
| RP-44 | RP-090436 | 2626 | | Correction of GCF WI-068 Improved L2 Flexible RLC UM test case 7.2.2.14 | F | 8.1.0 | 8.2.0 | R5s090022 |
| RP-44 | RP-090436 | 2627 | | TTCN Correction in TCs 8.2.6.39, 8.2.6.44 | F | 8.1.0 | 8.2.0 | R5s090028 |
| RP-44 | RP-090436 | 2628 | | Correction to the Network Sharing test cases | F | 8.1.0 | 8.2.0 | R5s090038 |
| RP-44 | RP-090436 | 2629 | | Correction to Rel-7 CPC testcase 8.2.6.61 | F | 8.1.0 | 8.2.0 | R5s090037 |
| RP-44 | RP-090436 | 2630 | | TTCN Correction to testcase 8.3.1.30 | F | 8.1.0 | 8.2.0 | R5s090041 |
| RP-44 | RP-090436 | 2631 | | Addition of GCF WI-070 CPC RRC testcase 8.2.1.40 to HS_ENH_r7 ATS v8.0.0 | B | 8.1.0 | 8.2.0 | R5s090039 |
| RP-44 | RP-090436 | 2632 | | Addition of GCF WI-068 MAC test case 7.1.5a.5.2 to HSPA7_ENH ATS | B | 8.1.0 | 8.2.0 | R5s090043 |
| RP-44 | RP-090436 | 2633 | | TTCN Correction to constraint c_DynamicAllocationPRR used to send PACKET UPLINK ASSIGNMENT, in test step ts_LLC_XID. | F | 8.1.0 | 8.2.0 | R5s090046 |
| RP-44 | RP-090436 | 2634 | | TTCN Correction to RLC test cases (7.2.2.3, 7.2.2.4, 7.2.2.5 , 7.2.2.6) for Rel-7 and later UEs. | F | 8.1.0 | 8.2.0 | R5s090055 |
| RP-44 | RP-090436 | 2635 | | Addition of GCF WI-070 CPC RRC testcase 8.2.2.53 to HS_ENH_r7 ATS v8.1.0 | B | 8.1.0 | 8.2.0 | R5s090056 |
| RP-44 | RP-090436 | 2636 | | TTCN Correction in test case 12.9.7b | F | 8.1.0 | 8.2.0 | R5s090053 |
| RP-44 | RP-090436 | 2637 | | Baseline upgrade to March-09 Rel-8 | F | 8.1.0 | 8.2.0 | R5s090045 |
| RP-44 | RP-090436 | 2638 | | Correction to HSU Network Sharing test cases and some generic changes | F | 8.1.0 | 8.2.0 | R5s090052 |
| RP-44 | RP-090436 | 2639 | | Corrections to GCF WI-070 CPC Test Cases 8.2.6.61 | F | 8.1.0 | 8.2.0 | R5s090048 |
| RP-44 | RP-090436 | 2640 | | TTCN correction to the test cases 8.3.7.1a (Support of A5/3 algorithm) for Rel-99 UE | F | 8.1.0 | 8.2.0 | R5s090054 |
| RP-44 | RP-090436 | 2641 | | Correction to the Network Sharing test cases | F | 8.1.0 | 8.2.0 | R5s090047 |
| RP-44 | RP-090436 | 2642 | | Correction to RAB test case variables, "tcv_Background" and "tcv_Streaming" | F | 8.1.0 | 8.2.0 | R5s090051 |
| RP-44 | RP-090436 | 2643 | | Correction to GCF WI 25 HSU test case 8.1.2.18 | F | 8.1.0 | 8.2.0 | R5s090050 |
| RP-44 | RP-090436 | 2644 | | Correction to RRC test case 8.3.2.12 | F | 8.1.0 | 8.2.0 | R5s090049 |
| RP-44 | RP-090436 | 2645 | | Corrections to handle v7b0NonCriticalExtensions in RRC Connection Req message (Rel-7). | F | 8.1.0 | 8.2.0 | R5s090061 |
| RP-44 | RP-090436 | 2646 | | Corrections to GCF WI-024 Network Sharing Test Cases 6.1.1.8, 6.1.1.9, 6.1.2.11, 6.2.2.4 | F | 8.1.0 | 8.2.0 | R5s090060 |
| RP-44 | RP-090435 | 2647 | | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.1.0 | 8.2.0 | - |
| RP-45 | RP-090796 | 2648 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.2.0 | 8.3.0 | - |
| RP-45 | RP-090797 | 2649 | - | Addition of GCF WI-069 64 QAM MAC test case 7.1.5a.5.3 to HSPA7_ENH ATS | B | 8.2.0 | 8.3.0 | R5s090074 |
| RP-45 | RP-090797 | 2650 | - | Corrections to GCF WI-070 CPC Test Cases 8.2.6.61 | F | 8.2.0 | 8.3.0 | R5s090079 |
| RP-45 | RP-090797 | 2651 | - | Correction to GCF WI-012 RRC Testcase 8.3.1.30 | F | 8.2.0 | 8.3.0 | R5s090078 |
| RP-45 | RP-090797 | 2652 | - | Addition of GCF WI-069 64QAM RAB test case | B | 8.2.0 | 8.3.0 | R5s090076 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| | | | | 14.6.1c to HSPA7_ENH ATS | | | | |
| RP-45 | RP-090797 | 2653 | - | Addition of GCF WI-068 Improved L2 RAB testcase 14.7.6b to HS_ENH_r7 ATS v8.1.0 | B | 8.2.0 | 8.3.0 | R5s090070 |
| RP-45 | RP-090797 | 2654 | - | Addition of GCF WI-068 Improved L2 RAB testcase 14.6.6a to HS_ENH_r7 ATS v8.1.0 | B | 8.2.0 | 8.3.0 | R5s090068 |
| RP-45 | RP-090797 | 2655 | - | Correction to GCF WI 70 CPC RRC test cases | F | 8.2.0 | 8.3.0 | R5s090080 |
| RP-45 | RP-090797 | 2656 | - | Correction to the wk19 TTCN for Packet Uplink Assignment message | F | 8.2.0 | 8.3.0 | R5s090081 |
| RP-45 | RP-090797 | 2657 | - | TTCN Correction to testcase 9.4.2.2.1. | F | 8.2.0 | 8.3.0 | R5s090082 |
| RP-45 | RP-090797 | 2658 | - | Addition of GCF WI-070 CPC RRC testcase 8.2.6.58 to HS_ENH_r7 ATS v8.2.0 | B | 8.2.0 | 8.3.0 | R5s090083 |
| RP-45 | RP-090797 | 2659 | - | Improvement of Rel-7 security steps | F | 8.2.0 | 8.3.0 | R5s090087 |
| RP-45 | RP-090797 | 2660 | - | Correction to Bcap type definition to support 9 speech versions | F | 8.2.0 | 8.3.0 | R5s090089 |
| RP-45 | RP-090797 | 2661 | - | Correction to the CPC test case 8.2.6.58 | F | 8.2.0 | 8.3.0 | R5s090093 |
| RP-45 | RP-090797 | 2662 | - | Correction to the MRAT test case 8.3.7.14 | F | 8.2.0 | 8.3.0 | R5s090092 |
| RP-45 | RP-090797 | 2663 | - | Addition of CS Voice over HSPA test case 7.3.7.1 | B | 8.2.0 | 8.3.0 | R5s090090 |
| RP-45 | RP-090797 | 2664 | - | Addition of GCF WI-069 64QAM RAB test case 14.6.6b to HSPA7_ENH ATS v8.2.0 | B | 8.2.0 | 8.3.0 | R5s090085 |
| RP-45 | RP-090797 | 2665 | - | Correction to DualCarrierFreqParam Structured Type Definition | F | 8.2.0 | 8.3.0 | R5s090102 |
| RP-45 | RP-090797 | 2666 | - | Corrections to GCF WI-068 and WI-069 test cases 14.6.1c and 7.1.5a.5.2 and 7.1.5a.5.3. | F | 8.2.0 | 8.3.0 | R5s090101 |
| RP-45 | RP-090797 | 2667 | - | Correction to GCF WI 24/1 test case 6.1.2.11 | F | 8.2.0 | 8.3.0 | R5s090100 |
| RP-45 | RP-090797 | 2668 | - | Correction to GCF WI-010 IR-U test cases 8.3.9.5 | F | 8.2.0 | 8.3.0 | R5s090097 |
| RP-45 | RP-090797 | 2669 | - | Correction to GCF WI-025 HSUPA TC 7.1.6.2.2 | F | 8.2.0 | 8.3.0 | R5s090106 |
| RP-45 | RP-090797 | 2670 | - | Addition of GCF WI-068 IMPROVED L2 RRC testcase 8.2.2.57 to HS_ENH_r7 ATS v8.2.0 | B | 8.2.0 | 8.3.0 | R5s090098 |
| RP-45 | RP-090797 | 2671 | - | Addition of Rel-8 RRC test case 8.2.2.58 | B | 8.2.0 | 8.3.0 | R5s090094 |
| RP-45 | RP-090797 | 2672 | - | Packet Uplink Assignment should be sent on PACCH instead of PAGCH | F | 8.2.0 | 8.3.0 | R5s090103 |
| RP-45 | RP-090794 | 2673 | - | Documentation of LCR TDD ASP changes | F | 8.2.0 | 8.3.0 | R5-094070 |
| RP-45 | RP-090799 | 2674 | - | ASP enhancement for Improved Layer 2 UL and 64QAM+MIMO | F | 8.2.0 | 8.3.0 | R5-095029 |
| RP-45 | RP-090794 | 2675 | - | ASP corrections for Enhanced FACH DL | F | 8.2.0 | 8.3.0 | R5-095190 |
| RP-46 | RP-091119 | 2676 | - | Routine maintenance for divergent updates | F | 8.3.0 | 8.4.0 | R5-096431 |
| RP-46 | RP-091115 | 2677 | - | Removal of GPRS P-channels from GERAN test model and ASPs | F | 8.3.0 | 8.4.0 | R5-096432 |
| RP-46 | RP-091113 | 2678 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.3.0 | 8.4.0 | - |
| RP-46 | RP-091114 | 2679 | - | Addition of GCF WI-101 Rel-7 Ciphering test case 8.2.2.43a to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090107 |
| RP-46 | RP-091114 | 2680 | - | Addition of GCF WI-101 Rel-7 Ciphering test case 8.1.7.4 to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090109 |
| RP-46 | RP-091114 | 2681 | - | Addition of GCF WI 70 Rel-7 CPC test case 8.2.3.37 | B | 8.3.0 | 8.4.0 | R5s090104 |
| RP-46 | RP-091114 | 2682 | - | Correction to CPC RRC test case 8.2.2.53 | F | 8.3.0 | 8.4.0 | R5s090111 |
| RP-46 | RP-091114 | 2683 | - | Correction to GCF WI 24/1 test case 6.2.1.10 | F | 8.3.0 | 8.4.0 | R5s090112 |
| RP-46 | RP-091114 | 2684 | - | Corrections to CPC testcases | F | 8.3.0 | 8.4.0 | R5s090122 |
| RP-46 | RP-091114 | 2685 | - | Corrections to RAB Test Cases | F | 8.3.0 | 8.4.0 | R5s090126 |
| RP-46 | RP-091114 | 2686 | - | Corrections to GCF Rel 99, Rel-5 and Rel-6 test cases | F | 8.3.0 | 8.4.0 | R5s090123 |
| RP-46 | RP-091114 | 2687 | - | Correction to the test step ts_RRC_receiveConnSetupCmpl_CheckA5_3 | F | 8.3.0 | 8.4.0 | R5s090119 |
| RP-46 | RP-091114 | 2688 | - | Correction to the GCF WI-014 HSDPA TC 8.2.1.27, 8.3.4.9, 8.2.6.40 | F | 8.3.0 | 8.4.0 | R5s090124 |
| RP-46 | RP-091114 | 2689 | - | Addition of GCF WI-101 Rel-7 Ciphering test case 8.1.7.3c to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090117 |
| RP-46 | RP-091114 | 2690 | - | Addition of GCF WI-101 Rel-7 Ciphering test case 8.1.7.3b to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090115 |
| RP-46 | RP-091114 | 2691 | - | Addition of GCF WI-101 Rel-7 Ciphering test case 8.1.7.3 to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090113 |
| RP-46 | RP-091114 | 2692 | - | Correction to GCF WI 24/1 test case 6.1.1.9 | F | 8.3.0 | 8.4.0 | R5s090120 |
| RP-46 | RP-091114 | 2693 | - | Correction to R99 FACH to DCH and DCH to FACH transition RRC test cases | F | 8.3.0 | 8.4.0 | R5s090125 |
| RP-46 | RP-091114 | 2694 | - | Correction to GCF WI 68 RRC test case 8.2.2.57 | F | 8.3.0 | 8.4.0 | R5s090121 |
| RP-46 | RP-091114 | 2695 | - | Correction to GCF WI-10 IR_U test case 8.4.1.33 | F | 8.3.0 | 8.4.0 | R5s090129 |
| RP-46 | RP-091114 | 2696 | - | Correction to WK37 TTCN | F | 8.3.0 | 8.4.0 | R5s090132 |
| RP-46 | RP-091114 | 2697 | - | Correction to GCF WI-101 SNOW 3G TC 8.2.2.43a | F | 8.3.0 | 8.4.0 | R5s090131 |
| RP-46 | RP-091114 | 2698 | - | TTCN Correction in TC 6.1.2.6 | F | 8.3.0 | 8.4.0 | R5s090130 |
| RP-46 | RP-091114 | 2699 | - | Addition of GCF WI-101 Rel-7 SNOW Ciphering test case 8.3.11.1a to HS_ENH_r7 ATS v8.2.0. | B | 8.3.0 | 8.4.0 | R5s090127 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-46 | RP-091114 | 2700 | - | Correction to ts_TransitToURA_PCH_P17_P18 in RRC ATS | F | 8.3.0 | 8.4.0 | R5s090136 |
| RP-46 | RP-091114 | 2701 | - | Correction to RRC Connection Request test steps to update Release Indication | F | 8.3.0 | 8.4.0 | R5s090133 |
| RP-46 | RP-091114 | 2702 | - | Correction to HSDPA, HSUPA and HSPA7 DCH to FACH and FACH to DCH transition test cases | F | 8.3.0 | 8.4.0 | R5s090147 |
| RP-46 | RP-091114 | 2703 | - | Corrections to Rel-6 testcases to make F-DPCH optional | F | 8.3.0 | 8.4.0 | R5s090143 |
| RP-46 | RP-091114 | 2704 | - | Corrections to Rel-7 testcases to make F-DPCH optional | F | 8.3.0 | 8.4.0 | R5s090158 |
| RP-46 | RP-091114 | 2705 | - | Correction to Rel-7 Enhanced L2 test case 8.2.2.57 | F | 8.3.0 | 8.4.0 | R5s090146 |
| RP-46 | RP-091114 | 2706 | - | Corrections to Rel-7 64QAM testcase 14.6.6b | F | 8.3.0 | 8.4.0 | R5s090159 |
| RP-46 | RP-091114 | 2707 | - | Correction to GCF WI-101 Rel-7 Ciphering test case 8.2.2.43a | F | 8.3.0 | 8.4.0 | R5s090162 |
| RP-46 | RP-091114 | 2708 | - | Addition of GCF WI-101 GCF Rel-7 Ciphering test case 8.2.2.43b to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090173 |
| RP-46 | RP-091114 | 2709 | - | Addition of GCF WI-101 Rel-7 Ciphering test case 8.1.7.3d to HSPA7_ENH ATS | B | 8.3.0 | 8.4.0 | R5s090169 |
| RP-46 | RP-091114 | 2710 | - | Addition of CS voice over HSPA RAB test case 14.7.9 | B | 8.3.0 | 8.4.0 | R5s090134 |
| RP-46 | RP-091114 | 2711 | - | Addition of GCF WI 70 Rel-7 CPC MAC test case 7.1.6.3.4 | B | 8.3.0 | 8.4.0 | R5s090151 |
| RP-46 | RP-091114 | 2712 | - | Addition of GCF WI 70 Rel-7 CPC MAC test case 7.1.6.3.3 | B | 8.3.0 | 8.4.0 | R5s090149 |
| RP-46 | RP-091114 | 2713 | - | Addition of RFT067 test case 6.2.1.8a.2 | B | 8.3.0 | 8.4.0 | R5s090187 |
| RP-46 | RP-091114 | 2714 | - | Addition of RFT067 test case 6.2.1.8a.1 | B | 8.3.0 | 8.4.0 | R5s090185 |
| RP-46 | RP-091114 | 2715 | - | Addition of RFT067 test case 6.2.1.2a | B | 8.3.0 | 8.4.0 | R5s090183 |
| RP-46 | RP-091114 | 2716 | - | Incorrect implementation of CR R5s090082 | F | 8.3.0 | 8.4.0 | R5s090182 |
| RP-46 | RP-091114 | 2717 | - | Addition of GCF WI 101 Rel-7 Snow 3G InterRAT test case 8.3.11.1b | B | 8.3.0 | 8.4.0 | R5s090190 |
| RP-46 | RP-091114 | 2718 | - | Corrections to test steps and constraints with identical names | F | 8.3.0 | 8.4.0 | R5s090206 |
| RP-46 | RP-091114 | 2719 | - | Corrections to L2 Enhancement RAB test case 14.7.6b | F | 8.3.0 | 8.4.0 | R5s090208 |
| RP-46 | RP-091114 | 2720 | - | Addition of GCF WI 101 Rel-7 Snow 3G InterRAT test case 8.3.7.1b | B | 8.3.0 | 8.4.0 | R5s090192 |
| RP-47 | RP-100144 | 2721 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.4.0 | 8.5.0 | - |
| RP-47 | RP-100145 | 2722 | - | Correction to HSPA7 Enhanced L2 test case 8.2.2.57 | F | 8.4.0 | 8.5.0 | R5s090305 |
| RP-47 | RP-100145 | 2723 | - | Correction to RRC HSDPA test case 8.3.1.40 | F | 8.4.0 | 8.5.0 | R5s090308 |
| RP-47 | RP-100145 | 2724 | - | Correction to the test cases 8.2.6.55 and 14.7.9 | F | 8.4.0 | 8.5.0 | R5s090309 |
| RP-47 | RP-100145 | 2725 | - | Corrections to GMM test case 12.9.12 | F | 8.4.0 | 8.5.0 | R5s090207 |
| RP-47 | RP-100145 | 2726 | - | Addition of RFT067 test case 6.2.1.8a.3 | B | 8.4.0 | 8.5.0 | R5s090338 |
| RP-47 | RP-100145 | 2727 | - | Addition of RFT080 test case 8.1.2.22a | B | 8.4.0 | 8.5.0 | R5s090329 |
| RP-47 | RP-100145 | 2728 | - | Addition of RFT080 test case 8.1.2.22 | B | 8.4.0 | 8.5.0 | R5s090327 |
| RP-47 | RP-100145 | 2729 | - | Addition of RFT080 test case 8.1.2.21a | B | 8.4.0 | 8.5.0 | R5s090325 |
| RP-47 | RP-100145 | 2730 | - | Addition of RFT 80 test case 8.1.2.21 | B | 8.4.0 | 8.5.0 | R5s090323 |
| RP-47 | RP-100145 | 2731 | - | Correction to RRC test case 8.1.7.1, 8.1.7.1b, 8.1.7.1c and 8.1.7.2 | F | 8.4.0 | 8.5.0 | R5s090372 |
| RP-47 | RP-100145 | 2732 | - | Correction to Rel-7 CPC testcase 8.2.2.53 | F | 8.4.0 | 8.5.0 | R5s090370 |
| RP-47 | RP-100145 | 2733 | - | Correction to RRC test cases 8.1.1.1 and 8.1.1.9 | F | 8.4.0 | 8.5.0 | R5s090374 |
| RP-47 | RP-100145 | 2734 | - | Addition of GCF WI 80 Rel-7 CPC RRC test case 8.2.2.55 | B | 8.4.0 | 8.5.0 | R5s100010 |
| RP-47 | RP-100145 | 2735 | - | Correction to the test cases 8.3.1.39 from HSD_ENH_r5 test suite | F | 8.4.0 | 8.5.0 | R5s100026 |
| RP-47 | RP-100145 | 2736 | - | Corrections to CPC testcases 7.1.6.3.3 & 7.1.6.3.4 | F | 8.4.0 | 8.5.0 | R5s100023 |
| RP-47 | RP-100145 | 2737 | - | TTCN Correction to testcase 7.1.6.2.10 | F | 8.4.0 | 8.5.0 | R5s100027 |
| RP-47 | RP-100145 | 2738 | - | TTCN Correction to test step ts_CC_EnterU10_MO | F | 8.4.0 | 8.5.0 | R5s100028 |
| RP-47 | RP-100145 | 2739 | - | Correction to R99 testcase 8.2.2.35 | F | 8.4.0 | 8.5.0 | R5s100036 |
| RP-47 | RP-100145 | 2740 | - | Corrections to Rel-7 test step ts_InitVariablesRel7 | F | 8.4.0 | 8.5.0 | R5s100037 |
| RP-47 | RP-100145 | 2741 | - | Corrections to CPC RRC testcase 8.2.2.55 | F | 8.4.0 | 8.5.0 | R5s100045 |
| RP-47 | RP-100145 | 2742 | - | Correction to HSPA7 suite | F | 8.4.0 | 8.5.0 | R5s100048 |
| RP-47 | RP-100145 | 2743 | - | Corrections to R99 NAS ATS | F | 8.4.0 | 8.5.0 | R5s100046 |
| RP-47 | RP-100145 | 2744 | - | Correction to CPC test case 8.2.2.55 | F | 8.4.0 | 8.5.0 | R5s100050 |
| RP-47 | RP-100145 | 2745 | - | AGPS baseline upgrade to March 09 in Rel-8 | F | 8.4.0 | 8.5.0 | R5s090224 |
| RP-47 | RP-100145 | 2746 | - | Corrections to GCF WI 25 HSU test case 8.2.6.52 | F | 8.4.0 | 8.5.0 | R5s090216 |
| RP-47 | RP-100145 | 2747 | - | Correction to test cases 8.3.11.1a and 8.3.11.1b | F | 8.4.0 | 8.5.0 | R5s090303 |
| RP-47 | RP-100145 | 2748 | - | Regression CR on wk46 TTCN | F | 8.4.0 | 8.5.0 | R5s090304 |
| RP-47 | RP-100145 | 2749 | - | LCR TDD: Addition of NAS test case 12.4.1.5 | B | 8.4.0 | 8.5.0 | R5s090299 |
| RP-47 | RP-100145 | 2750 | - | LCR TDD: Addition of RRC test case 8.1.2.1 | B | 8.4.0 | 8.5.0 | R5s090297 |
| RP-47 | RP-100145 | 2751 | - | LCR TDD: Addition of RLC test case 7.2.3.28 | B | 8.4.0 | 8.5.0 | R5s090295 |
| RP-47 | RP-100145 | 2752 | - | LCR TDD: Addition of RLC test case 7.2.3.17 | B | 8.4.0 | 8.5.0 | R5s090285 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-47 | RP-100145 | 2753 | - | LCR TDD: Addition of RAB test case 18.1.2.32.1 | B | 8.4.0 | 8.5.0 | R5s090301 |
| RP-47 | RP-100145 | 2754 | - | LCR TDD: Addition of RLC test case 7.2.3.26 | B | 8.4.0 | 8.5.0 | R5s090293 |
| RP-47 | RP-100145 | 2755 | - | LCR TDD: Addition of RLC test case 7.2.3.22 | B | 8.4.0 | 8.5.0 | R5s090291 |
| RP-47 | RP-100145 | 2756 | - | LCR TDD: Addition of RLC test case 7.2.3.20 | B | 8.4.0 | 8.5.0 | R5s090289 |
| RP-47 | RP-100145 | 2757 | - | LCR TDD: Addition of RLC test case 7.2.3.18 | B | 8.4.0 | 8.5.0 | R5s090287 |
| RP-47 | RP-100145 | 2758 | - | LCR TDD: Addition of RLC test case 7.2.3.16 | B | 8.4.0 | 8.5.0 | R5s090283 |
| RP-47 | RP-100145 | 2759 | - | LCR TDD: Addition of RLC test case 7.2.3.15 | B | 8.4.0 | 8.5.0 | R5s090281 |
| RP-47 | RP-100145 | 2760 | - | LCR TDD: Addition of RLC test case 7.2.3.13 | B | 8.4.0 | 8.5.0 | R5s090279 |
| RP-47 | RP-100145 | 2761 | - | LCR TDD: Addition of RLC test case 7.2.3.6 | B | 8.4.0 | 8.5.0 | R5s090277 |
| RP-47 | RP-100145 | 2762 | - | LCR TDD: Addition of RLC test case 7.2.3.5 | B | 8.4.0 | 8.5.0 | R5s090275 |
| RP-47 | RP-100145 | 2763 | - | LCR TDD: Addition of RLC test case 7.2.3.4 | B | 8.4.0 | 8.5.0 | R5s090273 |
| RP-47 | RP-100145 | 2764 | - | LCR TDD: Addition of MAC test case 7.1.1.5 | B | 8.4.0 | 8.5.0 | R5s090271 |
| RP-47 | RP-100145 | 2765 | - | LCR TDD: Addition of MAC test case 7.1.1.4 | B | 8.4.0 | 8.5.0 | R5s090269 |
| RP-47 | RP-100145 | 2766 | - | LCR TDD: Addition of MAC test case 7.1.1.3 | B | 8.4.0 | 8.5.0 | R5s090267 |
| RP-47 | RP-100145 | 2767 | - | Correction to RRC test cases 6.1.2.2, 8.3.1.24 and 8.3.2.13 | F | 8.4.0 | 8.5.0 | R5s090371 |
| RP-47 | RP-100145 | 2768 | - | Correction to HSD, HSU and HS7 test cases | F | 8.4.0 | 8.5.0 | R5s100056 |
| RP-47 | RP-100145 | 2769 | - | Addition of CS Over HSPA test case 14.7.10 | B | 8.4.0 | 8.5.0 | R5s100059 |
| RP-47 | RP-100145 | 2770 | - | Addition of GCF WI 25 HSUPA MAC test case 7.1.6.3.2 | B | 8.4.0 | 8.5.0 | R5s100061 |
| RP-47 | RP-100153 | 2771 | - | UTRA LCR TDD ASP enhancement for Rel-8 | F | 8.4.0 | 8.5.0 | R5-100047 |
| RP-47 | RP-100137 | 2772 | - | Routine maintenance for divergent updates | F | 8.4.0 | 8.5.0 | R5-101042 |
| RP-47 | RP-100149 | 2773 | - | Update ASP for FDD dual cell test | F | 8.4.0 | 8.5.0 | R5-101047 |
| RP-47 | RP-100150 | 2774 | - | FDD ASP enhancement for the enhanced UL of FACH test | F | 8.4.0 | 8.5.0 | R5-101048 |
| RP-48 | RP-100512 | 2775 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.5.0 | 8.6.0 | - |
| RP-48 | RP-100506 | 2790 | - | Routine maintenance of TS 34.123-3 | F | 8.5.0 | 8.6.0 | R5-103530 |
| RP-48 | RP-100519 | 2791 | - | ASP correction for Enhanced FACH uplink | F | 8.5.0 | 8.6.0 | R5-103645 |
| RP-48 | RP-100517 | 2792 | - | ASP corrections for Dual Cell | F | 8.5.0 | 8.6.0 | R5-103863 |
| RP-48 | RP-100513 | 2776 | - | Correction to HSU test cases. | F | 8.5.0 | 8.6.0 | R5s100064 |
| RP-48 | RP-100513 | 2777 | - | Corrections to HSUPA MAC testcase 7.1.6.2.6 | F | 8.5.0 | 8.6.0 | R5s100069 |
| RP-48 | RP-100513 | 2779 | - | Regression CR for UMTS ATS | F | 8.5.0 | 8.6.0 | R5s100070 |
| RP-48 | RP-100513 | 2778 | - | Corrections to RRC testcase 8.2.6.37 & 8.2.6.37b | F | 8.5.0 | 8.6.0 | R5s100071 |
| RP-48 | RP-100513 | 2780 | - | Correction to Rel-7 RAB test cases on HARQ number of processes initialization | F | 8.5.0 | 8.6.0 | R5s100108 |
| RP-48 | RP-100513 | 2781 | - | Regression CR for WK10 TTCN | F | 8.5.0 | 8.6.0 | R5s100115 |
| RP-48 | RP-100513 | 2782 | - | Correction to WI-101 HS_ENH_r7 test case 8.3.7.1b | F | 8.5.0 | 8.6.0 | R5s100121 |
| RP-48 | RP-100513 | 2783 | - | Correction to WI-070 CPC test case 8.2.2.53 | F | 8.5.0 | 8.6.0 | R5s100122 |
| RP-48 | RP-100513 | 2784 | - | Addition of GCF WI-114 64 QAM RRC test case 8.2.2.63 to HSPA7_ENH ATS | B | 8.5.0 | 8.6.0 | R5s100123 |
| RP-48 | RP-100513 | 2785 | - | Addition of GCF WI-114 64 QAM RRC test case 8.2.6.62 to HSPA7_ENH ATS | B | 8.5.0 | 8.6.0 | R5s100125 |
| RP-48 | RP-100513 | 2786 | - | Correction to testcases 8.3.2.12, 6.2.2.2 | F | 8.5.0 | 8.6.0 | R5s100164 |
| RP-48 | RP-100513 | 2788 | - | Correction to RRC Connection Release test steps in RAB R99 - R8 test cases | F | 8.5.0 | 8.6.0 | R5s100165 |
| RP-48 | RP-100513 | 2789 | - | Correction to the Out of Service area test cases. | F | 8.5.0 | 8.6.0 | R5s100168 |
| RP-48 | RP-100513 | 2787 | - | Baseline upgrade of UTRA ATS to March-10 Rel-8 | F | 8.5.0 | 8.6.0 | R5s100171 |
| RP-49 | RP-100985 | 2793 | - | ASP documentation for TDD and maintenance | F | 8.6.0 | 8.7.0 | R5-104203 |
| RP-49 | RP-100985 | 2794 | - | Routine maintenance of TS 34.123-3 | F | 8.6.0 | 8.7.0 | R5-105034 |
| RP-49 | RP-100985 | 2795 | - | Add new PIXIT related to GERAN UE classmarks | F | 8.6.0 | 8.7.0 | R5-105027 |
| RP-49 | RP-100824 | 2796 | - | Correction to the GCF WI-24 test case 6.2.1.11 | F | 8.6.0 | 8.7.0 | R5s100185 |
| RP-49 | RP-100824 | 2797 | - | Corrections to Rel-99 NAS testcases | F | 8.6.0 | 8.7.0 | R5s100207 |
| RP-49 | RP-100824 | 2798 | - | Corrections to Rel-7 testcases | F | 8.6.0 | 8.7.0 | R5s100206 |
| RP-49 | RP-100824 | 2799 | - | Regression CR on wk16 UMTS ATS | F | 8.6.0 | 8.7.0 | R5s100186 |
| RP-49 | RP-100824 | 2800 | - | Correction to GCF WI-025 E_DCH Testcase 7.1.6.2.1 | F | 8.6.0 | 8.7.0 | R5s100255 |
| RP-49 | RP-100824 | 2801 | - | Correction to GCF WI 25 HSU test cases 7.1.6.4.2 and 7.1.6.2.1 | F | 8.6.0 | 8.7.0 | R5s100276 |
| RP-49 | RP-100824 | 2802 | - | Corrections to Rel-6 HSUPA MAC test cases | F | 8.6.0 | 8.7.0 | R5s100290 |
| RP-49 | RP-100824 | 2803 | - | Regression CR on wk21 UMTS ATS | F | 8.6.0 | 8.7.0 | R5s100275 |
| RP-49 | RP-100824 | 2804 | - | Correction to GCF WI-070 CPC Test Cases 7.1.6.3.3, 7.1.6.3.4 | F | 8.6.0 | 8.7.0 | R5s100280 |
| RP-49 | RP-100824 | 2805 | - | Correction to Rel-99 SMS test case 16.3 | F | 8.6.0 | 8.7.0 | R5s100297 |
| RP-49 | RP-100824 | 2806 | - | Correction to GCF WI 25 HSUPA MAC test case 7.1.6.3.2 | F | 8.6.0 | 8.7.0 | R5s100328 |
| RP-49 | RP-100824 | 2807 | - | Addition of GCF WI 70 Rel-7 CPC test case 8.3.4.11 | F | 8.6.0 | 8.7.0 | R5s100277 |
| RP-49 | RP-100824 | 2808 | - | Correction to GCF WI 25 HSUPA test case 7.1.6.3.2 | B | 8.6.0 | 8.7.0 | R5s100355 |
| RP-49 | RP-100824 | 2809 | - | Correction to GCF WI-070 CPC test case 8.2.3.37 | F | 8.6.0 | 8.7.0 | R5s100484 |
| RP-49 | RP-100824 | 2810 | - | Correction to GCF WI-025 HSUPA test case 7.1.6.3.2 | F | 8.6.0 | 8.7.0 | R5s100483 |
| RP-49 | RP-100824 | 2811 | - | Correction to GCF WI-070 CPC Test Cases 7.1.6.3.3, 7.1.6.3.4 | F | 8.6.0 | 8.7.0 | R5s100404 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-49 | RP-100824 | 2812 | - | Correction to GCF WI 10 RRC test case 6.1.2.2. | F | 8.6.0 | 8.7.0 | R5s100397 |
| RP-49 | RP-100824 | 2813 | - | Correction to GCF WI 10 IR_U test case 8.3.9.5. | F | 8.6.0 | 8.7.0 | R5s100396 |
| RP-49 | RP-100824 | 2814 | - | Corrections to R7 CPC test cases | F | 8.6.0 | 8.7.0 | R5s100482 |
| RP-49 | RP-100824 | 2815 | - | Corrections to HSUPA MAC test case 7.1.6.3.2 & 7.1.6.2.6 | F | 8.6.0 | 8.7.0 | R5s100481 |
| RP-49 | RP-100823 | 2816 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.6.0 | 8.7.0 | - |
| - | - | - | - | Updated the lists of approved test cases for FDD and LCR TDD in Annex A to align with TTCN. | - | 8.6.0 | 8.7.0 | - |
| RP-50 | RP-101148 | 2819 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.7.0 | 8.8.0 | - |
| RP-50 | RP-101146 | 2817 | - | New channel configurations for LCR TDD RB tests | F | 8.7.0 | 8.8.0 | R5-106065 |
| RP-50 | RP-101146 | 2818 | - | Routine maintenance | F | 8.7.0 | 8.8.0 | R5-106547 |
| RP-50 | RP-101149 | 2822 | - | Addition of GCF WI-110 Enhanced Cell FACH DL MAC test case 7.1.5a.6 to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100509 |
| RP-50 | RP-101149 | 2821 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.1.2.20 to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100511 |
| RP-50 | RP-101149 | 2820 | - | Correction to GCF WI 10 SMS test case 16.1.1 | F | 8.7.0 | 8.8.0 | R5s100514 |
| RP-50 | RP-101149 | 2824 | - | Correction to GCF WI-024 network sharing test case 6.2.1.11 | F | 8.7.0 | 8.8.0 | R5s100518 |
| RP-50 | RP-101149 | 2823 | - | Correction for GCF WI-010 NAS test case 12.2.1.11 | F | 8.7.0 | 8.8.0 | R5s100519 |
| RP-50 | RP-101149 | 2826 | - | Regression CR on wk36 UMTS ATS | F | 8.7.0 | 8.8.0 | R5s100540 |
| RP-50 | RP-101149 | 2828 | - | Corrections to Rel-7 Enhanced Cell-FACH DL test cases | F | 8.7.0 | 8.8.0 | R5s100543 |
| RP-50 | RP-101149 | 2827 | - | Corrections to Rel-7 L2-Enhancement test case 8.2.2.57 | F | 8.7.0 | 8.8.0 | R5s100544 |
| RP-50 | RP-101149 | 2825 | - | Corrections to Rel-7 CPC test case 8.2.6.58 and Rel-7 L2 Enh test case 8.2.2.57 | F | 8.7.0 | 8.8.0 | R5s100547 |
| RP-50 | RP-101149 | 2834 | - | Correction to GCF WI-025 testcase 7.1.6.3.2 | F | 8.7.0 | 8.8.0 | R5s100551 |
| RP-50 | RP-101149 | 2833 | - | Corrections to Rel-8 CSVoice over HSPA test cases | F | 8.7.0 | 8.8.0 | R5s100552 |
| RP-50 | RP-101149 | 2832 | - | Corrections to Rel-6 test cases 8.2.1.36 and 8.2.1.36a | F | 8.7.0 | 8.8.0 | R5s100553 |
| RP-50 | RP-101149 | 2831 | - | Correction to GCF WI-025 testcase 7.1.6.2.10 | F | 8.7.0 | 8.8.0 | R5s100554 |
| RP-50 | RP-101149 | 2830 | - | Addition of GCF WI-067 MiMo RAB test case 14.6.1d to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100567 |
| RP-50 | RP-101149 | 2829 | - | Addition of GCF WI-067 MiMo RAB test case 14.6.6c to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100569 |
| RP-50 | RP-101149 | 2835 | - | Correction to UE Network Capability in UMTS | F | 8.7.0 | 8.8.0 | R5s100574 |
| RP-50 | RP-101149 | 2836 | - | Correction to UMTS Security Capabilities. | F | 8.7.0 | 8.8.0 | R5s100578 |
| RP-50 | RP-101149 | 2838 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RAB test case 14.5.3 to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100599 |
| RP-50 | RP-101149 | 2837 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.1.10.2 to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100601 |
| RP-50 | RP-101149 | 2839 | - | Corrections to Rel-99 testcases | F | 8.7.0 | 8.8.0 | R5s100613 |
| RP-50 | RP-101149 | 2840 | - | Correction to the common test steps_RegistrationReject_Idle | F | 8.7.0 | 8.8.0 | R5s100677 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-50 | RP-101149 | 2842 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.2.2.59 to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100716 |
| RP-50 | RP-101149 | 2841 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.2.2.60 to HSPA7_ENH ATS | F | 8.7.0 | 8.8.0 | R5s100718 |
| RP-50 | RP-101149 | 2846 | - | Correction to MAC testcase 7.1.5a.6 | F | 8.7.0 | 8.8.0 | R5s100762 |
| RP-50 | RP-101149 | 2845 | - | Correction to Rel-7 CPC testcase 8.3.4.11 | F | 8.7.0 | 8.8.0 | R5s100763 |
| RP-50 | RP-101149 | 2844 | - | Correction for GCF WI-010 SMS test case 16.2.2 | F | 8.7.0 | 8.8.0 | R5s100770 |
| RP-50 | RP-101149 | 2843 | - | Correction for GCF WI-012 NAS test case 9.4.3.3 | F | 8.7.0 | 8.8.0 | R5s100771 |
| RP-51 | RP-110167 | 2850 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.8.0 | 8.9.0 | - |
| RP-51 | RP-110165 | 2847 | - | Routine maintenance for LCR TDD ASP | F | 8.8.0 | 8.9.0 | R5-110103 |
| RP-51 | RP-110165 | 2848 | - | Routine maintenance of 34123-3 | F | 8.8.0 | 8.9.0 | R5-110104 |
| RP-51 | RP-110165 | 2849 | - | Table and figure renumbering in 34.123-3 | F | 8.8.0 | 8.9.0 | R5-110365 |
| RP-51 | RP-110168 | 2860 | - | Addition of GCF WI-104 Idle Mode test case 6.1.1.14 to HSPA7_ENH ATS | B | 8.8.0 | 8.9.0 | R5s100710 |
| RP-51 | RP-110168 | 2865 | - | Addition of GCF WI-104 Idle Mode test case 6.1.1.12 to HSPA7_ENH ATS | B | 8.8.0 | 8.9.0 | R5s100764 |
| RP-51 | RP-110168 | 2859 | - | Correction to GCF WI 10 NAS test case 12.2.1.4.2 | F | 8.8.0 | 8.9.0 | R5s100786 |
| RP-51 | RP-110168 | 2858 | - | Correction for GCF WI-010 SMS test case 16.2.1 | F | 8.8.0 | 8.9.0 | R5s100791 |
| RP-51 | RP-110168 | 2857 | - | Correction to Rel-7 GCF WI-110 testcase 7.1.5a.6 | F | 8.8.0 | 8.9.0 | R5s100798 |
| RP-51 | RP-110168 | 2863 | - | Correction for GCF WI-025 HSUPA test case 8.2.6.51 | F | 8.8.0 | 8.9.0 | R5s100804 |
| RP-51 | RP-110168 | 2864 | - | Correction to RRC test cases 8.2.2.43 and 8.2.2.43a | F | 8.8.0 | 8.9.0 | R5s100805 |
| RP-51 | RP-110168 | 2862 | - | Correction to Rel-7 MAC test case 7.1.5a.5.2 and 7.1.5a.5.3 | F | 8.8.0 | 8.9.0 | R5s100807 |
| RP-51 | RP-110168 | 2861 | - | Correction to the RFT 67 test cases | F | 8.8.0 | 8.9.0 | R5s100808 |
| RP-51 | RP-110168 | 2852 | - | Addition of GCF WI-114 64 QAM RRC test case 8.3.4.13 to HSPA7_ENH ATS | B | 8.8.0 | 8.9.0 | R5s100809 |
| RP-51 | RP-110168 | 2851 | - | Corrections to Rel-7 Enhanced Cell-FACH DL and L2 Enhancement testcases | F | 8.8.0 | 8.9.0 | R5s100841 |
| RP-51 | RP-110168 | 2853 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.3.1.47 to HSPA7_ENH ATS | B | 8.8.0 | 8.9.0 | R5s110017 |
| RP-51 | RP-110168 | 2856 | - | Correction to GCF WI-010 RRC test case 8.3.2.12 | F | 8.8.0 | 8.9.0 | R5s110048 |
| RP-51 | RP-110168 | 2855 | - | Correction to GCF WI-067 HSPA7 MIMO test cases 14.6.1d and 14.6.6c | F | 8.8.0 | 8.9.0 | R5s110049 |
| RP-51 | RP-110168 | 2854 | - | Correction to GCF WI-010 NAS test case 12.2.1.3 | F | 8.8.0 | 8.9.0 | R5s110050 |
| RP-51 | RP-110168 | 2866 | - | Correction to RFT 67 test cases | F | 8.8.0 | 8.9.0 | R5s110066 |
| RP-51 | RP-110168 | 2867 | - | Corrections to CPC & CS Voice Over HSPA testcases | F | 8.8.0 | 8.9.0 | R5s110072 |
| RP-51 | RP-110168 | 2868 | - | Correction to GCF WI 25 HSUPA MAC test case 7.1.6.1.1 | F | 8.8.0 | 8.9.0 | R5s110083 |
| RP-52 | RP-110653 | 2871 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 8.9.0 | 9.0.0 | - |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-52 | RP-110651 | 2869 | - | Removal of technical content in 34.123-3 v8.9.0 and substitution with pointer to the next Release | F | 8.9.0 | 9.0.0 | R5-112242 |
| RP-52 | RP-110652 | 2870 | - | Routing maintenance | F | 8.9.0 | 9.0.0 | R5-112591 |
| RP-52 | RP-110654 | 2873 | - | Correction to CS Voice Over HSPA RRC test case 8.2.2.58 | F | 8.9.0 | 9.0.0 | R5s110059 |
| RP-52 | RP-110654 | 2874 | - | Corrections to Rel-7 64QAM test case 8.3.4.13 | F | 8.9.0 | 9.0.0 | R5s110071 |
| RP-52 | RP-110654 | 2872 | - | Correction to GMM test case 12.4.3.4 | F | 8.9.0 | 9.0.0 | R5s110093 |
| RP-52 | RP-110654 | 2882 | - | Addition of GCF WI-104 Idle Mode test case 6.1.1.13 to HSPA7_ENH ATS | B | 8.9.0 | 9.0.0 | R5s110102 |
| RP-52 | RP-110654 | 2881 | - | Addition of GCF WI-104 Idle Mode test case 6.1.1.15 to HSPA7_ENH ATS | B | 8.9.0 | 9.0.0 | R5s110104 |
| RP-52 | RP-110654 | 2880 | - | Correction to GCF WI-014 HSDPA test case 7.1.5.6 | F | 8.9.0 | 9.0.0 | R5s110106 |
| RP-52 | RP-110654 | 2878 | - | Corrections to RFT-67 test cases 6.2.1.2a and 6.2.1.8a.2 | F | 8.9.0 | 9.0.0 | R5s110107 |
| RP-52 | RP-110654 | 2879 | - | Correction to GCF WI-010 RLC test case 7.2.3.24 | F | 8.9.0 | 9.0.0 | R5s110108 |
| RP-52 | RP-110654 | 2877 | - | Correction to HSPA7_ENH test suite | F | 8.9.0 | 9.0.0 | R5s110111 |
| RP-52 | RP-110654 | 2876 | - | Correction to the Rel-7 Enhanced Cell FACH test case 14.5.3 and 8.1.10.2 | F | 8.9.0 | 9.0.0 | R5s110113 |
| RP-52 | RP-110654 | 2875 | - | Correction to the Rel-7 Enhanced Cell FACH test case 8.2.2.59 | F | 8.9.0 | 9.0.0 | R5s110126 |
| RP-52 | RP-110654 | 2883 | - | Regression CR on wk10 UMTS ATS | F | 8.9.0 | 9.0.0 | R5s110169 |
| RP-52 | RP-110654 | 2889 | - | Baseline upgrade of UTRA ATS to March-11 in Rel-9 | F | 8.9.0 | 9.0.0 | R5s110175 |
| RP-52 | RP-110654 | 2884 | - | Corrections to Rel-7 Enhanced CellFACH testcases (11wk10) | F | 8.9.0 | 9.0.0 | R5s110191 |
| RP-52 | RP-110654 | 2886 | - | Correction to GCF WI-101 HSPA7 test case 8.1.7.3c | F | 8.9.0 | 9.0.0 | R5s110224 |
| RP-52 | RP-110654 | 2887 | - | Correction to GCF WI-010 NAS test cases 12.2.1.4.1 and 12.2.1.5a.1 | F | 8.9.0 | 9.0.0 | R5s110225 |
| RP-52 | RP-110654 | 2885 | - | Corrections to UTRA Rel-7 & Rel-8 testcases (11wk10) | F | 8.9.0 | 9.0.0 | R5s110229 |
| RP-52 | RP-110654 | 2888 | - | Regression CR on wk10 UMTS ATS | F | 8.9.0 | 9.0.0 | R5s110231 |
| RP-52 | RP-110654 | 2891 | - | Correction to RRC HSDPA test case 8.2.2.42 | F | 8.9.0 | 9.0.0 | R5s110240 |
| RP-52 | RP-110654 | 2890 | - | Correction to the transmission of SI 2Bis for MRAT test cases | F | 8.9.0 | 9.0.0 | R5s110241 |
| RP-53 | RP-111158 | 2894 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 9.0.0 | 9.1.0 | - |
| RP-53 | RP-111142 | 2892 | - | Routine maintenance and updates for LCR TDD | F | 9.0.0 | 9.1.0 | R5-113036 |
| RP-53 | RP-111143 | 2893 | - | Routine maintenance and updates | F | 9.0.0 | 9.1.0 | R5-113653 |
| RP-53 | RP-111159 | 2896 | - | Correction to the idle mode test case 6.1.2.3 | F | 9.0.0 | 9.1.0 | R5s110280 |
| RP-53 | RP-111159 | 2895 | - | Correction to AT commands used for PS call activation | F | 9.0.0 | 9.1.0 | R5s110281 |
| RP-53 | RP-111159 | 2897 | - | Correction to GCF WI 25 HSUPA MAC test case 7.1.6.1.1 | F | 9.0.0 | 9.1.0 | R5s110284 |
| RP-53 | RP-111159 | 2898 | - | Correction to GCF WI-010 test case 12.6.1.3.3 | F | 9.0.0 | 9.1.0 | R5s110316 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-53 | RP-111159 | 2903 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.1.1.5a to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110332 |
| RP-53 | RP-111159 | 2902 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.1.1.12 to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110334 |
| RP-53 | RP-111159 | 2901 | - | Correction to GCF WI-010 Idle mode test case 6.1.2.3 | F | 9.0.0 | 9.1.0 | R5s110343 |
| RP-53 | RP-111159 | 2900 | - | Correction to GCF WI-010 RRC test case 8.3.2.12 | F | 9.0.0 | 9.1.0 | R5s110344 |
| RP-53 | RP-111159 | 2899 | - | Correction to GCF WI-068 RRC test case 8.2.2.57 | F | 9.0.0 | 9.1.0 | R5s110345 |
| RP-53 | RP-111159 | 2906 | - | Adding originating subscribed traffic call in RRC establishment cause | F | 9.0.0 | 9.1.0 | R5s110349 |
| RP-53 | RP-111159 | 2905 | - | Addition of GCF WI-110 Enhanced Cell FACH DL RRC test case 8.4.1.50 to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110366 |
| RP-53 | RP-111159 | 2904 | - | Addition of GCF WI-110 Enhanced Cell FACH DL test case 7.1.5a.7 to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110380 |
| RP-53 | RP-111159 | 2909 | - | Addition of GCF WI-118 MIMO Enhancement test case 8.2.2.62 to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110387 |
| RP-53 | RP-111159 | 2908 | - | Addition of 3G eCall test case 13.3.1.2 to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110390 |
| RP-53 | RP-111159 | 2907 | - | Addition of 3G eCall test case 13.3.1.3 to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110392 |
| RP-53 | RP-111159 | 2914 | - | Corrections to Rel6 RRC and idle mode test cases | F | 9.0.0 | 9.1.0 | R5s110434 |
| RP-53 | RP-111159 | 2910 | - | Corrections to UTRA 11wk21 ATS | F | 9.0.0 | 9.1.0 | R5s110477 |
| RP-53 | RP-111159 | 2913 | - | Addition of GCF WI-070 HS SCCH Less test case 8.2.6.56 to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110479 |
| RP-53 | RP-111159 | 2912 | - | Correction to GCF WI-110 test case 8.4.1.50 | F | 9.0.0 | 9.1.0 | R5s110490 |
| RP-53 | RP-111159 | 2911 | - | Addition of GCF WI-070 HS SCCH Less test case 8.2.1.39 to HSPA7_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110501 |
| RP-53 | RP-111159 | 2919 | - | Addition of PPAC NAS test case 12.2.2.10 to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110503 |
| RP-53 | RP-111159 | 2918 | - | Addition of GCF WI-129 DC-HSDPA test case 14.6.1f to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110522 |
| RP-53 | RP-111159 | 2917 | - | Addition of GCF WI-129 DC-HSDPA test case 14.6.1g to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110524 |
| RP-53 | RP-111159 | 2916 | - | Addition of GCF WI-129 DC-HSDPA test case 14.6.6e to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110536 |
| RP-53 | RP-111159 | 2915 | - | Addition of GCF WI-129 DC-HSDPA test case 8.3.4.15 to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110538 |
| RP-53 | RP-111159 | 2921 | - | Addition of eCall test case 13.3.1.5 to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110542 |
| RP-53 | RP-111159 | 2920 | - | Addition of eCall test case 13.3.1.7 to HSPA8_ENH ATS | F | 9.0.0 | 9.1.0 | R5s110544 |
| RP-54 | RP-111583 | 2922 | - | Routine maintenance and updates for UTRA FDD | F | 9.1.0 | 9.2.0 | R5-115748 |
| RP-54 | RP-111585 | 2923 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 9.1.0 | 9.2.0 | - |
| RP-54 | RP-111586 | 2924 | - | Addition of GCF WI-130 Improved L2 UL RAB test case 14.7.3a to HSPA8_ENH ATS | F | 9.1.0 | 9.2.0 | R5s110540 |
| RP-54 | RP-111586 | 2925 | - | Correction to GCF WI-012 RRC test case 8.3.4.8 | F | 9.1.0 | 9.2.0 | R5s110606 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-54 | RP-111586 | 2926 | - | Corrections to 11wk36 ATS for Rel-7/Rel-8 testcases | F | 9.1.0 | 9.2.0 | R5s110635 |
| RP-54 | RP-111586 | 2927 | - | Addition of GCF WI-118 MIMO test case 8.2.6.63 to HSPA7_ENH ATS | F | 9.1.0 | 9.2.0 | R5s110629 |
| RP-54 | RP-111586 | 2928 | - | Addition of GCF WI-118 MIMO test case 8.2.6.54a to HSPA7_ENH ATS | F | 9.1.0 | 9.2.0 | R5s110627 |
| RP-54 | RP-111586 | 2929 | - | Addition of GCF WI-129 DC-HSDPA test case 14.6.6f to HSPA8_ENH ATS | F | 9.1.0 | 9.2.0 | R5s110625 |
| RP-54 | RP-111586 | 2930 | - | Regression CR for UTRA wk36 ATS | F | 9.1.0 | 9.2.0 | R5s110597 |
| RP-54 | RP-111586 | 2931 | - | Addition of GCF WI-130 Improved L2 UL RAB test case 14.7.6c to HSPA8_ENH ATS | F | 9.1.0 | 9.2.0 | R5s110662 |
| RP-54 | RP-111586 | 2932 | - | Addition of PPAC RRC test case 8.1.2.26 to HSPA8_ENH ATS | F | 9.1.0 | 9.2.0 | R5s110660 |
| RP-54 | RP-111586 | 2933 | - | Correction to GMM test cases 12.4.1.4c2 and 12.4.1.4d1 | F | 9.1.0 | 9.2.0 | R5s110686 |
| RP-54 | RP-111586 | 2934 | - | Changes related to originating subscribed traffic call | F | 9.1.0 | 9.2.0 | R5s110689 |
| RP-54 | RP-111586 | 2935 | - | Addition of TC 8.1.5.7 to HSPA9 ATS | F | 9.1.0 | 9.2.0 | R5s110671 |
| RP-54 | RP-111586 | 2936 | - | Correction to GCF WI-068 RAB test case 14.7.6b | F | 9.1.0 | 9.2.0 | R5s110716 |
| RP-54 | RP-111586 | 2937 | - | Correction to ts_SetMCC_VPLMN_Band6 | F | 9.1.0 | 9.2.0 | R5s110715 |
| RP-54 | RP-111586 | 2938 | - | Correction to GCF WI-010 NAS test case 12.4.1.4a | F | 9.1.0 | 9.2.0 | R5s110714 |
| RP-54 | RP-111586 | 2939 | - | Corrections to GCF WI-070 CPC test case 8.3.4.11 | F | 9.1.0 | 9.2.0 | R5s110711 |
| RP-55 | RP-120172 | 2940 | - | Routine maintenance and updates for LCR TDD | F | 9.2.0 | 9.3.0 | R5-120307 |
| RP-55 | RP-120184 | 2941 | - | Routine maintenance and updates | F | 9.2.0 | 9.3.0 | R5-120613 |
| RP-55 | RP-120185 | 2942 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 9.2.0 | 9.3.0 | - |
| RP-55 | RP-120186 | 2943 | - | Addition of Rel-8 64QAM+Mimo RAB test case 14.6.6d to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s110735 |
| RP-55 | RP-120186 | 2944 | - | Addition of Rel-8 64QAM+Mimo RAB test case 14.6.1e to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s110733 |
| RP-55 | RP-120186 | 2945 | - | Regression CR for UTRA wk48 ATS | F | 9.2.0 | 9.3.0 | R5s120015 |
| RP-55 | RP-120186 | 2946 | - | Correction to GCF WI-110 Enhanced Cell FACH test case 8.3.1.47 | F | 9.2.0 | 9.3.0 | R5s120005 |
| RP-55 | RP-120186 | 2947 | - | Addition of eCall test case 13.3.1.4 to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s110797 |
| RP-55 | RP-120186 | 2948 | - | Addition of GCF WI-130 Improved L2 UL MAC test case 7.1.7.1 to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s110755 |
| RP-55 | RP-120186 | 2949 | - | Corrections to 11wk48 ATS for Rel-7/Rel-8 testcases | F | 9.2.0 | 9.3.0 | R5s120047 |
| RP-55 | RP-120186 | 2950 | - | Correction to selection expression for GMM TCs 12.9.x | F | 9.2.0 | 9.3.0 | R5s120032 |
| RP-55 | RP-120186 | 2951 | - | Correction to GCF WI-110 Enhanced Cell FACH test case 7.1.5a.7 | F | 9.2.0 | 9.3.0 | R5s120004 |
| RP-55 | RP-120186 | 2952 | - | Correction to MS Classmark 2 and MS Identity IEs in the NAS Messages | F | 9.2.0 | 9.3.0 | R5s120063 |
| RP-55 | RP-120186 | 2953 | - | Addition of GCF WI-129 DC test case 8.3.4.16 to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s120043 |

| Meeting | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|---------|-----------|------|-----|---|-----|----------|----------|-----------|
| RP-55 | RP-120186 | 2954 | - | Addition of GCF WI-129 DC test case 8.3.4.16a to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s120045 |
| RP-55 | RP-120186 | 2955 | - | Addition of GCF WI-129 DC test case 8.3.4.15a to HSPA8_ENH ATS | F | 9.2.0 | 9.3.0 | R5s120041 |
| RP-55 | RP-120186 | 2956 | - | Correction to RRC test case 8.3.2.11 | F | 9.2.0 | 9.3.0 | R5s120064 |
| RP-55 | RP-120186 | 2957 | - | Correction to test case 8.1.5.7 | F | 9.2.0 | 9.3.0 | R5s120066 |
| RP-56 | RP-120650 | 2959 | - | CR to 34.123-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.123-3 (prose), Annex A | F | 9.3.0 | 9.4.0 | - |
| RP-56 | RP-120654 | 2977 | - | Correction to UTRA test cases | F | 9.3.0 | 9.4.0 | R5s120085 |
| RP-56 | RP-120654 | 2976 | - | Correction to selection expression of GCF WI-67 test case 14.6.6c | F | 9.3.0 | 9.4.0 | R5s120094 |
| RP-56 | RP-120654 | 2975 | - | Regression CR for UTRA wk08 ATS | F | 9.3.0 | 9.4.0 | R5s120123 |
| RP-56 | RP-120654 | 2972 | - | Corrections to VoiceDomainPref IE definition in Attach Request | F | 9.3.0 | 9.4.0 | R5s120131 |
| RP-56 | RP-120654 | 2974 | - | Correction to the NAS test cases for USIM removal | F | 9.3.0 | 9.4.0 | R5s120171 |
| RP-56 | RP-120654 | 2973 | - | Correction to GCF WI-010 NAS test case 12.4.1.4a | F | 9.3.0 | 9.4.0 | R5s120172 |
| RP-56 | RP-120654 | 2964 | - | Baseline upgrade of UTRA ATS to March-12 in Rel-10 | F | 9.3.0 | 9.4.0 | R5s120177 |
| RP-56 | RP-120654 | 2971 | - | Correction to UTRA RRC PPAC test case 8.1.2.26 | F | 9.3.0 | 9.4.0 | R5s120217 |
| RP-56 | RP-120654 | 2970 | - | Addition of 3G eCall test case 13.3.1.6 to HSPA8_ENH ATS | F | 9.3.0 | 9.4.0 | R5s120225 |
| RP-56 | RP-120654 | 2969 | - | Correction to Rel-99 RRC test case 8.3.1.9 | F | 9.3.0 | 9.4.0 | R5s120242 |
| RP-56 | RP-120654 | 2966 | - | Correction to UTRA Capability testcase 8.1.5.7 (Based on 12wk08 ATS) | F | 9.3.0 | 9.4.0 | R5s120267 |
| RP-56 | RP-120654 | 2967 | - | Corrections to Rel-8 testcases (12wk08 ATS) | F | 9.3.0 | 9.4.0 | R5s120268 |
| RP-56 | RP-120654 | 2968 | - | Corrections to NAS testcase 9.4.2.4.1 (12wk08 ATS) | F | 9.3.0 | 9.4.0 | R5s120269 |
| RP-56 | RP-120654 | 2965 | - | Correction to test step ts_SendSysInfoType2ter | F | 9.3.0 | 9.4.0 | R5s120270 |
| RP-56 | RP-120654 | 2963 | - | Correction to IRAT test cases in IR_U Test Suite | F | 9.3.0 | 9.4.0 | R5s120272 |
| RP-56 | RP-120654 | 2962 | - | Addition of 3G eCall test case 13.3.1.10 to HSPA8_ENH ATS | F | 9.3.0 | 9.4.0 | R5s120299 |
| RP-56 | RP-120654 | 2961 | - | Correction to UTRA test case 8.1.5.7 | F | 9.3.0 | 9.4.0 | R5s120337 |
| RP-56 | RP-120654 | 2960 | - | Correction to UTRA test case 8.4.1.8 | F | 9.3.0 | 9.4.0 | R5s120343 |
| RP-57 | RP-121103 | 2979 | - | Removal of technical content in 34.123-3 v9.4.0 and substitution with pointer to the next Release | F | 9.4.0 | 9.5.0 | R5-123308 |

History

| Document history | | |
|-------------------------|---------------|-------------|
| V9.0.0 | February 2012 | Publication |
| V9.1.0 | February 2012 | Publication |
| V9.2.0 | February 2012 | Publication |
| V9.3.0 | April 2012 | Publication |
| V9.4.0 | August 2012 | Publication |
| V9.5.0 | October 2012 | Publication |